



Protecting, Maintaining and Improving the Health of All Minnesotans

Electronically delivered

June 16, 2026

Administrator
Pioneer Care Center
1131 SOUTH MABELLE AVENUE
FERGUS FALLS, MN 56537

RE: CCN:245463

Cycle Start Date: June 4, 2026

Dear Administrator:

On June 4, 2026, a survey was completed at your facility by the Minnesota Department(s) of Health and Public Safety, to determine if your facility was in compliance with Federal participation requirements for skilled nursing facilities and/or nursing facilities participating in the Medicare and/or Medicaid programs.

This survey found the most serious deficiencies in your facility to be widespread deficiencies that constituted no actual harm with potential for more than minimal harm that was not immediate jeopardy (Level F), as evidenced by the electronically attached CMS-2567 whereby corrections are required.

ELECTRONIC PLAN OF CORRECTION (ePoC)

Within **ten (10) calendar days** after your receipt of this notice, you must submit an acceptable ePOC for the deficiencies cited. An acceptable ePOC will serve as your allegation of compliance. Upon receipt of an acceptable ePOC, we will authorize a revisit to your facility to determine if substantial compliance has been achieved.

To be acceptable, a provider's ePOC must include the following:

- How corrective action will be accomplished for those residents found to have been affected by the deficient practice.
- How the facility will identify other residents having the potential to be affected by the same deficient practice.

What measures will be put into place, or systemic changes made, to ensure that the deficient practice will not recur.

- How the facility will monitor its corrective actions to ensure that the deficient practice is being corrected and will not recur.
- The date that each deficiency will be corrected.
- An electronic acknowledgement signature and date by an official facility representative.

The state agency may, in lieu of an onsite revisit, determine correction and compliance by accepting the facility's ePoC if the ePoC is reasonable, addresses the problem and provides evidence that the corrective action has occurred.

If an acceptable ePoC is not received within 10 calendar days from the receipt of this letter, we will recommend to the CMS Region V Office that one or more of the following remedies be imposed:

- Denial of payment for new Medicare and Medicaid admissions (42 CFR 488.417);
- Civil money penalty (42 CFR 488.430 through 488.444).
- Termination of your facility's Medicare and/or Medicaid agreement (488.456(b)).

DEPARTMENT CONTACT

Questions regarding this letter and all documents submitted as a response to the resident care deficiencies (those preceded by an "F" and/or an "E" tag), i.e., the plan of correction should be directed to:

Stacy Line, BSN, RN, Regional Operations Supervisor
Fergus Falls District Office
Health Regulation Division
2312 College way
Fergus Falls, 56537
Email: stacy.line@state.mn.us

Office: 218-332-5159

PRESUMPTION OF COMPLIANCE - CREDIBLE ALLEGATION OF COMPLIANCE

The facility's ePoC will serve as your allegation of compliance upon the Department's acceptance. In order for your allegation of compliance to be acceptable to the Department, the ePoC must meet the criteria listed in the plan of correction section above. You will be notified by the Minnesota Department of Health, Licensing and Certification Program staff and/or the Department of Public Safety, State Fire Marshal Division staff, if your ePoC for the respective deficiencies (if any) is acceptable.

VERIFICATION OF SUBSTANTIAL COMPLIANCE

Upon receipt of an acceptable ePoC, a Post Certification Revisit (PCR), of your facility will be conducted to validate that substantial compliance with the regulations has been attained in accordance with your verification.

If substantial compliance has been achieved, certification of your facility in the Medicare and/or Medicaid program(s) will be continued and remedies will not be imposed. Compliance is certified as of the latest correction date on the approved ePoC, unless it is determined that either correction actually occurred between the latest correction date on the ePoC and the date of the first revisit, or correction occurred sooner than the latest correction date on the ePoC.

FAILURE TO ACHIEVE SUBSTANTIAL COMPLIANCE BY THE THIRD OR SIXTH MONTH AFTER THE LAST DAY OF THE SURVEY

If substantial compliance with the regulations is not verified by September 4, 2026 (three months after the identification of noncompliance), the CMS Region V Office must deny payment for new admissions as mandated by the Social Security Act (the Act) at Sections 1819(h)(2)(D) and 1919(h)(2)(C) and Federal regulations at 42 CFR Section 488.417(b).

In addition, if substantial compliance with the regulations is not verified by December 4, 2026 (six months after the identification of noncompliance) your provider agreement will be terminated. This action is mandated by the Social Security Act at Sections 1819(h)(2)(C) and 1919(h)(3)(D) and Federal regulations at 42 CFR Sections 488.412 and 488.456.

Please note that this notice does not constitute formal notice of imposition of alternative remedies or termination of your provider agreement. Should the Centers for Medicare & Medicaid Services determine that termination or any other remedy is warranted, it will provide you with a separate formal notification of that determination.

INFORMAL DISPUTE RESOLUTION (IDR)

In accordance with 42 CFR 488.331 and Minnesota Statute 144A.10 subd 15, you have one opportunity to question cited deficiencies through an informal dispute resolution process. You are required to send your written request, along with the specific deficiencies being disputed, and an explanation of why you are disputing those deficiencies, to: <https://forms.web.health.state.mn.us/form/NHDisputeResolution>

This request must be sent within the same ten calendar days you have for submitting an ePoC for the cited deficiencies. Please note that the failure to complete the informal dispute resolution process will not delay the dates specified for compliance or the imposition of remedies.

A copy of the Department's informal dispute resolution policies is posted on the MDH Information Bulletin website at: https://www.health.state.mn.us/facilities/regulation/infobulletins/ib04_8.html

INDEPENDENT INFORMAL DISPUTE RESOLUTION (INDEPENDENT IDR)

In accordance with 42 CFR § 488.431 and Minnesota Statute 144A.10 subd 16, when a CMP subject to being collected and placed in an escrow account is imposed, you have one opportunity to question cited deficiencies through an Independent IDR process. You may also contest scope and severity assessments for deficiencies which resulted in a finding of SQC or immediate jeopardy. You are required to send your written request, along with the specific deficiencies being disputed, and an explanation of why you are disputing those deficiencies, to: <https://forms.web.health.state.mn.us/form/NHDisputeResolution>

A facility may not use both IDR and independent IDR for the same deficiency citation(s) arising from the same survey unless the IDR process was completed prior to the imposition of the CMP. This request must be sent within ten calendar days of receipt of this offer. An incomplete Independent IDR process will not delay the effective date of any enforcement action.

Questions regarding all documents submitted as a response to the Life Safety Code deficiencies (those preceded by a "K" tag), i.e., the plan of correction, request for waivers, should be directed to:

Travis Z. Ahrens
State Fire Safety Supervisor
Health Care & Correctional Facilities
MN Department of Public Safety-Fire Marshal Division
445 Minnesota St., Suite 145
St. Paul, MN 55101
Email: travis.ahrens@state.mn.us
Web: www.sfm.dps.mn.gov
Cell: 1-507-308-4189

Feel free to contact me if you have questions.

Sincerely,



Sarah Lane, Compliance Analyst
Federal Enforcement | Health Regulation Division
Minnesota Department of Health
P.O. Box 64900

Saint Paul, MN 55164-0900

Telephone: 651-201-4308 Fax: 651-215-9697

Email: sarah.lane@state.mn.us

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 06/03/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
E0000	Initial Comments On 6/1/26 to 6/3/26, a survey for compliance with Appendix Z, Emergency Preparedness Requirements, §483.73(b)(6) was conducted during a standard recertification survey. The facility was IN compliance. The facility is enrolled in ePOC and therefore a signature is not required at the bottom of the first page of the CMS-2567 form. Although no plan of correction is required, it is required that the facility acknowledge receipt of the electronic documents.			E0000			
F0000	INITIAL COMMENTS On 6/1/26 to 6/3/26, a standard recertification survey was completed at your facility by the Minnesota Department of Health to determine if your facility was in compliance with the requirements at 42 CFR Part 483, Subpart B, Requirements for Long Term Care Facilities. Your facility was IN compliance. The facility is enrolled in ePOC and therefore a signature is not required at the bottom of the first page of the CMS-2567 form. Although no plan of correction is required, the facility must acknowledge receipt of the electronic documents.			F0000			

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See reverse for further instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0000 Bldg. 02	INITIAL COMMENTS FIRE SAFETY An annual Life Safety recertification survey was conducted by the Minnesota Department of Public Safety, State Fire Marshal Division on 06/04/2026. At the time of this survey, Pioneer Care Center was found not in compliance with the requirements for participation in Medicare/Medicaid at 42 CFR, Subpart 483.70(a), Life Safety from Fire, and the 2012 edition of National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19 Existing Health Care and the 2012 edition of NFPA 99, Health Care Facilities Code. THE FACILITY'S POC WILL SERVE AS YOUR ALLEGATION OF COMPLIANCE UPON THE DEPARTMENT'S ACCEPTANCE. YOUR SIGNATURE AT THE BOTTOM OF THE FIRST PAGE OF THE CMS-2567 FORM WILL BE USED AS VERIFICATION OF COMPLIANCE. UPON RECEIPT OF AN ACCEPTABLE POC, AN ONSITE REVISIT OF YOUR FACILITY MAY BE CONDUCTED TO VALIDATE THAT SUBSTANTIAL COMPLIANCE WITH THE REGULATIONS HAS BEEN ATTAINED IN ACCORDANCE WITH YOUR VERIFICATION. PLEASE RETURN THE PLAN OF CORRECTION FOR THE FIRE SAFETY DEFICIENCIES (K-TAGS) TO: IF PARTICIPATING IN THE E-POC PROCESS, A PAPER COPY OF THE PLAN OF CORRECTION IS NOT REQUIRED. Healthcare Fire Inspections State Fire Marshal Division 445 Minnesota St., Suite 145 St. Paul, MN 55101-5145, OR By email to: FM.HC.Inspections@state.mn.us			K0000			06/25/2026

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See reverse for further instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0000 Bldg. 02	Continued from page 1 THE PLAN OF CORRECTION FOR EACH DEFICIENCY MUST INCLUDE ALL OF THE FOLLOWING INFORMATION: 1.A detailed description of the corrective action taken or planned to correct the deficiency. 2.Address the measures that will be put in place to ensure the deficiency does not reoccur. 3.Indicate how the facility plans to monitor future performance to ensure solutions are sustained. 4.Identify who is responsible for the corrective actions and monitoring of compliance. 5.The actual or proposed date for completion of the remedy. Building 02 is a 2-story building with no basement and is Type II (111) construction. It is fully sprinkler protected and has a complete fire alarm system including smoke detectors in the corridor, sleeping rooms and common areas. Building 02 is divided into 5 smoke compartments. It is separated from Building 03 by a 2-hour fire barrier. As of November 1, 2016 this building is considered existing. The facility has a capacity of 103 beds and had a census of 98 at the time of the survey. The requirements at 42 CFR, Subpart 483.70(a), are NOT MET as evidenced by:			K0000			06/25/2026
K0355 SS = F Bldg. 02	Portable Fire Extinguishers CFR(s): NFPA 101 Portable Fire Extinguishers Portable fire extinguishers are selected, installed, inspected, and maintained in accordance with NFPA 10, Standard for Portable Fire Extinguishers. 18.3.5.12, 19.3.5.12, NFPA 10 This STANDARD is NOT MET as evidenced by:			K0355	The facility obtained and filed documentation verifying completion of the annual fire extinguisher inspections by Summit Fire Protection. All fire extinguisher inspection records have been organized and maintained in the Life Safety Code compliance binder. Summit Fire Protection completed annual Fire Extinguisher Inspection on 3/5/2026. Summit serviced the extinguisher on 3/5/2026 that was indicated on the report on page 3 of the report - that it needed service. Summit provided documentation on 6/4/2026 indicating that the extinguisher was serviced and passed inspection on 3/5/2026.		06/24/2026

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0355 SS = F Bldg. 02	Continued from page 2 Based on observation and staff interview, the facility failed to maintain access to portable fire extinguishers per NFPA 101 (2012 edition), Life Safety Code, section 9.7.4.1, and NFPA 10 (2010 edition), Standard for Portable Fire Extinguishers, section 7.3.1.1.1. This deficient finding could have a widespread impact on the residents within the facility. Findings include: On 06/04/2026, at 10:46am, it was revealed by documentation review that the fire extinguishers annual inspection documentation could not be provided. An interview with the Maintenance Director verified this deficient finding at the time of discovery.			K0355	Continued from page 2 This information was received by Brad Bushinger Environmental Services Director and placed with the 3/5/2026 Summit Report. Environmental Service Director will monitor for ongoing compliance.		06/24/2026
K0761 SS = F Bldg. 02	Maintenance, Inspection & Testing - Doors CFR(s): NFPA 101 Maintenance, Inspection & Testing - Doors Fire doors assemblies are inspected and tested annually in accordance with NFPA 80, Standard for Fire Doors and Other Opening Protectives. Non-rated doors, including corridor doors to patient rooms and smoke barrier doors, are routinely inspected as part of the facility maintenance program. Individuals performing the door inspections and testing possess knowledge, training or experience that demonstrates ability. Written records of inspection and testing are maintained and are available for review. 19.7.6, 8.3.3.1 (LSC) 5.2, 5.2.3 (2010 NFPA 80) This STANDARD is NOT MET as evidenced by: Based on a review of available documentation and staff interview, the facility failed to inspect fire doors per NFPA 101 (2012 edition), Life Safety Code section 8.3.3.1, and NFPA 80 (2010 edition), Standard for Fire Doors and Other Opening Protectives, section 5.2.5.2. This deficient finding could have a widespread impact on the residents within the facility.			K0761	The Annual Door Inspection for the 13 points has been completed and documentation added to the information binder on 6/8/2026. Verified by Brad Bushinger Environmental Services Director. Environmental Services Director will monitor for ongoing compliance.		06/24/2026

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0761 SS = F Bldg. 02	Continued from page 3 Findings include: On 06/04/2026, at 11:07am, it was revealed by review of available documentation the required annual door inspection documentation the facility failed to provide a document showing all 13 points of the required door inspection was completed. An interview with the Maintenance Director verified this deficient finding at the time of discovery.			K0761			06/24/2026
K0918 SS = F Bldg. 02	Electrical Systems - Essential Electric Syste CFR(s): NFPA 101 Electrical Systems - Essential Electric System Maintenance and Testing The generator or other alternate power source and associated equipment is capable of supplying service within 10 seconds. If the 10-second criterion is not met during the monthly test, a process shall be provided to annually confirm this capability for the life safety and critical branches. Maintenance and testing of the generator and transfer switches are performed in accordance with NFPA 110. Generator sets are inspected weekly, exercised under load 30 minutes 12 times a year in 20-40 day intervals, and exercised once every 36 months for 4 continuous hours. Scheduled test under load conditions include a complete simulated cold start and automatic or manual transfer of all EES loads, and are conducted by competent personnel. Maintenance and testing of stored energy power sources (Type 3 EES) are in accordance with NFPA 111. Main and feeder circuit breakers are inspected annually, and a program for periodically exercising the components is established according to manufacturer requirements. Written records of maintenance and testing are maintained and readily available. EES electrical panels and circuits are marked, readily identifiable, and separate from normal power circuits. Minimizing the possibility of damage of the emergency power source is a design consideration for new installations. 6.4.4, 6.5.4, 6.6.4 (NFPA 99), NFPA 110, NFPA 111, 700.10 (NFPA 70) This STANDARD is NOT MET as evidenced by: Based on a review of available documentation and staff interview, the facility failed to maintain generators per NFPA 110 (2010 edition), Standard for Emergency and Standby Power Systems, sections			K0918	On 8/3/2026 the facilities generator is scheduled for service. At that time the fuel will be tested for reliability and documentation will be placed in the generator file. Testing will be completed by Christians Custom LLC. Verified by Brad Bushinger Environmental Services Director. Ongoing compliance will be monitored by the Environmental Services Director.		08/03/2026

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0918 SS = F Bldg. 02	Continued from page 4 4.2 and 8.3.8. This deficient finding could have a widespread on the residents within the facility. Findings include On 06/04/2026, at 11:06am, it was revealed by a review of available documentation at the time of the survey the facility could not provide a letter of reliability and/or a fuel testing document from a fuel company. An interview with the Maintenance Director verified this deficient finding at the time of discovery.			K0918			08/03/2026
K0920 SS = F Bldg. 02	Electrical Equipment - Power Cords and Extens CFR(s): NFPA 101 Electrical Equipment - Power Cords and Extension Cords Power strips in a patient care vicinity are only used for components of movable patient-care-related electrical equipment (PCREE) assemblies that have been assembled by qualified personnel and meet the conditions of 10.2.3.6. Power strips in the patient care vicinity may not be used for non-PCREE (e.g., personal electronics), except in long-term care resident rooms that do not use PCREE. Power strips for PCREE meet UL 1363A or UL 60601-1. Power strips for non-PCREE in the patient care rooms (outside of vicinity) meet UL 1363. In non-patient care rooms, power strips meet other UL standards. All power strips are used with general precautions. Extension cords are not used as a substitute for fixed wiring of a structure. Extension cords used temporarily are removed immediately upon completion of the purpose for which it was installed and meets the conditions of 10.2.4. 10.2.3.6 (NFPA 99), 10.2.4 (NFPA 99), 400-8 (NFPA 70), 590.3(D) (NFPA 70), TIA 12-5 This STANDARD is NOT MET as evidenced by: Based on observation and staff interview, the facility failed to maintain the usage of electrical adaptive devices per NFPA 99 (2012 edition), Health Care Facilities Code, sections 10.5.2.3.1 and 10.2.4.2.1, NFPA 70, (2011 edition), National Electrical Code, sections 400-8, and UL 1363. This deficient finding could have an isolated impact on the residents within the facility. Findings include:			K0920	All refrigerators and coffee makers identified during the survey were immediately removed from power strips and plugged directly into permanently installed wall receptacles. Verified by Brad Bushinger Environmental Services Director. Ongoing compliance will be monitored by the Environmental Services Director.		06/23/2026

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0920 SS = F Bldg. 02	Continued from page 5 On 06/04/2026, at the following times, it was revealed by observation that there were several electrical appliances plugged power-strips, multi-plug adapters and/or extension cords in the following areas; 1) at 12:09pm, Power-strip with frig, in Malissa's office 2) at 12:12pm, Power-strip with frig, in Jenny's office 3) at 12:14pm, Power-strip with frig and coffee maker, in Jenny's office 4) at 12:15pm, Power-strip with frig and coffee maker, in HR Directors office 5) at 12:17pm, Power-strip with frig and coffee maker, in 2 floor Nurses office 6) at 12:09pm, Power-strip with frig, in infection control office An interview with the Maintenance Director verified this deficient finding at the time of discovery.			K0920			06/23/2026
K0353 SS = E Bldg. 02	Sprinkler System - Maintenance and Testing CFR(s): NFPA 101 Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available. a) Date sprinkler system last checked b) Who provided system test c) Water system supply source Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25			K0353	Storage materials in the Meadows Wing and Birch Wing clean linen rooms were immediately lowered to maintain the required minimum 18-inch clearance below sprinkler heads. A facility-wide inspection of all storage rooms and shelving areas was completed to verify sprinkler clearance requirements were maintained. 6/22/2026 all Linen Storage rooms have information posted indicated items can't be placed above line on wall indicating 18 inches from ceiling. A reference line was placed on each wall in the Linen Storage Rooms. Verified by Environmental Director Brad Bushinger. Environmental Director will monitor for ongoing compliance.		06/23/2026

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0353 SS = E Bldg. 02	Continued from page 6 This STANDARD is NOT MET as evidenced by: Based on observation and staff interview, the facility failed to maintain spacing between storage and the sprinkler system per NFPA 101 (2012 edition), Life Safety Code, Section 9.7.5, NFPA 25 (2011 edition), Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems, Section 5.2.1.2, and NFPA 13 (2010 edition), Standard for the Installation of Sprinkler Systems, Sections 8.6.5.3.2. These deficient findings could have a patterned impact on the residents within the facility. Findings include: On 06/04/2026, at the following times, it was revealed by observation that storage materials had been placed on a storage rack, bringing the storage materials within the required 18 inch clearance area under the sprinkler heads. These obstructions were found in: 1) at 11:50am, on the Meadows Wing Clean Linen Storage room 2) at 11:59am, on the Burch Wing Clean Linen Storage room An interview with the Maintenance Director verified this deficient finding at the time of discovery.			K0353			06/23/2026
K0324 SS = D Bldg. 02	Cooking Facilities CFR(s): NFPA 101 Cooking Facilities Cooking equipment is protected in accordance with NFPA 96, Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations, unless: * residential cooking equipment (i.e., small appliances such as microwaves, hot plates, toasters) are used for food warming or limited cooking in accordance with 18.3.2.5.2, 19.3.2.5.2 * cooking facilities open to the corridor in smoke compartments with 30 or fewer patients comply with the conditions under 18.3.2.5.3, 19.3.2.5.3, or * cooking facilities in smoke compartments with 30 or fewer patients comply with conditions under 18.3.2.5.4, 19.3.2.5.4.			K0324	An approved alignment marking system and appliance restraint/positioning device were installed for the wheeled gas-fired stove and range top. Equipment was returned to its approved location. All movable gas-fired cooking appliances within the kitchen were reviewed to verify compliance with positioning and restraint requirements. The work was completed 6/22/2026 Verified by Brad Bushinger EnvironmentalDirector. Compliance will be monitored by the Environmental Director.		06/23/2026

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0324 SS = D Bldg. 02	Continued from page 7 Cooking facilities protected according to NFPA 96 per 9.2.3 are not required to be enclosed as hazardous areas, but shall not be open to the corridor. 18.3.2.5.1 through 18.3.2.5.4, 19.3.2.5.1 through 19.3.2.5.5, 9.2.3, TIA 12-2 This STANDARD is NOT MET as evidenced by: Based on observation and interview, the facility failed to install the kitchen hood extinguishing system in accordance with NFPA 101 (2012 edition), The Life Safety Code, section 19.3.2.5, 19.3.2.5.1, 19.3.2.5.2*, 9.2.5, NFPA 96 (2011 edition) Ventilation Control and Fire Protection of Commercial Cooking Operations, section 12.1.2.3 and 12.1.2.3.1. These deficient findings could an isolated impact on the residents within the facility. The findings include: On 06/04/2026, at 11:36am, it was revealed that the wheeled, gas-fired stove and griddle located on the cooking line in the kitchen was not provided with an approved method of attachment and/or an alignment mark to ensure the appliances was returned to an approved design location after it had been moved for maintenance and cleaning. Both the attachment device and alignment mark are required for each gas operated and deep fat fryer cooking device. An interview with the Maintenance Director verified this deficient finding at the time of discovery.			K0324			06/23/2026
K0372 SS = D Bldg. 02	Subdivision of Building Spaces - Smoke Barrie CFR(s): NFPA 101 Subdivision of Building Spaces - Smoke Barrier Construction 2012 EXISTING Smoke barriers shall be constructed to a 1/2-hour fire resistance rating per 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke barrier. 19.3.7.3, 8.6.7.1(1) Describe any mechanical smoke control system in REMARKS.			K0372	The penetrations identified above the smoke barrier doors in the Birch, Autumn, and Deerwood wing locations were repaired using approved fire/smoke barrier materials to restore the integrity of the smoke barrier. This was Verified by Brad Bushinger Environmental Services Director 6/22/2026. Environmental Services Director will monitor for ongoing compliance.		06/23/2026

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BLDG ... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0372 SS = D Bldg. 02	Continued from page 8 This STANDARD is NOT MET as evidenced by: Based on observation and staff interview, the facility failed to maintain their smoke barrier per NFPA 101 (2012 edition), Life Safety Code, sections 19.3.7.1, 19.3.7.3, 8.5.2.2, and 8.5.6.5. These deficient findings could have a widespread impact on the residents within the facility. Findings include: On 06/04/2026, at the following times, it was revealed by observation that there was a penetration running from one smoke compartment to another above doors in the following locations: 1) at 11:16am, above doors leading to Burch wing, 2 floor. 2) at 11:18am, above doors between Burch and autumn wings, 2 floor. 3) at 12:28pm, above doors leading to Deerwood wing, 2 floor. An interview with the Maintenance Director verified this deficient finding at the time of discovery.			K0372			06/23/2026

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 245463		(X2) MULTIPLE CONSTRUCTION A. BUILDING 03 - SOUTH BLDG... B. WING		(X3) DATE SURVEY COMPLETED 06/04/2026	
NAME OF PROVIDER OR SUPPLIER Pioneer Care Center				STREET ADDRESS, CITY, STATE, ZIP CODE 1131 SOUTH MABELLE AVENUE , FERGUS FALLS, Minnesota, 56537			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0000 Bldg. 03	INITIAL COMMENTS FIRE SAFETY An annual Life Safety recertification survey was conducted by the Minnesota Department of Public Safety, State Fire Marshal Division on 06/04/2026. At the time of this survey, Pioneer Care Center was found in compliance with the requirements for participation in Medicare/Medicaid at 42 CFR, Subpart 483.70(a), Life Safety from Fire, and the 2012 edition of National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19 Existing Health Care and the 2012 edition of NFPA 99, the Health Care Facilities Code. Building 03 is a 1-story building with no basement and is Type V (111) construction. Building 03 is fully sprinkler protected and has a complete fire alarm system including smoke detectors in the corridor, sleeping rooms and common areas. Building 03 is divided into 3 smoke compartments. It is separated from Building 02 by a 2-hour fire barrier. As of November 1, 2016 this building is considered existing. The facility has a capacity of 103 beds and had a census of 98 at time of the survey. The requirements at 42 CFR, Subpart 483.70(a), are MET.			K0000			06/25/2026

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See reverse for further instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE