CENTERS FOR MEDICARE & MEDICAID SERVICES

ID: ENQT

MEDICARE/MEDICAID CERTIFICATION AND TRANSMITTAL PART I - TO BE COMPLETED BY THE STATE SURVEY AGENCY

PART I	- TO BE COMPLETED BY	THE STA	E STATE SURVEY AGENCY Facility ID: 00168			
MEDICARE/MEDICAID PROVIDER NO. (L1) 24E166 2.STATE VENDOR OR MEDICAID NO. (L2) 458995500	3. NAME AND ADDRESS OF FAC (L3) BIRCHWOOD CARE HO! (L4) 715 WEST 31ST STREET (L5) MINNEAPOLIS, MN		(L6) 55408	4. TYPE OF ACTION: 7 (L8) 1. Initial 2. Recertification 3. Termination 4. CHOW 5. Validation 6. Complaint		
5. EFFECTIVE DATE CHANGE OF OWNERSHIP (L9) 01/01/2004	7. PROVIDER/SUPPLIER CATEGO 01 Hospital 05 HHA	09 ESRD	10 (L7) 13 PTIP 22 CLIA	7. On-Site Visit 9. Other 8. Full Survey After Complaint		
6. DATE OF SURVEY 02/10/2017 (L34) 8. ACCREDITATION STATUS: (L10) 0 Unaccredited	02 SNF/NF/Dual 06 PRTF 03 SNF/NF/Distinct 07 X-Ray 04 SNF 08 OPT/SP	10 NF 11 ICF/IID 12 RHC	14 CORF 15 ASC 16 HOSPICE	FISCAL YEAR ENDING DATE: (L35) 09/30		
11. LTC PERIOD OF CERTIFICATION From (a): To (b): 12. Total Facility Beds 60 (L18) 13. Total Certified Beds 60 (L17)	A. In Compliance With Program Requirements Compliance Based On: 1. Acceptable POC B. Not in Compliance with Pro Requirements and/or Applied W	gram	And/Or Approved Waivers Of Th 2. Technical Personnel 3. 24 Hour RN 4. 7-Day RN (Rural SNF 5. Life Safety Code	6. Scope of Services Limit 7. Medical Director		
14. LTC CERTIFIED BED BREAKDOWN 18 SNF 18/19 SNF 19 SNF 60 (L37) (L38) (L39)	ICF IID (L42) (L43)	aiveis.	* Code: A 15. FACILITY MEETS 1861 (e) (1) or 1861 (j) (1):	(L15)		
16. STATE SURVEY AGENCY REMARKS (IF APPLICABLE) 17. SURVEYOR SIGNATURE	E SHOW LTC CANCELLATION DATE Date:	18. STATE SURVEY AGENCY A	APPROVAL Date:			
Gloria Derfus, Unit Supervisor	03/28/2017	(L19)	Anne Peterson, Enforc	ement Specialist 08/04/2017 _(L20)		
PART II - TO BI	E COMPLETED BY HCFA R	EGIONA	L OFFICE OR SINGLE ST.	ATE AGENCY		
DETERMINATION OF ELIGIBILITY _X 1. Facility is Eligible to Participate 2. Facility is not Eligible (L21)	20. COMPLIANCE WITH RIGHTS ACT:	H CIVIL	Statement of Financial Solvency (HCFA-2572) Ownership/Control Interest Disclosure Stmt (HCFA-1513) Both of the Above :			
22. ORIGINAL DATE OF PARTICIPATION 03/31/1974 (L24) (L41)			26. TERMINATION ACTION: VOLUNTARY 00 01-Merger, Closure 02-Dissatisfaction W/ Reimburseme	05-Fail to Meet Health/Safety		
25. LTC EXTENSION DATE: 27. ALTERNATI	VE SANCTIONS n of Admissions: (L44)		03-Risk of Involuntary Termination 04-Other Reason for Withdrawal	OTHER 07-Provider Status Change 00-Active		
28. TERMINATION DATE: 29	. INTERMEDIARY/CARRIER NO.	(L31)	30. REMARKS			
31. RO RECEIPT OF CMS-1539 32 (L32)	. DETERMINATION OF APPROVAL I	DATE (L33)	DETERMINATION APPR	OVAL		



PROTECTING, MAINTAINING AND IMPROVING THE HEALTH OF ALL MINNESOTANS

CMS Certification Number (CCN): 24E166

March 28, 2017

Mr. Randal Hagemeyer, Administrator Birchwood Care Home 715 West 31st Street Minneapolis, MN 55408

Dear Mr. Hagemeyer:

The Minnesota Department of Health assists the Centers for Medicare and Medicaid Services (CMS) by surveying skilled nursing facilities and nursing facilities to determine whether they meet the requirements for participation. To participate as a skilled nursing facility in the Medicare program or as a nursing facility in the Medicaid program, a provider must be in substantial compliance with each of the requirements established by the Secretary of Health and Human Services found in 42 CFR part 483, Subpart B.

Based upon your facility being in substantial compliance, we are recommending to CMS that your facility be recertified for participation in the Medicaid program.

Effective February 2, 2017 the above facility is certified for:

60 Nursing Facility Beds

You should advise our office of any changes in staffing, services, or organization, which might affect your certification status.

If, at the time of your next survey, we find your facility to not be in substantial compliance your Medicaid provider agreement may be subject to non-renewal or termination.

Please contact me if you have any questions.

Sincerely,

Kamala Fiske-Downing

Minnesota Department of Health Licensing and Certification Program

Kumalu Fiske Downing

Health Regulation Division

Telephone: (651) 201-4112 Fax: (651) 215-9697 Email: Kamala.Fiske-Downing@state.mn.us



PROTECTING, MAINTAINING AND IMPROVING THE HEALTH OF ALL MINNESOTANS

Electronically delivered March 28, 2017

Mr. Randal Hagemeyer, Administrator Birchwood Care Home 715 West 31st Street Minneapolis, MN 55408

RE: Project Number SE166026

Dear Mr. Hagemeyer:

On January 26, 2017, we informed you that we would recommend enforcement remedies based on the deficiencies cited by this Department for a standard survey, completed on January 10, 2017. This survey found the most serious deficiencies to be widespread deficiencies that constituted no actual harm with potential for more than minimal harm that was not immediate jeopardy (Level F) whereby corrections were required.

On February 10, 2017, the Minnesota Department of Health completed a Post Certification Revisit (PCR) by review of your plan of correction and on February 14, 2017 the Minnesota Department of Public Safety completed a PCR to verify that your facility had achieved and maintained compliance with federal certification deficiencies issued pursuant to a standard survey, completed on January 10, 2017. We presumed, based on your plan of correction, that your facility had corrected these deficiencies as of February 2, 2017. Based on our PCR, we have determined that your facility has corrected the deficiencies issued pursuant to our standard survey, completed on January 10, 2017, effective February 2, 2017 and therefore remedies outlined in our letter to you dated January 26, 2017, will not be imposed.

Please note, it is your responsibility to share the information contained in this letter and the results of this visit with the President of your facility's Governing Body.

Feel free to contact me if you have questions.

Sincerely,

Kamala Fiske-Downing

Minnesota Department of Health Licensing and Certification Program

Kumalu Fiske Downing

Health Regulation Division

Telephone: (651) 201-4112 Fax: (651) 215-9697 Email: Kamala.Fiske-Downing@state.mn.us

DEPARTMENT OF HEALTH AND HUMAN SERVICES

CENTERS FOR MEDICARE & MEDICAID SERVICES

		ARE/MEDICAII TO BE COMPI							ID: ENQT Facility ID: 00168
1. MEDICARE/MEDICAID PROV NO.(L1) 24E166 2. STATE VENDOR OR MEDICA (L2) 458995500	TIDER	3. NAME AND AE (L3) BIRCHWOO (L4) 715 WEST 3 (L5) MINNEAPO	DDRESS OF FAC DD CARE HO 1ST STREET	CILITY	(L6) 5		4. TYPE (1. Initial 3. Termi 5. Valida	OF ACTIC	
5. EFFECTIVE DATE CHANGE C (L9) 01/01/2004	1/ 10/2017 ^{L34)} (L10)	7. PROVIDER/SU 01 Hospital 02 SNF/NF/Dual 03 SNF/NF/Distinct 04 SNF	PPLIER CATEG 05 HHA 06 PRTF 07 X-Ray 08 OPT/SP	ORY 09 ESRD 10 NF 11 ICF/IID 12 RHC	10 (L7) 13 PTIP 14 CORF 15 ASC 16 HOSPICE	22 CLIA	FISCAL YE	urvey Afte	9. Other r Complaint NG DATE: (L35)
11. LTC PERIOD OF CERTIFICATE From (a): To (b): 12. Total Facility Beds 13. Total Certified Beds 14. LTC CERTIFIED BED BREAKI 18 SNF 18/19 SN (L37) (L38) 16. STATE SURVEY AGENCY RE	60 (L18) 60 (L17) DOWN IF 19 SNF 60 (L39)	X B. Not in Com Requirements ICF (L42)	nce With equirements be Based On: ecceptable POC appliance with Progrand/or Applied V IID (L43)	gram Vaivers:	3. 24 Ho 4. 7-Day 5. Life S	nical Personnel our RN / RN (Rural SN Gafety Code 3* HEETS	6. S 7. M F) 8. P 9. B (L12)	•	ervices Limit rector m Size
17. SURVEYOR SIGNATURE		Date :			18. STATE SURV	VEY AGENCY	APPROVAL		Date:
Amy Charais, HF			2/09/2017	(L19)					<u>cialist</u> 03/13/2017 (L20)
19. DETERMINATION OF ELIGIF 1. Facility is Eligible t 2. Facility is not Eligible.	o Participate	20. COM	PLIANCE WITH		21. 1. Sta 2. Ov	atement of Finar wnership/Contro oth of the Above	ncial Solvency (HCFA-257	
22. ORIGINAL DATE OF PARTICIPATION 03/31/1974 (L24)	23. LTC AGREEN BEGINNING (L41) 27. ALTERNATI	S DATE	ENDING DAT		26. TERMINAT VOLUNTARY 01-Merger, Closu 02-Dissatisfaction 03-Risk of Involur	re n W/ Reimburse	ement	INVOLUM 05-Fail to 06-Fail to	(L30) NTARY Meet Health/Safety Meet Agreement
25. LTC EXTENSION DATE: (L27)	A. Suspension	of Admissions:	(L44) (L45)		04-Other Reason f	=		OTHER 07-Provid 00-Active	er Status Change
28. TERMINATION DATE:	(L28)	. INTERMEDIARY/	CARRIER NO.	(L31)	30. REMARKS				
31. RO RECEIPT OF CMS-1539		. DETERMINATION	OF APPROVAL						

(L33)

DETERMINATION APPROVAL

(L32)

DEPARTMENT OF HEALTH AND HUMAN SERVICES

CENTERS FOR MEDICARE & MEDICAID SERVICES

					AND TRANSMITTAL TE SURVEY AGENCY	ID: ENQ Facility ID	
MEDICARE/MEDICAID PROV NO.(L1) 24E166		3. NAME AND AI (L3) BIRCHWO	ODRESS OF FA	CILITY OME	TE SERVET AGENCY	4. TYPE OF ACTION: 20	L8)
2. STATE VENDOR OR MEDICA (L2) 458995500		(L4) 715 WEST 3 (L5) MINNEAPO		r 	(L6) 55408	3. Termination 4. CH 5. Validation 6. Cor	mplaint
5. EFFECTIVE DATE CHANGE ((L9) 01/01/2004		7. PROVIDER/SU 01 Hospital	05 HHA	09 ESRD	10 (L7) 13 PTIP 22 CLIA	7. On-Site Visit 9. Oth 8. Full Survey After Complaint	
6. DATE OF SURVEY 01 8. ACCREDITATION STATUS: 0 Unaccredited 1 TJC 2 AOA 3 Othe	./10/2017 ^(L10)	02 SNF/NF/Dual 03 SNF/NF/Distinct 04 SNF	06 PRTF 07 X-Ray 08 OPT/SP	10 NF 11 ICF/IID 12 RHC	14 CORF D 15 ASC 16 HOSPICE	FISCAL YEAR ENDING DATE:	(L35)
11. LTC PERIOD OF CERTIFICATE From (a): To (b):	ON	10.THE FACILITY A. In Complia. Program Re Compliance	nce With quirements	AS:	And/Or Approved Waivers Of2. Technical Personnel3. 24 Hour RN		it
12.Total Facility Beds 13.Total Certified Beds	60 (L18) 60 (L17)	X B. Not in Com	cceptable POC pliance with Pro-	-	4. 7-Day RN (Rural SN 5. Life Safety Code		
14. LTC CERTIFIED BED BREAKI 18 SNF 18/19 SN		ICF	ПД		*Code: B * 15. FACILITY MEETS 1861 (e) (1) or 1861 (j) (1):	(L15)	
(L37) (L38)	(L39)	(L42)	(L43)				
16. STATE SURVEY AGENCY RE	MARKS (IF APPLICA	BLE SHOW LTC CAI	NCELLATION 1	DATE):			
17. SURVEYOR SIGNATURE		Date:			18. STATE SURVEY AGENCY	APPROVAL Date:	
Amy Charais, HFI	E NE II	02	2/09/2017	(L19)	Kamala Fiske-Downing,	Enforcement Specialist 03/	/13/2017 (L20)
PA	ART II - TO BE C	COMPLETED B	Y HCFA RE	GIONAL	OFFICE OR SINGLE S	TATE AGENCY	
19. DETERMINATION OF ELIGIB 1. Facility is Eligible to 2. Facility is not Eligib	Participate le		PLIANCE WITE IS ACT:	I CIVIL		icial Solvency (HCFA-2572) I Interest Disclosure Strat (HCFA-151) :	3)
	(L21)						
22. ORIGINAL DATE OF PARTICIPATION 03/31/1974	23. LTC AGREEM BEGINNING		LTC AGREEM ENDING DAI	TE	26. TERMINATION ACTION: VOLUNTARY 01-Merger, Closure 02-Dissatisfaction W/ Reimburse	05-Fail to Meet Health	•
(L24) 25. LTC EXTENSION DATE:	(L41) 27. ALTERNATIV	E SANCTIONS	(L25)		03-Risk of Involuntary Termination	n and the state of	ient
(1.27)	A. Suspension B. Rescind Sus	of Admissions:	(L44)		04-Other Reason for Withdrawal	OTHER 07-Provider Status Chi 00-Active	inge
28. TERMINATION DATE:		 INTERMEDIARY/C	(L45)	-	30, REMARKS		_
	(L28)			(L31)	S. ALM delo		
31. RO RECEIPT OF CMS-1539	32.	DETERMINATION (OF APPROVAL 1	DATE			
	(L32)	3-14-	17	(L33)	DETERMINATION APPR	OVAL OVAL	7



PROTECTING, MAINTAINING AND IMPROVING THE HEALTH OF ALL MINNESOTANS

Electronically delivered January 26, 2017

Mr. Randal Hagemeyer, Administrator Birchwood Care Home 715 West 31st Street Minneapolis, MN 55408

RE: Project Number SE166026

Dear Mr. Hagemeyer:

On January 10, 2017, a standard survey was completed at your facility by the Minnesota Departments of Health and Public Safety to determine if your facility was in compliance with Federal participation requirements for skilled nursing facilities and/or nursing facilities participating in the Medicare and/or Medicaid programs.

This survey found the most serious deficiencies in your facility to be widespread deficiencies that constitute no actual harm with potential for more than minimal harm that is not immediate jeopardy (Level F), as evidenced by the attached CMS-2567 whereby corrections are required. A copy of the Statement of Deficiencies (CMS-2567) is enclosed.

Please note that this notice does not constitute formal notice of imposition of alternative remedies or termination of your provider agreement. Should the Centers for Medicare & Medicaid Services determine that termination or any other remedy is warranted, it will provide you with a separate formal notification of that determination.

This letter provides important information regarding your response to these deficiencies and addresses the following issues:

<u>Opportunity to Correct</u> - the facility is allowed an opportunity to correct identified deficiencies before remedies are imposed;

<u>Electronic Plan of Correction</u> - when a plan of correction will be due and the information to be contained in that document;

<u>Remedies</u> - the type of remedies that will be imposed with the authorization of the Centers for Medicare and Medicaid Services (CMS) if substantial compliance is not attained at the time of a revisit;

<u>Potential Consequences</u> - the consequences of not attaining substantial compliance 3 and 6 months after the survey date; and

<u>Informal Dispute Resolution</u> - your right to request an informal reconsideration to dispute the attached deficiencies.

Please note, it is your responsibility to share the information contained in this letter and the results of this visit with the President of your facility's Governing Body.

DEPARTMENT CONTACT

Questions regarding this letter and all documents submitted as a response to the resident care deficiencies (those preceded by a "F" tag), i.e., the plan of correction should be directed to:

Gloria Derfus, Unit Supervisor
Minnesota Department of Health
P.O. Box 64900
St. Paul, Minnesota 55164-0900
gloria.derfus@state.mn.us
Telephone: (651) 201-3792 Fax: (651) 215-9697

OPPORTUNITY TO CORRECT - DATE OF CORRECTION - REMEDIES

As of January 14, 2000, CMS policy requires that facilities will not be given an opportunity to correct before remedies will be imposed when actual harm was cited at the last standard or intervening survey and also cited at the current survey. Your facility does not meet this criterion. Therefore, if your facility has not achieved substantial compliance by February 21, 2017, the Department of Health will impose the following remedy:

• State Monitoring. (42 CFR 488.422)

In addition, the Department of Health is recommending to the CMS Region V Office that if your facility has not achieved substantial compliance by February 21, 2017 the following remedy will be imposed:

• Per instance civil money penalty. (42 CFR 488.430 through 488.444)

ELECTRONIC PLAN OF CORRECTION (ePoC)

An ePoC for the deficiencies must be submitted within **ten calendar days** of your receipt of this letter. Your ePoC must:

- Address how corrective action will be accomplished for those residents found to have been affected by the deficient practice;

- Address how the facility will identify other residents having the potential to be affected by the same deficient practice;
- Address what measures will be put into place or systemic changes made to ensure that the deficient practice will not recur;
- Indicate how the facility plans to monitor its performance to make sure that solutions are sustained. The facility must develop a plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective action evaluated for its effectiveness. The plan of correction is integrated into the quality assurance system;
- Include dates when corrective action will be completed. The corrective action completion dates must be acceptable to the State. If the plan of correction is unacceptable for any reason, the State will notify the facility. If the plan of correction is acceptable, the State will notify the facility. Facilities should be cautioned that they are ultimately accountable for their own compliance, and that responsibility is not alleviated in cases where notification about the acceptability of their plan of correction is not made timely. The plan of correction will serve as the facility's allegation of compliance; and,
- Submit electronically to acknowledge your receipt of the electronic 2567, your review and your ePoC submission.

If an acceptable ePoC is not received within 10 calendar days from the receipt of this letter, we will recommend to the CMS Region V Office that one or more of the following remedies be imposed:

- Optional denial of payment for new Medicare and Medicaid admissions (42 CFR 488.417 (a));
- Per day civil money penalty (42 CFR 488.430 through 488.444).

Failure to submit an acceptable ePoC could also result in the termination of your facility's Medicare and/or Medicaid agreement.

PRESUMPTION OF COMPLIANCE - CREDIBLE ALLEGATION OF COMPLIANCE

The facility's ePoC will serve as your allegation of compliance upon the Department's acceptance. Your signature at the bottom of the first page of the CMS-2567 form will be used as verification of compliance. In order for your allegation of compliance to be acceptable to the Department, the ePoC must meet the criteria listed in the plan of correction section above. You will be notified by the Minnesota Department of Health, Licensing and Certification Program staff and/or the Department of Public Safety, State Fire Marshal Division staff, if your ePoC for the respective deficiencies (if any) is acceptable.

VERIFICATION OF SUBSTANTIAL COMPLIANCE

Upon receipt of an acceptable ePoC, an onsite revisit of your facility may be conducted to validate that substantial compliance with the regulations has been attained in accordance with your verification. A Post Certification Revisit (PCR) will occur after the date you identified that compliance was achieved in your plan of correction.

If substantial compliance has been achieved, certification of your facility in the Medicare and/or Medicaid program(s) will be continued and remedies will not be imposed. Compliance is certified as of the latest correction date on the approved ePoC, unless it is determined that either correction actually occurred between the latest correction date on the ePoC and the date of the first revisit, or correction occurred sooner than the latest correction date on the ePoC.

Original deficiencies not corrected

If your facility has not achieved substantial compliance, we will impose the remedies described above. If the level of noncompliance worsened to a point where a higher category of remedy may be imposed, we will recommend to the CMS Region V Office that those other remedies be imposed.

Original deficiencies not corrected and new deficiencies found during the revisit

If new deficiencies are identified at the time of the revisit, those deficiencies may be disputed through the informal dispute resolution process. However, the remedies specified in this letter will be imposed for original deficiencies not corrected. If the deficiencies identified at the revisit require the imposition of a higher category of remedy, we will recommend to the CMS Region V Office that those remedies be imposed.

Original deficiencies corrected but new deficiencies found during the revisit

If new deficiencies are found at the revisit, the remedies specified in this letter will be imposed. If the deficiencies identified at the revisit require the imposition of a higher category of remedy, we will recommend to the CMS Region V Office that those remedies be imposed. You will be provided the required notice before the imposition of a new remedy or informed if another date will be set for the imposition of these remedies.

FAILURE TO ACHIEVE SUBSTANTIAL COMPLIANCE BY THE THIRD OR SIXTH MONTH AFTER THE LAST DAY OF THE SURVEY

If substantial compliance with the regulations is not verified by April 10, 2017 (three months after the identification of noncompliance), the CMS Region V Office must deny payment for new admissions as mandated by the Social Security Act (the Act) at Sections 1819(h)(2)(D) and 1919(h)(2)(C) and Federal regulations at 42 CFR Section 488.417(b). This mandatory denial of payments will be based on the failure to comply with deficiencies originally contained in the Statement of Deficiencies, upon the identification of new deficiencies at the time of the revisit, or if deficiencies have been issued as the

result of a complaint visit or other survey conducted after the original statement of deficiencies was issued. This mandatory denial of payment is in addition to any remedies that may still be in effect as of this date.

We will also recommend to the CMS Region V Office and/or the Minnesota Department of Human Services that your provider agreement be terminated by July 10, 2017 (six months after the identification of noncompliance) if your facility does not achieve substantial compliance. This action is mandated by the Social Security Act at Sections 1819(h)(2)(C) and 1919(h)(3)(D) and Federal regulations at 42 CFR Sections 488.412 and 488.456.

INFORMAL DISPUTE RESOLUTION

In accordance with 42 CFR 488.331, you have one opportunity to question cited deficiencies through an informal dispute resolution process. You are required to send your written request, along with the specific deficiencies being disputed, and an explanation of why you are disputing those deficiencies, to:

Nursing Home Informal Dispute Process Minnesota Department of Health Health Regulation Division P.O. Box 64900 St. Paul, Minnesota 55164-0900

This request must be sent within the same ten days you have for submitting an ePoC for the cited deficiencies. All requests for an IDR or IIDR of federal deficiencies must be submitted via the web at: http://www.health.state.mn.us/divs/fpc/profinfo/ltc/ltc idr.cfm

You must notify MDH at this website of your request for an IDR or IIDR within the 10 calendar day period allotted for submitting an acceptable electronic plan of correction. A copy of the Department's informal dispute resolution policies are posted on the MDH Information Bulletin website at: http://www.health.state.mn.us/divs/fpc/profinfo/infobul.htm

Please note that the failure to complete the informal dispute resolution process will not delay the dates specified for compliance or the imposition of remedies.

Questions regarding all documents submitted as a response to the Life Safety Code deficiencies (those preceded by a "K" tag), i.e., the plan of correction, request for waivers, should be directed to:

Mr. Tom Linhoff, Fire Safety Supervisor Health Care Fire Inspections Minnesota Department of Public Safety State Fire Marshal Division 445 Minnesota Street, Suite 145 St. Paul, Minnesota 55101-5145

> Email: tom.linhoff@state.mn.us Telephone: (651) 430-3012

Fax: (651) 215-0525

Feel free to contact me if you have questions.

Sincerely,

Kamala Fiske-Downing

Minnesota Department of Health Licensing and Certification Program

Kumalu Fish Downing

Program Assurance Unit Health Regulation Division

Telephone: (651) 201-4112 Fax: (651) 215-9697

PRINTED: 02/09/2017 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			E CONSTRUCTION		E SURVEY IPLETED
		24E166	B. WING			01/	10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			7	TREET ADDRESS, CITY, STATE, ZIP CODE 15 WEST 31ST STREET IINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULE CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
F 000	INITIAL COMMENT	ΓS	FC	000			
	signature is not req						
E 225	revisit of your facilit validate that substa regulations has bee your verification.	acceptable POC an on-site y may be conducted to ntial compliance with the en attained in accordance with	F 2	225			2/1/17
SS=D	ALLEGATIONS/INE (a) The facility mus	DIVIDUALS	1 2	23			2/1/17
	, ,	therwise engage individuals					
		d guilty of abuse, neglect, propriation of property, or court of law;					
	nurse aide registry	ng entered into the State concerning abuse, neglect, atment of residents or their property; or					
	or her professional body as a result of	ary action in effect against his license by a state licensure a finding of abuse, neglect, atment of residents or resident property.					
	licensing authorities	ate nurse aide registry or sany knowledge it has of if law against an employee,					
A BODATODY	/ DIRECTOR'S OR PROVID	ER/SUPPLIER REPRESENTATIVE'S SIG	NIATLIDE		TITI F		(X6) DATE

Electronically Signed 02/03/2017

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` '	PLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED		
		24E166	B. WING		01/	10/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	,	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUI CROSS-REFERENCED TO THE APPRO DEFICIENCY)	_D BE	(X5) COMPLETION DATE
F 225	nurse aide or other (c) In response to a exploitation, or mis (1) Ensure that all a abuse, neglect, expincluding injuries of misappropriation of reported immediate after the allegation cause the allegation serious bodily injury the events that cau abuse and do not reported immediate after the allegation serious bodily injury the events that cau abuse and do not reported immediate adult protective serfor jurisdiction in locaccordance with Staprocedures. (2) Have evidence thoroughly investigation, or mis investigation is in performance and with State law, including the alleged violatic corrective action missing the alleged violatic corrective action missing explosion.	te unfitness for service as a facility staff. allegations of abuse, neglect, treatment, the facility must: alleged violations involving ploitation or mistreatment, in unknown source and is resident property, are ply, but not later than 2 hours is made, if the events that in involve abuse or result in y, or not later than 24 hours if see the allegation do not involve esult in serious bodily injury, to fithe facility and to other to the State Survey Agency and vices where state law provides ing-term care facilities) in ate law through established that all alleged violations are ated. potential abuse, neglect, treatment while the rogress. Its of all investigations to the story or her designated to other officials in accordance adding to the State Survey orking days of the incident, and on is verified appropriate	F 22	5		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` '	LE CONSTRUCTION	(X3) DATE SURVEY COMPLETED		
		24E166	B. WING	 	01/	10/2017
	PROVIDER OR SUPPLIER		:	STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
F 225	review, the facility f	tion, interview and document ailed to operationalize their nducting background checks	F 225	See attached document labele 1B: A new reference check pol written and all employees invol hiring process have been educ this policy. All potential new hir documentation of reference ch Reference check verification for	icy was ved in the ated on es will have ecks on the	
	List By D/M/Y (date E2, E3, E4, and E5 dates of 9/21/16 the A review of E2's enemployed at the face	nployee file indicated she was cility beginning on 9/27/16. The I not include any record of		will be attached to the applicati managers who are involved in process will be responsible. But Office Manager will monitor to reference check form is filled of filing new employee file in Busit Office. All managers and Busit Director responsible for compli	on. All the hiring siness be sure ut before ness ess office	
	employed at the factor The employment fill reference check. A review of E5's ememployed at the factor is the factor in the fact	inployee file indicated she was cility beginning on 10/111/16. e did not contain evidence of a inployment file indicated he was cility beginning on 12/6/16. ecord did not contain evidence				
	During an interview on 1/10/17, at 4:00 p.m. the business office manager (BOM) stated the director of nutritional services (DNS) was responsible for completing the reference checks for E1 and E5. She stated the DNS was not available and verified no reference checks were in the employee files. During an interview on 1/10/17, at 4:33 p.m., the director of nursing (DON) stated she did not complete a reference check for E3. She stated she had worked with E3 in the past. The DON					

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` '	IPLE CONSTRUCTION NG		E SURVEY MPLETED
		24E166	B. WING _		01/	/10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	•	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	_D BE	(X5) COMPLETION DATE
F 225 F 226 SS=D	stated she had not and stated she did the last 10 years. A facility policy titled Vulnerable Adult Poindicated the facility procedures geared which include: Screemployment in the a minimum: referent past employer. The information from premployers in effort information about a 483.12(b)(1)-(3), 48 DEVELOP/IMPLME POLICIES 483.12 (b) The facility must written policies and (1) Prohibit and preexploitation of resident property, (2) Establish policies investigate any successive suc	worked with E3 for ten years not know her work history for d Birchwood Care Home blicy, dated July 16, 2015, a maintains policies and toward abuse prevention ening all applicants for facility. Screening to include at tice checks from current and/or facility did not check for evious and/or current to uncover any potential my past criminal prosecutions. 33.95(c)(1)-(3) ENT ABUSE/NEGLECT, ETC at develop and implement procedures that: Vent abuse, neglect, and ents and misappropriation of the sand procedures to	F 23			2/1/17

AND DUAN OF CODDECTION TO THE TOTAL NUMBER.		, ,	TPLE CONSTRUCTION NG		(X3) DATE SURVEY COMPLETED	
		24E166	B. WING _		01/	10/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP COD 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
F 226	educates staff on- (c)(1) Activities that exploitation, and miproperty as set forth (c)(2) Procedures for neglect, exploitation resident property (c)(3) Dementia maprevention. This REQUIREMENT by: Based on observative review, In addition, operationalize their background checks reviewed. Findings include: A facility policy titled Vulnerable Adult Poindicated the facility procedures geared which include: Screemployment in the aminimum: reference past employer. A review of a facility List By D/M/Y (date E2, E3, E4, and E5 dates of 9/21/16 throw A review of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed at the facility and E5 dates of E2's ememployed E2's ememployed at the facility and E5 dates of E2's ememployed E2's em	constitute abuse, neglect, sappropriation of resident in at § 483.12. or reporting incidents of abuse, in, or the misappropriation of an agement and resident abuse. It is not met as evidenced at a evidence and a ev		See attached document labeled 1B: A new reference check powritten and all employees invohiring process have been educt this policy. All potential new hir documentation of reference check verification fowill be attached to the applicat managers who are involved in process will be responsible. But Office Manager will monitor to reference check form is filled of filing new employee file in Bus Office. All managers and Busin manager are responsible.	licy was lived in the cated on res will have necks on the orm which ion. All the hiring usiness be sure out before iness	

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING		` '	E SURVEY MPLETED
		24E166	B. WING _		01/	10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	·	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETION DATE
F 226	employed at the factor The employment fill reference check. A review of E5's ememployed at the factor of a reference check. During an interview business office mandirector of nutritional responsible for comfor E1 and E5. She	apployee file indicated she was cility beginning on 10/111/16. e did not contain evidence of a apployment file indicated he was cility beginning on 12/6/16. ecord did not contain evidence k. on 1/10/17, at 4:00 p.m. the mager (BOM) stated the all services (DNS) was appleting the reference checks stated the DNS was not ed no reference checks were	F 22	26		
F 279 SS=D	Director of Nursing complete a reference she had worked with stated she had not and stated she did the last 10 years. To information from premployers in effort information about a 483.20(d);483.21(b) COMPREHENSIVE 483.20 (d) Use. A facility massessments components in the reside		F 21	79		2/2/17

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` '	FIPLE CONSTRUCTION NG		(X3) DATE SURVEY COMPLETED	
		24E166	B. WING _		01.	/10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP C 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE	(X5) COMPLETION DATE
F 279	and revise the resic plan. 483.21 (b) Comprehensive (1) The facility must comprehensive per each resident, consist forth at §483.10 includes measurable to meet a resident's and psychosocial nicomprehensive associated plan must des (i) The services that or maintain the resiphysical, mental, ar required under §48. (ii) Any services that under §483.24, §48 provided due to the under §483.10, includer §483.1	Care Plans It develop and implement a son-centered care plan for sistent with the resident rights (c)(2) and §483.10(c)(3), that le objectives and timeframes is medical, nursing, and mental eeds that are identified in the ressment. The comprehensive cribe the following - It are to be furnished to attain dent's highest practicable and psychosocial well-being as 3.24, §483.25 or §483.40; and att would otherwise be required 33.25 or §483.40 but are not resident's exercise of rights uding the right to refuse 83.10(c)(6). Services or specialized es the nursing facility will	F 2'	,		
	rationale in the resid	ARR, it must indicate its dent's medical record. with the resident and the tative (s)-				

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED		
		24E166	B. WING			01/-	10/2017
	PROVIDER OR SUPPLIER			71	TREET ADDRESS, CITY, STATE, ZIP CODE 15 WEST 31ST STREET IINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPF DEFICIENCY)	BE	(X5) COMPLETION DATE
F 279	desired outcomes. (B) The resident's properties of the resident of the requirements of the requirements of the requirements of the requirement of the resident of the residen	goals for admission and preference and potential for acilities must document nt's desire to return to the sessed and any referrals to sies and/or other appropriate pose. Is in the comprehensive care e, in accordance with the orth in paragraph (c) of this orth in paragraph (c) of this orth in paragraph (c) of this orth in the orth in paragraph (c) of this orth in paragraph (d) of this orth in the orth in paragraph (d) of this orth in the orth in	F 2	79	Birchwood Care Home IDT discuss any falls every day in morning meet including causal factors and necess interventions. R29 was receiving Procurrently going to pool therapy and ambulates with a walker. Her care was reviewed and revised. The falls assessment policy was reviewed an updated, see attachment #1E. See form 2E and 3E, we have revised of tracking and documentation of falls use during our morning meeting to with watching for patterns and import tracking of interventions including a to the careplan. Any falls will be documented on the communication for a period of 2 weeks to be sure a are aware of recent falls. Audit of p months of falls was done to assure care plans are up to date. Education has been initiated for nurstaff. Remainder of nursing staff wieducated on updated policy and ne	ting sary T, is plan s risk nd also our for assist oved adding n page all staff ast 6 all rsing II be	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		, ,	TIPLE CONSTRUC	` /	(X3) DATE SURVEY COMPLETED		
		24E166	B. WING			01/	/10/2017
	PROVIDER OR SUPPLIER			715 WEST 31	RESS, CITY, STATE, ZIP CODE ST STREET LIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	(EAC	ROVIDER'S PLAN OF CORRECT CH CORRECTIVE ACTION SHOU S-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETION DATE
F 279	assessment dated sustained multiple to used assistive devior of shuffling steps. It indicated she had a while using her wal reminded of safety slowly, using her caneeded. A review of R29's E Progress Notes alouncident Report For falls: 12/17/16, and station and reported find R29 on the flood 12/17/16, indicated walker and fell bacton floor at the ended denies hitting head 12/13/16, indicated advised to be more called for help to gestaff she woke up to balance when standated 6/25/16 indicher bed. A Progress indicated an interdifall was completed was related to her walker. On 5/13/16 The resident was ly her bed, stated she bed. On 5/4/16, R2 trying to use the balance. She was	11/23/16, indicated R29 falls in the last six months, ces and ambulated with short. The assessment further a steady gait and good balance ker and continued to be measures including rising ane and asking for help as an and asking for help as an an an an an asking for help as an	F 2'	forms at February brought t review a Director	a mandatory nursing mey 19th. The falls logs will to quarterly QAPI meeting and discussion. In the falls logs will be responsible for the factor will be responsible for the factor.	be gs for Care	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING			01/10/2017
-	PROVIDER OR SUPPLIER	,		STREET ADDRESS, CITY, STATE, ZIP C 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF COF (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE
F 279	sat at a table. R29 ambulating and who chair. During the in lot of falls. She state spells" and stated, my bed." R29 state recent falls with he During an interview assistant director of a resident and fills of stated the incident of nursing (DON). Interventions should to the care plan. During an interview DON stated falls we morning meeting. Spotential causes, lot discuss physical that to look at medication interview at 4:50 p. assessment was constated if there were time an extra one we "probably had not realls for R29." She doing "super good" of her most recent. During an interview registered nurse (Fin about a year and stated she was a hishe has fallen, it we not get a report. Do	appeared steady while en lowering herself into the terview, R29 stated she had a ted she sometimes has "dizzy "It's a project getting up from to no one had discussed her r." on 1/10/17, at 3:49 p.m., the f nursing (ADON) stated when floor nurse assessed the ut an incident report. She report is given to the director The ADON stated after a fall, dobe implemented and added on on 1/10/17, at 3:50 p.m., the ere discussed daily in the She stated they look for took at the environment, erapy, or talk to the pharmacist on. During a subsequent m., the DON stated a fall risk ompleted with each MDS. She is multiple falls in a period of would be done but stated they eviewed any of the December further stated she felt R29 was and had not done an analysis	F 2	79		

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/	10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPROFILE OF THE A) BE	(X5) COMPLETION DATE
F 279		ge 10 rd R29 talk about her falls but ny specific interventions for	F 2	79		
F 323 SS=D	of which occurred in no evidence the fac- effort to determine a new interventions to from further falls.	story of falls in the facility, two in the past 30 days, there was sility reviewed the falls in an a root cause or implement any or minimize potential injury 1)-(3) FREE OF ACCIDENT VISION/DEVICES	F 3	23		2/1/17
		sure that - vironment remains as free rds as is possible; and				
		eceives adequate supervision ices to prevent accidents.				
	appropriate alternation bed rail. If a bed or must ensure correct	e facility must attempt to use tives prior to installing a side or side rail is used, the facility it installation, use, and rails, including but not limited ments.				
	(1) Assess the residence from bed rails prior	dent for risk of entrapment to installation.				
		s and benefits of bed rails with dent representative and obtain rior to installation.				
		bed's dimensions are resident's size and weight.				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIP A. BUILDING	(X3) DATE SURVEY COMPLETED		
		24E166	B. WING		01/10/2017
	PROVIDER OR SUPPLIER		7	STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE COMPLÉTION
F 323	This REQUIREMED by: Based on observareview, the facility finterventions to pre (R29) reviewed for Findings include: R29's care plan dafalls and directed sposition slowly, renreminders to seek condition, and weawear. The care plapsychotropic drug comfort and episod R29's quarterly Mir 11/23/16, indicated cognitively impaired problems and inatteindicated R29 was ambulation, dressin but required supervassessment dated sustained multiple used assistive deviof shuffling steps. Indicated she had awhile using her wal reminded of safety slowly, using her caneeded. A review of R29's E Progress Notes alc Incident Report Formal review of R29's E Progress Notes alc Incident Report Formal R29's E Progress Notes alc Incident R29's E Progress Notes A Progr	NT is not met as evidenced tion, interview and document ailed to implement event falls for 1 of 1 resident falls. ted 8/5/16 indicated a risk for taff to remind her to change ninders to slow down, help in community during icy r proper and non-slip foot	F 323	Birchwood Care Home IDT discuss any falls every day in morning meet including causal factors and necess interventions. R29 was receiving Pourrently going to pool therapy and ambulates with a walker. Her care placed was reviewed and revised. The falls assessment policy was reviewed an updated, see attachment #1E. See form 2E and 3E, we have revised of tracking and documentation of falls use during our morning meeting to with watching for patterns and impound imposed interventions. Any falls we documented on the communication for a period of 2 weeks to be sure a are aware of recent falls. An audit we done of the past 6 months of falls to sure interventions were implemented prevent falls. Education has been initiated for nurstaff. Remainder of nursing staff will educated on updated policy and neforms at a mandatory nursing meet February 19th. The falls logs will be brought to quarterly QAPI meetings review and discussion. Director of Nursing and Resident C Coordinator will be responsible for compliance.	cing sary T, is plan s risk also ur for assist oved vill be page all staff vas be d to rsing I be w ing for

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` '	TIPLE CONSTRUCTION NG		(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01	/10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP C 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE	(X5) COMPLETION DATE
F 323	station and reporter find R29 on the flood 12/17/16, indicated walker and fell back-12/16/16, R29 has extremities right shathigh12/13/16, R29 sat No injury noted, dereport form dated 1 the floor and was a -12/7/16, care confimeds and history ogood, balance is stoof mobility6/25/16, R29 caller floor. R29 told staff bathroom but lost be incident report form fell backward onto dated 6/27/16, indic (IDT) review of fall R29 felt her fall was and not using her was -5/13/16, writer call lying on her back as she tripped coming progress noted indicated determined fall resigiven to slow down	d R29 fell. Staff responded to br, and incident report dated R29 was reaching for her kward. bruising on bilateral lower in and left knee and left inner on floor at the end of her bed. The hitting head. An incident 2/13/16, indicated she sat on dvised to be more careful. The erence note- Fall risk due to falls, rolling walker. Gait is eady. Independent in all areas of for help to get up from the she woke up to use the halance when standing. An indicated 6/25/16, indicated R29 there bed. A Progress Note cated an interdisciplinary team was completed and indicated is related to her new slippers	F 3:			
	identified no new re-5/4/16, R29 had a use the bathroom. 8 centimeters (cm) and a 3 cm x 4 cm arm.	w medications. The review ecommendations. fall at 1:50 a.m. while trying to On assessment a "big" bruise x 8 cm was noted to left knee bruise on the back of her left sed the residents fall that				

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING _		01	10/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	, ,,,	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETION DATE
F 323	morning. R29 state the bathroom, lost encouraged to slow monitor2/23/16, Writer intrecent fall while ge an outing. Reviewe changes necessary. At 1:38 p.m., on 1/3 surveyor. She was a walker. She amb sat at a table. R29 ambulating and who chair. During the in lot of falls. She state spells" and stated, my bed." R29 state recent falls with he During an interview assistant director of a resident and fills ou stated the incident of nursing (DON). Swere related to chastiding down in bed interventions shoul to the care plan. During an interview DON stated falls we morning meeting. Spotential causes, lo discuss physical the to look at medicatic R29's falls were related to state the look at look a	d she woke up and had to use her balance and fell. Resident v down and continue to erviewed R29 and analyzed ting in and out of van during d falls risk assessment with no v. 10/17, R29 approached ambulating independently with ulated to the dining room and appeared steady while en lowering herself into the terview, R29 stated she had a ded she sometimes has "dizzy "It's a project getting up from the do no one had discussed her	F 32	3		

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		TIPLE CONSTRUCTION NG		(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/	10/2017	
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)) BE	(X5) COMPLETION DATE	
F 323	report. During a subp.m., the DON state completed with each were multiple falls i would be done but done one in Decemstated she felt R29 had not done an an During an interview registered nurse (Rin about a year and stated she was a hishe has fallen, it was not get a report. Dustated R29 misjudg stated she had hea While R29 had a hiof which occurred in no evidence the facelity continued to intervention for falls assessments indicaproblem.	locumented on the incident osequent interview at 4:50 and a fall risk assessment was h MDS. She stated if there in a period of time an extra one stated they "probably hadn't ober for R29." She further was doing "super good" and alysis of her most recent falls. on 1/10/17, at 5:13 p.m., N)-A stated R29 had not fallen half that she was aware of but gh risk for falls. RN-A stated, if as not on her shift and she did wring the interview LPN-A ed her seating a lot. She rd R29 talk about her falls. story of falls in the facility, two in the past 30 days, there was stillity reviewed the falls in an a root cause. Furthermore, the implement reminders as an a root cause and a root cause arout and a root cause and a root cause arout and a root cause arout a root	F 3			2/2/17	
30-L	(d) Influenza and pi	neumococcal immunizations					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCT A. BUILDING		TIPLE CONSTRUCTION NG	` '	E SURVEY MPLETED		
		24E166	B. WING _		01/	/10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE- ((EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
F 334	each resident or the receives education potential side effect (ii) Each resident is immunization October annually, unless the contraindicated or timmunized during the contraindicated endough the contraind	ne influenza immunization, e resident's representative regarding the benefits and is of the immunization; offered an influenza per 1 through March 31 immunization is medically he resident has already been his time period; the resident's representative to refuse immunization; and medical record includes indicates, at a minimum, the into resident's representative ation regarding the benefits offects of influenza in the either received the influenza in the receive the influenza in medical contraindications or disease. The facility must disease. The facility must disease. The facility must disease to ensure that-	F 33	34		

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
	24E166	B. WING		01/	10/2017	
NAME OF PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP COD			
			715 WEST 31ST STREET			
BIRCHWOOD CARE HOME			MINNEAPOLIS, MN 55408			
PREFIX (EACH DEFICIENCY MU	IENT OF DEFICIENCIES ST BE PRECEDED BY FULL DENTIFYING INFORMATION)	ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE		
(iv) The resident's med documentation that ind following: (A) That the resident of was provided education and potential side effect immunization; and (B) That the resident elementary in the pneumococcal immunitation or refut the pneumococcal immunitation or refut this REQUIREMENT by: Based on interview an facility failed to implem of immunization for pneumococcal immunization for pneumococc	the immunization is ted or the resident has ted; resident's representative refuse immunization; and dical record includes licates, at a minimum, the resident's representative in regarding the benefits ets of pneumococcal received the zation or did not receive nunization due to medical isal. It is not met as evidenced and document review, the ent the current standards reumonia for 3 of 5 to 337), over 65 years old, ories were reviewed. That not implemented their nunizations for pneumonia 3 residents of the facility	F 3	The immunization policy and was reviewed and updated to current guidelines. A letter out new guidelines and requesting to administer the pneumovax has been sent to all primary cappointments. Goal is to have resident assessed by their MD vaccination with the PCV 13 w next 90 days unless it is contror they have previously receive attachment 1F and 2F for the letter and updated policy. Our admission immunization form updated to reflect current guid well for any new admissions c	reflect the lining the physicians njections are Dr. every for ithin the aindicated ed one. See ohysician new will be elines as		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING			01/ ⁻	10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			7	TREET ADDRESS, CITY, STATE, ZIP CODE 15 WEST 31ST STREET IINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	(PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPF DEFICIENCY)	BE	(X5) COMPLETION DATE
F 334	13-valent Conjugate of PCV13 should be year after the most R17's record indicate the facility since Jaidocumentation to ir offered or administe R18's record indicate facility since Octocumentation to ir offered or administe R37's record indicate facility since Jaidocumentation to ir offered or administe During an interview (DON) and assistant on 1/10/17, at 2:54 facility process for protocomposition of the process for prot	a dose of pneumococcal e Vaccine (PCV13). The dose e administered at least one recent PPSV23 dose." ted the resident had resided at nuary 2016, there was no ndicate a PCV13 had been ered. ted the resident had resided at stober 2015, there was no ndicate a PCV13 had been ered. ted the resident had resided at stober 2015, there was no ndicate a PCV13 had been ered. ted the resident had resided at nuary 2007, there was no ndicate a PCV13 had been ered. with the director of nursing nt director of nursing (ADON) p.m., The DON stated the oneumonia immunizations had ted. The DON and ADON residents over the age of 65 munization offered or cled Influenza and nunizations dated 5/2/2007,	F 3	34	Care Coordinator, Director of Medic Records are responsible for compli		
F 371 SS=F	resident." 483.60(i)(1)-(3) FO		F 3	71			2/1/17

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` '	LE CONSTRUCTION ((X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/10/2017
	PROVIDER OR SUPPLIER		7	STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD I CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	BE COMPLÉTION
F 371	Continued From pa	ge 18	F 371		
		d from sources approved or story by federal, state or local			
	 (i) This may include food items obtained directly from local producers, subject to applicable State and local laws or regulations. (ii) This provision does not prohibit or prevent facilities from using produce grown in facility gardens, subject to compliance with applicable safe growing and food-handling practices. 				
		loes not preclude residents ods not procured by the facility.			
		re, distribute and serve food in ofessional standards for food			
	(i)(3) Have a policy regarding use and storage of foods brought to residents by family and other visitors to ensure safe and sanitary storage, handling, and consumption. This REQUIREMENT is not met as evidenced	sidents by family and other afe and sanitary storage, umption.			
	review, the facility f dishwashing tempe potential spread of the potential to affe	tion, interview, and document ailed to maintain safe tratures to prevent the food borne illness which had ct all 57 residents in the sitors who ate out of the		The dishwashing temperature was immediately corrected by Ecolab. Al Dietary staff were immediately re-educated regarding appropriate temperatures of the dish machine, a Dietary training will be conducted wi weeks. See attachment 1D, dishmatemperature log. Dietary manager w	n all thin 2 chine
	Findings include:			responsible for supervising, Assistant Dietary manager will monitor log and	nt d spot
		chen tour on 1/09/17, at 1:21 rector of nutrition services		check temperature a minimum of 3 per week. See attachment 2D for	times

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIP A. BUILDING	LE CONSTRUCTION		(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/	10/2017
	PROVIDER OR SUPPLIER	•		STREET ADDRESS, CITY, STATE, ZIP (715 WEST 31ST STREET MINNEAPOLIS, MN 55408	<u> </u>	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CORRECTION Y MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE		
F 371	compartment dish the manufacturer ic indicated a minimu Fahrenheit (F) and 2017 dishwashing indicating all temper the wash cycle and rinse cycle. The DN dishes through the temperature gauge dishwasher read: #1 156F wash, 177 #2 149F wash, 174 #3 168F wash, 179 During interview or (C)-A stated he was been running below stated the dishwas three times a day, low recorded temperature to runcheck it. The regist rinse cycle should be not aware of the low Review of the Dish indicated: December 2016 - 2 recorded, all 142F November 2016 - 5 recorded, all below rinse October 2016 - 84	used a high temperature, one machine. This was verified by dentification plate which m wash of 150 degrees rinse of 180F. The January, temperature log was reviewed eratures were below 144F for 1 below 177 degrees F for the NS then ran three loads of dishwasher. The digital on the outside of the PF rinse PF r	F 371	Assistant manager checklis Infection Control nurse will for compliance.		

AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING _		01	/10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP COI 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES YMUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORR (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE AF DEFICIENCY)	HOULD BE	(X5) COMPLETION DATE
F 371	recorded, 54 of whi below 174F for rins August 2016- 80 of recorded, 51 of whi and 178F for rinse July 2016 - not prov. June 2016- 76 of 96 of which were befor rinse During an interview DNS stated he called paper products become chemical test strips three compartment stated "sometimes but not lately though not tell him about the temperatures for the During an interview Ecolab representation contacted before to temperatures and a contractor a couple "had nothing to do machine." ER states set to 178F, he did now. Three more diwash 168F, rinse 1 wash 173F, rinse 1 wash 174F, rinse 1 During an interview Cook-A stated he the states of the sta	58 of 90 opportunities were ch were 142F for wash and e 93 opportunities were ch were below 145F for wash yided 0 opportunities were recorded, elow 145F for wash and 176F on 1/9/17, at 1:45 p.m., the ed Ecolab, they would use ause they did not have nor a policy for using the sink to wash dishes and I monitor the temperatures, h." DNS verified the staff did he continuous low e wash and rinse cycles. on 1/9/17, at 2:30 p.m., an eve (ER) stated he was not day about low wash and rinse although he had replaced a months prior stated that it with the temperatures of the d the internal board had been not know why, but turned it up ish load were observed to be: 88F 91F 96F on 1/9/17, at 2:32 p.m. hought the rinse should be yith what it should be, I take a lot	F 3'	71		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/ ⁻	10/2017	
NAME OF PROVIDER OR SUPPLIER BIRCHWOOD CARE HOME			7	TREET ADDRESS, CITY, STATE, ZIP CODE 15 WEST 31ST STREET MINNEAPOLIS, MN 55408			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPF DEFICIENCY)	BE	(X5) COMPLETION DATE	
F 465 SS=F	two dishwashing cy wash 156F, rinse 18 wash 166F, rinse 18 wash 166F, rinse 18 wash 166F, rinse 18 Review of undated Log instructions ind through an entire w temperature before should be Wash 15 should be 180 F and Review of the facility February 2016 through an entire with the facility. 483.90(h)(5) SAFE/FUNCTIONALE ENVIRON (h) Other Environment The facility must prosanitary, and comforms anitary, and comforms and smoking safety non-smoking regarding and smoking safety non-smoking resided This REQUIREMENT by: Based on observations	cles were observed to be: 32F 34F Dish machine Temperature icated "run the dishwasher ash-rinse cycle and record the use, dishwasher temperature 0 F or above and Rinse d above." y infection control logs from ugh January 9, 2017 indicated ointestinal illness outbreak in allowed a safe, functional, ortable environment for the public. cies, in accordance with State, and local laws and ng smoking, smoking areas, othat also take into account	F 371	The dish room area has been clea including walls, dishwasher, doorwa	ned	2/1/17	
	clean environment i	in the kitchen. This had the I 57 residents in the facility out of the facility kitchen. In		entering the kitchen. See attachme 2C and 3C for updated policies. The Dietary Manager will be responsible	nt 1C, e		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING		` '	(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/	10/2017	
	PROVIDER OR SUPPLIER	•	;	STREET ADDRESS, CITY, STATE, ZIP CODI 715 WEST 31ST STREET MINNEAPOLIS, MN 55408			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE	
F 465	orderly and comfor second and third floincluded resident refined included resident refined includes includes including the DNS: The dish room are 6 ft X 6 ft: on and a legs and where the a grimy, brown/blace The walls around stainless steel table dish area) of the or had food splatter graded includes a feet. The lower half of dishwasher was consplatter, debris and unit. Both sides of the was splattered with chipped off both side on 1/10/17, at 12:4 the kitchen the followerified by the DNS. The plastic corner dish room was craced includes and third flowerified by the DNS.	refailed to maintain a sanitary, table interior throughout the cors of the facility which coms. p.m. during the initial kitchen it's director of nutrition services go was observed and verified by the early approximately 10 feet (ft) X thround all stainless steel table is wall meets the floor there was calcapted the wall meets the floor there was calcapted to the right and left (clean the compartment dishwasher or	F 465	supervision. The Assistant Die Manager will monitor at least 3 week to be sure cleaning log is and that appropriate cleaning I done. The plastic corner protect been ordered and will be replated soon as they are received but than 30 days. The door frame painted. The Formica counter the ice machine and cabinet do been cleaned so surface soil horemoved but these cabinets with replaced within 60 days. All en issues listed will be repaired on within 90 days. Director of mairesponsible for compliance.	times per s up to date has been ctors have ced as no greater was top under pors have as been Il be vironmental painted		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01	/10/2017	
	NAME OF PROVIDER OR SUPPLIER BIRCHWOOD CARE HOME (X4) ID SUMMARY STATEMENT OF DEFICIENCIES			STREET ADDRESS, CITY, STATE, ZIF 715 WEST 31ST STREET MINNEAPOLIS, MN 55408			
(X4) ID PREFIX TAG			ON SHOULD BE HE APPROPRIATE	(X5) COMPLETION DATE			
F 465	under the ice mach brown specks imbeleft of the coffee m Formica was lifted the left of ice mach lower cabinet doors coffee stains. - To the right of the the dirty dish plasti splattered with foor ripped and coming three feet in length During interview or DNS verified the elbe cleaned and stacleaned everyday to the dishwasher is composed to be clear request a supply composed to be clear request a supply composed to be clear request a supply composed to see where the dishwasher is composed to see where the same of undated policies: - "Sanitation of Die staff to maintain the condition. It indicat be posted for all clear real clear regulations of the staff to maintain the condition. It indicat the posted for all clear regulations of the staff to maintain the condition. It indicat the posted for all clear regulations of the staff to maintain the condition. It indicat the posted for all clear regulations of the staff to maintain the condition. It indicat the posted for all clear regulations of the staff to maintain the condition. It indicat the posted for all clear regulations of the staff to maintain the condition. It indicat the posted for all clear regulations of the staff to maintain the condition. It indicates the posted for all clear regulations of the staff to maintain the condition of the staff to maintain the condit	brown stains on the Formica nine and brown stains with edded in the stain area to the aker. The center seam in the up and coming apart. Wall to nine and the front of all the s was splattered with food and kitchen entry the wall behind c bin container was heavily d debris. The wallpaper was apart at a seam approximately	F4	65			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/	10/2017	
NAME OF PROVIDER OR SUPPLIER BIRCHWOOD CARE HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		10/2011	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPERTION DEFICIENCY)	D BE	(X5) COMPLETION DATE	
F 465	and the RD will more monthly. - "Cleaning Walls" - from food particles cleaned at least one - "Maintenance of Distriction of the machine will be assure proper function cleaned, de-limed at the machine be cleated. - "Cleaning Floors" dining room floors will be a thorough cleaning done at least twice During an environm maintenance (DM) following observation. -Room 202 had six the bathroom floor. -Room 203 had a total closet and inside the patched but not pail and closet and inside the area above the toile ceiling that had been match the ceiling.	weekly to ensure completion nitor kitchen sanitation indicated the walls will be free and dirt and they should be ce a month and as needed. Dish Machine" - indicated the e properly maintained to tioning, would be regularly as needed and the outside of aned with soap and water. - indicated the kitchen and will be kept clean and sanitary, e swept and cleaned daily and gusing a disinfectant will be a week. Inental tour with the director of on 1/10/17, at 3:50 p.m. the ons were confirmed. In bathroom tiles missing from the poilet bolt cover missing. In ceiling above the toilet of the e doorway of the room. The et had a brown area on the en repaired and not painted to air conditioner unit in the wall	F 465				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			TIPLE CONSTRUCTION NG		(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/	10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			STREET ADDRESS, CITY, STATE, ZIP COI 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORE ((EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE AF DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE
F 465	Throughout the sec wallpaper was peel several baseboards the walls. The DM of treatment provided and there were plar wallpaper, paint the the trim and baseboresident rooms. The official bids for this During an interview 1/10/17, at 4:17 p.n bids for maintenancoutside companies facility would complete.	cond and third floor the ing away from the wall and and trim were missing from confirmed this was from a to the facility related to pests as in place to repair the walls and ceiling and repair pards in the hallways and a DM stated there were no work to be completed. with the Administrator on and, he confirmed he had no be work to be completed by a The administrator stated the lete the work due to the cost.	F 4	65		

FE166026

PRINTED: 02/07/2017 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` ′	PLE CONSTRUCTION G 01 - MAIN BUILDING 01		E SURVEY IPLETED
		24E166	B WING_		01/	10/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPI DEFICIENCY)	ULD BE	(X5) COMPLETION DATE
K 000	THE FACILITY'S PALLEGATION OF ODEPARTMENT'S ASIGNATURE AT THE PAGE OF THE CMUSED AS VERIFICOUSED AS VERIFICOUSED TO SUBSTANTIAL COREGULATIONS HACCORDANCE WAS found not in corequirements for page Medicare/Medicaid 483.70(a), Life Safe edition of National (NFPA) Standard 10 Chapter 19 Existing edition of NFPA 99 Code.	COC WILL SERVE AS YOUR COMPLIANCE UPON THE ACCEPTANCE. YOUR HE BOTTOM OF THE FIRST IS-2567 FORM WILL BE CATION OF COMPLIANCE. OF AN ACCEPTABLE POC, AN OF YOUR FACILITY MAY BE VALIDATE THAT OMPLIANCE WITH THE AS BEEN ATTAINED IN VITH YOUR VERIFICATION. Survey was conducted by the ment of Public Safety, State on on January 10, 2017. At vey, Birchwood Care Home ompliance with the articipation in I at 42 CFR, Subpart fety from Fire, and the 2012 Fire Protection Association I01, Life Safety Code (LSC), IG Health Care and the 2012 I, the Health Care Facilities I THE PLAN OF OR THE FIRE SAFETY	K 00			
APORATOR	Healthcare Fire Ins State Fire Marshal 445 Minnesota St.,	Division	SNATURE	TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: 00168

02/03/2017

Electronically Signed

	OF DEFICIENCIES OF CORRECTION	IDENTIFICATION NUMBER:	` '	IG 01 - MAIN BUILDING 01		PLETED
		24E166	B, WING_		01/	10/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX T A G	(EACH DEFICIENC)	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPF DEFICIENCY)	ULD BE	(X5) COMPLETION DATE
K 000	DEFICIENCY MUS FOLLOWING INFO 1. A description of to correct the defic 2. The actual, or pr 3. The name and/oresponsible for corprevent a reoccurre Birchwood Care House times. The different times. The constructed in 1960 Type II(222) constructed in 1960 Type I	itate.mn.us and n@state.mn.us RRECTION FOR EACH IT INCLUDE ALL OF THE DRMATION: what has been, or will be, done				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` '					SURVEY PLETED	
			24E166	B. WING			01/1	0/2017
		ROVIDER OR SUPPLIER	*		715	REET ADDRESS, CITY, STATE, ZIP CODE 5 WEST 31ST STREET NNEAPOLIS, MN 55408		
(X4) PREI TAG	FIX	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	K	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
Κű	000	Continued From pa	age 2	ΚC	00			
	163 6=E	NOT MET as evide NFPA 101 Interior Interior Nonbearing Interior nonbearing construction are coor limited-combust Interior nonbearing minimum 2-hour fir fire-retardant-treate noncombustible or provided they are r 18.1.6.4, 18.1.6.5, This STANDARD Based on observate facility did not mair resistance rating o 19.1.6.5. This deficients within the Findings Include: On a facility tour be 1730 on January 1 that the two hour fire	Nonbearing Wall Construction g Wall Construction walls in Type I or II enstructed of noncombustible ible materials. walls required to have a re resistance rating are ed wood enclosed within limited-combustible materials, not used as shaft enclosures.	К 1	63	After correspondence with the Fire Marshall, the following corrective ac will be taken within 30 days: Chemic treat the wood panel with fire retard chemical. Director of Maintenance we responsible.	etion cally ant	2/1/17
	2 11 6=D	maintenance direc NFPA 101 Means of Means of Egress -	tice was verified by the tor at the time of discovery. of Egress - General General lys, corridors, exit discharges,	K	211			2/1/17

PRINTED: 02/07/2017 FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	l`′	IPLE CONSTRUCTION NG 01 - MAIN BUILDING 01		PLETED
		24E166	B. WING_		01/1	10/2017
,,,,,,,	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROI DEFICIENCY)	.D BE	(X5) COMPLETION DATE
	with Chapter 7, and continuously maint full use in case of a 18/19.2.2 through 18.2.1, 19.2.1, 7.1. This STANDARD Based on observate facility did not maintegress that was frea 19.2.11, 19.2.1, 7.1 could effect staff with Findings include: On a facility tour butter 1730 on January 1 that the boiler room by storage. This deficient pracmaintenance direct NFPA 101 Doors with Self-Clapoors in an exit paor horizontal exit, sarea enclosure are closed position, undevice complying with the compartment or enterpretation of the sample of	accesses are in accordance of the means of egress is sained free of all obstructions to emergency, unless modified by 18/19.2.11. 10.1 is not met as evidenced by: ation and staff interview, the ntain a continuous means of the from obstructions. 19.2.2, 1.10.1. This deficient practice within the room. The etween the hours of 0900 and 0, 2017, observation revealed in egress stairs were obstructed of tice was verified by the stor at the time of discovery, with Self-Closing Devices assageway, stairway enclosure, amoke barrier, or hazardous eself-closing and kept in the aless held open by a release with 7.2.1.8.2 that automatically ors throughout the smoke intire facility upon activation of: I fire alarm system; and ectors designed to detect rough the opening or a required system; and	K 2	Stairs and surrounding areas have cleaned to maximize egress. A signosted to remind staff to keep state area clear. Director of Maintenance responsible for supervision and compliance with this area.	gn was iirway	2/1/17
		ystem; and ler system, if installed; and				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		,	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED
		24E166	B. WING		01/10/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES YMUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE COMPLETION
	This STANDARD is Based on observation facility did not main passageways, stair exits, smoke barried 19.2.2.2, 19.2.2.2 could affect resided Findings include: On a facility tour be 1730 on January 1 that the North exit floor corridor, did not latch. This deficient practimal maintenance direct NFPA 101 Stairways and Smoth St	2.8, 19.2.2.2.7, 19.2.2.2.8 s not met as evidenced by: tion and staff interview, the tain self-closing doors in exit way enclosures, horizontal rs, or hazardous areas. 2.8. This deficient practice hts in the smoke compartment. Etween the hours of 0900 and 0, 2017, observation revealed etairway door in the second ot self-close and positively Lice was verified by the tor at the time of discovery. It is and Smokeproof Enclosures okeproof Enclosures okeproof enclosures used as	K 22	Second floor door North was adjust 1/27/17 and tested x 10 times, doo positively latched 10 times. Directo Maintenance is responsible for supervision and compliance with tharea.	or of
	Based on observa facility did not prop	is not met as evidenced by: tion and staff interview, the erly enclose stairways used for 2.2.4, 7.2. This deficient ct all 57 residents.		First floor North exit fire- rated docordered on 1/9/17. Technician from door company stated it would be reweeks until door can be delivered. will be installed immediately upon Maintenance staff will check all fire	n fire oughly 4 Door arrival.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED		
		24E166	B. WING			01/1	10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			71	REET ADDRESS, CITY, STATE, ZIP CODE 5 WEST 31ST STREET INNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 225	1. On a facility tour and 1730 on Januarevealed that there in the exit stairways 2. On a facility tour and 1730 on Januare	between the hours of 0900 ary 10, 2017, observation were combustible decorations is. between the hours of 0900 ary 10, 2017, observation art floor, North exit stairway	К2	225	at least monthly when they are doing monthly fire detector checks. Direct Maintenance is responsible for compliance.		
K 321 SS=E	This deficient practice was verified by the maintenance director at the time of discovery. K 321 NFPA 101 Hazardous Areas - Enclosure		K3	321			2/1/17
		Automatic Sprinkler A Fired Heater Rooms r than 100 square feet)					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			COMPLETED		
		24E166	B. WING			01/1	0/2017
	PROVIDER OR SUPPLIER			71	REET ADDRESS, CITY, STATE, ZIP CODE 5 WEST 31ST STREET INNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE	(X5) COMPLETION DATE
K 321	d. Soiled Linen Roce. Trash Collection (exceeding 64 gallof. Combustible Stor (over 50 square feeg. Laboratories (if of Hazard - see K322 This STANDARD is Based on observa facility did not prophazardous areas. 1 could affect all resicompartment. Findings include: 1. On a facility tour and 1730 on Januarevealed that the lappen with a door with a door with a door with a door with a grant 1730 on Januarevealed that the minus 100 square feet and 100 square feet an	ance, and Paint Shops oms (exceeding 64 gallons) Rooms ons) rage Rooms/Spaces et) classified as Severe) s not met as evidenced by: tion and staff interview, the erly separate and protect 9.3.2.1. This deficient practice dents within the smoke between the hours of 0900 ary 10, 2017, observation aundry room door was held	КЗ	321	Laundry room door was immediate closed, wedge was removed from room and staff was educated on podangers. Medical Records door wil an automatic closing door installed 30 days. Director of Maintenance is responsible for compliance.	laundry otential I have within	
K 341 SS=E	maintenance direct NFPA 101 Fire Alarm System A fire alarm system components appro	tice was verified by the tor at the time of discovery, rm System - Installation - Installation n is installed with systems and ved for the purpose in FPA 70, National Electric Code,		341			2/1/17

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/1	10/2017
	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETION DATE
K 341	provide effective w building. In areas r detection is installe unit. In new occupa at notification appli and supervising sta	onal Fire Alarm Code to rarning of fire in any part of the not continuously occupied, ed at each fire alarm control ancy, detection is also installed lance circuit power extenders, ation transmitting equipment. wiring or other transmission ed for integrity.	K 34	41		
	Based on observation facility did not propried alarm system in 19.3.4.1, 9.6.1.8. The affect all residents of a facility tour beautiful for a facility for a	is not met as evidenced by: ation and staff interview, the berly install components of the n accordance with NFPA 72. This deficient practice could in the smoke compartment. etween the hours of 0900 and 0, 2017, observation revealed annual switch installed in the nel that can disable the tter door in the kitchen.		Test switch in fire panel will be rand direct wired with fire panel. be done within 30 days. Director Maintenance will be responsible.	This will of	
K 346 SS=C	maintenance direct NFPA 101 Fire Alarm - Out of Where required fir services for more	tice was verified by the stor at the time of discovery. Imm System - Out of Service If Service If a larm system is out of than 4 hours in a 24-hour ty having jurisdiction shall be	К 3	46		2/1/17

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	l ' '	LE CONSTRUCTION 6 01 - MAIN BUILDING 01	COMF	E SURVEY PLETED
		24E166	B WING		01/1	10/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROFILIENCY)	D BE	(X5) COMPLETION DATE
K 346	approved fire watch parties left unproted fire alarm system h 9.6.1.6 This STANDARD is Based on observate facility did not proper protocol for when the service for more that	ge 8 ilding shall be evacuated or an shall be provided for all oted by the shutdown until the as been returned to service. Is not met as evidenced by: It ion and document review, the erly implement a fire watch are fire alarm system is out of an 4 hours in 24-hour period. Internation of an 4 hours in 24-hour period. International of an 4 hour period. International of an 4 hour period. International of an 4 hour period	K 346	Birchwood Care Home has devel fire watch tour log sheet in the ever fire alarm system outage. See atta 3 and 4. Director of Maintenance responsible for this.	ent of a achment	
K 353 SS≠F	1730 on January 10 that the facility coul log sheet in the ever outage. This deficient pract of environmental se inspection. NFPA 101 Sprinkler Testing Sprinkler System - Automatic sprinkler inspected, tested, a with NFPA 25, Stan Testing, and Mainta Protection Systems maintenance, inspering maintained in a secondarial secondaria second	tween the hours of 0900 and 0, 2017, observation revealed d not provide a fire watch tour ent of a fire alarm system The was verified by the director ervices at the time of ervices at the time of the Maintenance and the Maintenance and testing and standpipe systems are and maintained in accordance dard for the Inspection, inining of Water-based Fire and Records of system design, ection and testing are sure location and readily system last checked	K 35			2/1/17

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1 ' '	LE CONSTRUCTION 6 01 - MAIN BUILDING 01	COMF	PLETED
		24E166	B. WING		01/1	10/2017
	PROVIDER OR SUPPLIER		-	STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 353	Continued From page 9		K 353	3		
	b) Who provided system test					
	c) Water system supply source					
	any non-required of system. 9.7.5, 9.7.7, 9.7.8, This STANDARD Based on observate facility did not main fire sprinkler system and the 2012 LSC This deficient practices include: On a facility tour bearing include: That the five year, a internal obstruction not performed. The	and NFPA 25 is not met as evidenced by: ation and document review, the ntain and test their automatic m in accordance with NFPA 25 NFPA 101. 9.7.5, 9.7.7, 9.7.8. tice could effect all 57 etween the hours of 0900 and 0, 2017, observation revealed automatic fire sprinkler system in investigation was due but was e last internal obstruction conducted on September 19,		Internal obstruction Investigation i scheduled to be completed on 2/8, will reschedule for every 5 years w Viking Sprinkler. Director of Mainte will be responsible for monitoring a compliance in this area.	/17. We vith enance	
K 354 SS=C	of environmental sinspection. NFPA 101 Sprinkle Sprinkler System - Where the sprinkle extent and duration	er system is impaired, the n of the impairment has been or buildings involved are	K 354	4		2/1/17

PRINTED: 02/07/2017 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED	
		24E166	B. WING			01/1	0/2017
	PROVIDER OR SUPPLIER			71	REET ADDRESS, CITY, STATE, ZIP CODE 5 WEST 31ST STREET INNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	x	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 354	or designated repredepartment and oth jurisdiction have be sprinkler system is hours in a 24-hour of the building affect approved fire watch system has been re 18.3.5.1, 19.3.5.1, This STANDARD is Based on observaticility did not propprotocol for when the system is out of se 24-hour period. 19.	are submitted to management esentative, and the fire her authorities having een notified. Where the out of service for more than 10 period, the building or portion of the country of the provided until the sprinkler	K 3	354	Birchwood Care Home has develoned to hour fire watch tour log sheet in of sprinkler system outage. See attachment 3 and 4. Director of Maintenance will be responsible for compliance in this area.	n case	
K 521 SS=F	On a facility tour be 1730 on January 1 that the facility coulog sheet in the even outage. This deficient pract of environmental sinspection. NFPA 101 HVAC HVAC Heating, ventilation	etween the hours of 0900 and 0, 2017, observation revealed ld not provide a fire watch tour ent of a fire alarm system tice was verified by the director ervices at the time of a shall be installed in the manufacturer's	K	521			2/2/17

Facility ID: 00168

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` '	PLE CONSTRUCTION G 01 - MAIN BUILDING 01		SURVEY PLETED
		24E166	B WING_		01/1	10/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CO 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	DDE	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE
K 521	Continued From pa 18.5.2.1, 19.5.2.1,		K 52	1		
	Based on observa facility's heating, ve in not in compliance 9.2, 19.5.2.1 and No practice could effect and third floor. Findings include: On a facility tour be 1730 on January 1	is not met as evidenced by: tion and staff interview, the entilation, and air conditioning e with the 2012 LSC NFPA 101 IFPA 90A. This deficient ct all residents on the second etween the hours of 0900 and 0, 2017, observation revealed sing the second and third floor haust plenum.		An HVAC worker came and facility, they will be contactin week with a plan. Once we have will resolve the matter will Director of Maintenance and will be responsible for comp	g us next nave direction, thin 120 days. I Administrator	
K 712 SS=C	of environmental sinspection. NFPA 101 Fire Drill Fire Drills Fire drills include the signal and simulating conditions. Fire drill times under varying on each shift. The and is aware that croutine. Responsible conducting drills is persons who are quality where drills are considered.	tice was verified by the director ervices at the time of the transmission of a fire alarm on of emergency fire the list are held at unexpected to goonditions, at least quarterly staff is familiar with procedures the list are part of established dility for planning and the assigned only to competent the light of the exercise leadership. The light of the l	K 71	2		2/1/17

PRINTED: 02/07/2017 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1		E CONSTRUCTION 11 - MAIN BUILDING 01	(X3) DATE COMP	SURVEY
		24E166	B. WING			01/1	0/2017
	PROVIDER OR SUPPLIER OOD CARE HOME			71	REET ADDRESS, CITY, STATE, ZIP CODE 5 WEST 31ST STREET INNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 712	19.7.1.7 This STANDARD Based on docume interview, the facility documentation that once per shift per overying times and on NFPA 101, Section This deficient practices and the second section of the sect	alarms. 3.7.1.7, 19.7.1.4 through is not met as evidenced by: entation review and staff ty could not provide t fire drills were conducted quarter for all staff under conditions as required by 2012 a 19.7.1.4. through 19.7.1.7. tice could affect all 57 etween the hours of 0900 and 0, 2017, observation revealed Id not provide documentation fied alarm signal from the	K 7	712	Birchwood Care Home does Fire per regulation. On the December flog the Alarm verification from the monitoring company was not logge was a clerical error. The monitoring company was notified but an entry omitted. In review of previous 2 ye fire drills, all other verifications were documented. This is corrected immediately through staff education extra reminder will be in place in filling. Director of Maintenance will be responsible for supervision.	ed, this ag was ars of e	
K 781 SS=F	of environmental sinspection. NFPA 101 Portable Portable Space He Portable space he prohibited in all he unless used in nor areas where the he 212 degrees Fahre 18.7.8, 19.7.8 This STANDARD Based on observatacility did not prop	•		781	A space heater Policy has been developed (see attachment #1). A have been educated and the police		2/1/17

Event ID: ENQT21

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1 ' '	LE CONSTRUCTION 01 - MAIN BUILDING 01		E SURVEY PLETED
		24E166	B, WING		01/	10/2017
	PROVIDER OR SUPPLIER OOD CARE HOME		7	STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	.D BE	(X5) COMPLETION DATE
	1730 on January 1 that the facility couldocumentation for the survey a policy as of the date of survey as of environmental survey as 101 Fundam Categories Fundamentals - Burbuilding systems as 1 through 4 require Categories are det	etween the hours of 0900 and 0, 2017, observation revealed Id not initially provide a space heater policy. Later in was produced but was dated urvey. Itice was verified by the director ervices at the time of the entals - Building System Idding System Categories are designed to meet Category ements as detailed in NFPA 99. The ermined by a formal and seessment procedure fied personnel.	K 781	readily available. Director of Main is responsible for supervision.	tenance	2/2/17
	Based on observa facility did not imple procedure for build Category 1 through	is not met as evidenced by: tion and document review, the ement a risk assessment ling systems designed to meet a 4 in accordance with NFPA s deficient practice could affect		We will be contacting an expert evaluation within 120 days. Direct Maintenance and Administrator was responsible for compliance.	tor of	

PRINTED: 02/07/2017 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` ′	PLE CONSTRUCTION G 01 - MAIN BUILDING 01	(X3) DATE COMF	SURVEY PLETED
		24E166	B. WING		01/1	0/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES YMUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX T A G	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROPRIED TO THE APPROPROPROPRIED TO THE APPROPROPROPRIED TO THE APPROPROPROPROPROPROPROPROPROPROPROPROPRO	D BE	(X5) COMPLETION DATE
K 901	On a facility tour be 1730 on January 10 that the facility coul	etween the hours of 0900 and 0, 2017, observation revealed d not provide a risk ed for building systems.	K 90	1		
K 918 SS=F	of environmental se inspection. NFPA 101 Electrica	ice was verified by the director ervices at the time of al Systems - Essential Electric	K 91	В		2/1/17
	Maintenance and The generator or of and associated equatives within 10 secriterion is not met process shall be procapability for the lift Maintenance and to transfer switches a with NFPA 110. Generator sets are under load 30 minuted and 30 minuted and and intervals, and a months for 4 continuated cold start transfer of all EES competent persons stored energy power accordance with N circuit breakers are program for period components is estated.	resting ther alternate power source uipment is capable of supplying econds. If the 10-second during the monthly test, a rovided to annually confirm this e safety and critical branches. The esting of the generator and re performed in accordance inspected weekly, exercised attes 12 times a year in 20-40 exercised once every 36 arous hours. Scheduled test and automatic or manual loads, and are conducted by the medical power in the surces (Type 3 EES) are in FPA 111. Main and feeder e inspected annually, and a ically exercising the ablished according to irements. Written records of				

Facility ID: 00168

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	, ,	PLE CONSTRUCTION G 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED	
		24E166	B. WING		01/1	0/2017
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 918	readily available. E circuits are marked Minimizing the postemergency powers consideration for no 6.4.4, 6.5.4, 6.6.4 (111, 700.10 (NFPA This STANDARD is Based on observa facility did not main generator in accord 6.4.4, 6.5.4, 6.6.4. effect all 57 resider Findings include: 1. On a facility tour and 1730 on Januar evealed that the faminute generator is minimum five minute and 1730 on Januar evealed that the faminimum five minute generator is minimum five minute that the faminimum five minute that the faminimum five	esting are maintained and EES electrical panels and and readily identifiable. Sibility of damage of the source is a design ew installations. NFPA 99), NFPA 110, NFPA 70) s not met as evidenced by: tion and document review, the stain the emergency back-up dance with the 2012 NFPA 99. These deficient practices could	K 918	Birchwood Care Home tests the generator on a monthly basis. The down period was not logged, this had been corrected immediately. See attachment #2 for Inspection shee has been updated to include cool period. See attachment #3 and #4 Monthly testing including documer of it being at least 30 percent load capacity. Director of Maintenance responsible.	t which down for ntation	
	director of mainten	actices were verified by the ance at the time of inspection. uipment - Cylinder and	K 92	3		2/2/17
	Greater than or eq	Cylinder and Container Storage ual to 3,000 cubic feet are designed, constructed, and				

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	· ′	PLE CONSTRUCTION G 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED
		24E166	B. WING _		01/10/2017
	PROVIDER OR SUPPLIE	R		STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408	
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE COMPLÉTION
K 923	5.1.3.3.3. >300 but <3,000 or Storage locations within an enclose limited- combusti gates outdoors) the gases are not stored separated from combustible of 1/2 hr. fire protect Less than or equal in a single smoke cylinders available care areas with a or equal to 300 constored in an enclohandled with precautionary seach door or gate where the sign in minimum "CAUT STORED WITHING STORED WHEN Integral pressure considered empty are marked to avoin the open are possible to avoin the open are possible stored on observations and the control of th	cubic feet are outdoors in an enclosure or d interior space of non- or ole construction, with door (or nat can be secured. Oxidizing red with flammables, and are ombustibles by 20 feet (5 feet if iclosed in a cabinet of construction having a minimum tion rating. al to 300 cubic feet e compartment, individual e for immediate use in patient in aggregate volume of less than ubic feet are not required to be exautions as specified in 11.6.2. ign readable from 5 feet is on e of a cylinder storage room, cludes the wording as a ION: OXIDIZING GAS(ES) N NO SMOKING." Ind so cylinders are used in order received from the supplier. Are segregated from full facility employs cylinders with gauge, a threshold pressure of is established. Empty cylinders ord confusion. Cylinders stored rotected from weather. 3.3, 11.3.4, 11.6.5 (NFPA 99) is not met as evidenced by: ration and staff interview, that experly store oxygen cylinders in NFPA 99. 11.3.1, 11.3.2, 11.3.3, is deficient practice could affect	K 92	We will be purchasing a Secura polyurethane green gas cylinder which will add additional fire preventies will be purchased and oxygin cabinet within 30 days. Director	cabinet vention. en placed

	EMENT OF DEFICIENCIES PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X2) MULTIPLE CONSTRUCTION A, BUILDING 01 - MAIN BUILDING 01		(X3) DATE COMP	SURVEY LETED		
		24E166	B. WING _		01/1	0/2017
	PROVIDER OR SUPPLIER	₹		STREET ADDRESS, CITY, STATE, ZIP CODE 715 WEST 31ST STREET MINNEAPOLIS, MN 55408		
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETION DATE
K 923	1730 on January that oxygen was be combustible storal storage room.	petween the hours of 0900 and 10, 2017, observation revealed being stored within five feet of ge in the central nursing ctice was verified by the director services at the time of	K 92	Nursing and Director of Maintena be responsible.	nce will	

CMS-671 Page 1 of 5





Confirmation page! Thank you for using the data entry system. If you have comments please send to:

monica.larson@health.state.mn.us

Please print this page and give it to your state survey team. A page for both the CMS-671 and CMS-672 will be required to complete the process.	Print this Page
Would you like to go to the CMS-672 form for data entry?	Go to CMS-672
I'm finished and would like to exit the application.	Exit

Standard Survey Date Format: mm/dd/yy From F1: 01/09/16 To F2: 01/10/16	Extended Survey Date Format: mm/dd/yy From F3: To F4:					
Name of Facility: BIRCHWOOD CARE HOME	Provider Number: 24E166	Fiscal Year ending:				
Address: 715 WEST 31ST STREET, MINNEAPOLIS	, HENNEPIN, MN 55	408				
Telephone Number: F6 612-823-7286	State/County Code: MN / HENNEPIN	State/Region Code: MN / 05				
A. F9 02 - Nursing Facility (NF) - Medicaid Participation B. Is this facility hospital based? F10 No If yes, indicate Hopsital Provider Number: F11						
Ownership: F12 03 - For Profit - Corporation						
Owned or leased by Multi-Facility Organizatio Name of Multi-Facility Organization: F14	n: F13 No					
Dedicated Special Care Units (show number of	beds for all that apply)					
AIDS F15 0 Alzł	neimer's Disease F16 0					
Dialysis F17 0 Disa	bled Child Young Adul	t F18 0				
Head Trama F19 0 Hos	pice F20 0					

CMS-671 Page 2 of 5

Huntington's Disease F21 0 Ventilator/Respiratory Care F22 0 Other Spec Rehab. F23 0 Does the facility currently have an organized resident group? F24 Yes Does the facility currently have an organized group of family Yes members of residents? F25 Does the facility conduct experimental research? F26 No Is the facility part of a continuing care retirement community No (CCRC)? F27 If the facility currently has a staffing waiver, indicate the type(s) of waiver(s) by writing in the date(s) of the last approval. Indicate the number of hours waived for each type of waiver granted. If the facility does not have a waiver, write NA in the blanks. Hours waived per Date: mm/dd/yy Waiver of seven day RN requirement. week: F28 F29 Hours waived per Date: mm/dd/yy Waiver of 24 hr licensed nursing requirement. week: F31 Does the facility currently have an approved nurse aide training and No competency program? F32 The following three questions are to be completed by the survey team. 1) Was this a staggered Survey? No - Not Staggered 2) If staggered, day of the week starting? **Surveyor to Complete** 3) If staggered, starting time? Surveyor to complete AM

	FACILITY STAFFING								
		A	В	С	D				
	Tag	Services Provided 1 2 3	Full-Time Staff (hours)	Part-Time Staff (hours)	Contract (hours)				
Administration	F33		160	80					
Physician Services	F34	No No Yes							
Medical Director	F35		0		2				
Other Physician	F36		0	0	0				
Physician Extender	F37	No No No	0	0	0				

CMS-671 Page 3 of 5

Nursing Services	F38	Yes No No			
RN Director of Nursing	F39		72	0	0
Nurses with Admin Duties	F40		72	53	0
Registered Nurses	F41		40	31	0
Licensed Practical/ Vocational Nurses	F42		80	166	0
Certified Nurse Aides	F43		72	167	0
Nurse Aides in Training	F44		0	0	0
Medication	F45		0	247	0
Pharmacists	F46	Yes No No	0	0	2
Dietary Services	F47	Yes No No			
Dietitian	F48		0	0	16
Food Service Workers	F49		148	271	0
Therapeutic Services	F50				
Occupational Therapist	F51	No No No	0	0	0
Occupational Therapy Assistant	F52		0	0	0
Occupational Therapy Aides	F53		0	0	0
Physical Therapist	F54	No No No	0	0	0
Physical Therapy Assist	F55		0	0	0
Physical Therapy Aides	F56		0	0	0
Speech/Language	F57	No No No	0	0	0
Therapeutic Recreation Spec.	F58	No No No	0	0	0
Qualified Activities Prof.	F59	No No No	0	0	0
Other Activities Staff	F60	Yes No No	233	0	0
Qualified Social Workers	F61	Yes No No	80	0	0

CMS-671 Page 4 of 5

Other Social Services Staff	F62	Yes No No	0	80	0
Dentists	F63	No No No	0	0	0
Podiatrists	F64	No No No	0	0	0
Mental Health Services	F65	Yes No No	0	0	0
Vocational Services	F66	No No No			
Clinical Laboratory Services	F67	Yes No No			
Diagnostic X-ray Services	F68	No No No			
Administration Storage of Blood	F69	No No No			
Housekeeping Services	F70	Yes No No	185	110	0
Other	F71		0	0	0
Name of Person Completing Form: Kathryn Herbert					Date: 01/12/17

• Share This

Spotlight

Minnesota eLicensing

Questions?

Please contact our Health Regulation Division: <u>health.fpc-web@state.mn.us</u> or 651-201-4101.

See also > Health Regulation

- Certificates & Records
- Data & Statistics
- Diseases & Conditions
- Emergency Preparedness
- Environments & Your Health
- Facilities & Professions
- Health Care & Coverage
- Injury, Violence & Safety
- Life Stages & Populations
- Policy, Economics & Legislation

CMS-672 Page 1 of 4





Confirmation page! Thank you for using the data entry system. If you have comments please send to:

monica.larson@health.state.mn.us

Please print this page and give it to your state survey team. A page for both the CMS-671 and CMS-672 will be required to complete the process.	Print this Page
Would you like to go to the CMS-671 form for data entry?	Go to CMS-671
I'm finished and would like to exit the application.	Exit

BIRCHWOOD CARE HOME							
Provider No. 24E166	Medicare F75	Medicaid F76 51	Other F'/'	Total Residents F78 57			

ADL	Independent	Assist of One Two Staff	Dependent
Bathing	F79 55	F80 2	F81 0
Dressing	F82 57	F83 0	F84 0
Transferring	F85 57	F86 0	F87 0
Toilet Use	F88 57	F89 0	F90 0
Eating	F91 57	F92 0	F93 0

A. Bowel/Bladder Status

F94 0 With indwelling or external catheter.

F95 Of total number of residents with catheters, **0** were present on admission.

B. Mobility

F100 0 Bedfast all or most of time..

F101 0 In chair all or most of time.

F102 49 Independently ambulatory.

CMS-672 Page 2 of 4

F96 1 Occasionally or frequently incontinent of bladder.

F97 1 Occasionally or frequently incontinent of bowel.

F98 **0** On individually written bladder training program.

F99 **0** On individually written bowel training program.

F103 8 Ambulation with assistance or assistive device.

F104 **0** Physically restrained.

F105 Of total number of residents with restrained, **0** were admitted with orders for restraints.

F106 0 With contractures.

F107 Of total number of residents with contractures, **0** had contractures on admission.

C. Mental Status

F108 3 With mental retardation.

F109 **28** With documentation signs and symptoms of depression.

F110 54 With documentation psychiatric diagnosis (excluding dementias and depression).

F111 3 Dementia: multi-infarct, senile, Alzheimer's type, or other than Alzheimer's type.

F112 38 With behavioral symptoms.

F113 38 Of the total number of residents with behavioral symptoms, the total number receiving a behavior management prpgram.

F114 35 Receiving health rehabilitative services for MI/MR.

D. Skin Integrity

F115 0 With pressure sores (exclude stage I).

F116 **0** Of the total number of residents with pressure sores excluding stage I, how many residents had pressure sores on admission?

F117 **20** Receiving preventive skin care.

F118 0 With rashes.

E. Special Care

F119 0 Receiving hospice care benefit.

F120 0 Receiving radiation therapy.

F121 1 Receiving chemotherapy.

F127 0 Receiving suction.

F128 13 Receiving injections (exclude vitamin B12 injections)

F129 0 Receiving tube feedings.

CMS-672 Page 3 of 4

F122 0 Receiving dialysis.

F123 0 Receiving intravenous therapy, parenteral nutrition, and/or blood transfusion.

F124 2 Receiving respiratory treatment.

F125 **0** Receiving tracheostomy care.

F126 **0** Receiving ostomy care.

F130 5 Receiving mechanically altered diets including pureed and all chopped food (not only meat).

F131 0 Receiving specialized rehabilitative services (Physical therapy, speech-language therapy, occupational therapy).

F132 **0** Assistive devices while eating.

F. Medication

F133 55 Receiving any psychoactive medication.

F134 55 Receiving antipsychotic medications.

F135 18 Receiving antianxiety medications.

F136 30 Receiving antidepressant medications.

F137 5 Receiving hypnotic medication.

F138 6 Receiving antibiotics.

F139 12 On pain management program.

G. Other

F140 4 With unplanned significant weight loss/gain.

F141 **0** Who do not communicate in the dominant language of the facility (includes those who use sign language).

F142 **0** Who use non-oral communicationdevices.

F143 8 With advance directives.

F144 43 Received influenza immunization.

F145 39 Received pneumococcal vaccine.

I certify that this Information is accurate to the best of my knowledge.						
Name of Person Completing	Title	Date				
Bernice Ngwa	RN	01/13/2017				

To be completed by MDH survey team.
F146 Was ombudsman office notified prior to survey? Yes
F147 Was ombudsman present during any portion of the survey? No
F148 Medication error rate 0%

• Share This

CMS-672 Page 4 of 4

Spotlight

Minnesota eLicensing

Questions?

Please contact our Health Regulation Division: <u>health.fpc-web@state.mn.us</u> or 651-201-4101.

See also > <u>Health Regulation</u>

- Certificates & Records
- Data & Statistics
- Diseases & Conditions
- Emergency Preparedness
- Environments & Your Health
- Facilities & Professions
- Health Care & Coverage
- Injury, Violence & Safety
- Life Stages & Populations
- Policy, Economics & Legislation
- Prevention & Healthy Living
- Search the Site
- Home
- About MDH
- Locations & Directions
- Comments & Questions
- Privacy Statement & Disclaimer
- Equal Opportunity

651-201-5000 Phone 888-345-0823 Toll-free

Information on this website is available in alternative formats upon request.

Ν

SURVEY TEAM COMPOSITION AND WORKLOAD REPORT

Public reporting burden for this collection of information is estimated to average 10 minutes per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Office of Financial Management, HCFA, P.O. Box 26684, Baltimore, MD 21207; or to the Office of Management and Budget, Paperwork Reduction Project(0838-0583), Washington, D.C. 20503.

Provider/Supplier	Number		Provider/Supplier Name								
24E166		BIF	BIRCHWOOD CARE HOME								
Type of Survey (select all that apply): I Extent of Survey (Select all that apply):			A Complaint B Dumping In C Federal Mo D Follow-up	E Initial Certification I Recertification F Inspection of Care J Sanction/Hearing G Validation K State License H Life safety Code L Chow							
A	A Routine/Standard (all providers/suppliers)						ity)				
			SURVEY TEAM A	ND WORKLOAD	DATA						
Please enter the wor	kload informa	tion for eac	h surveyor.	Use the sur	veyor's info	prmation nu	mber.	I			
Surveyor Id Number	First Date Arrived (B)	Last Date Departed (C)	Pre-Survey Preparation Hours (D)	On-Site Hours 12am-8am (E)	On-Site Hours 8am-6pm (F)	On-Site Hours 6pm-12am (G)	Travel (H)	Off-Site Report Preparation Hours (I)			
1. 19692	01-09-2017	01-10-2017	0.00	0.00	15.50	2.00	0.00	0.00			
2. 31223	01-09-2017	01-10-2017	0.00	0.00	16.00	2.00	0.00	9.50			
3. Team Leader 35569	01-09-2017	01-10-2017	1.50	2.00	16.00	0.00	0.00	8.50			
4.											
5.											
6.											
7.											
8.											
9.											
10.											
		1	,					•			
Total Supervisory Rev	view Hours							2.75			
Total Clerical/Data F								3.25			

Was Statement of Deficiencies given to the provider on-site at completion of the survey?

SURVEY TEAM COMPOSITION AND WORKLOAD REPORT

Public reporting burden for this collection of information is estimated to average 10 minutes per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Office of Financial Management, HCFA, P.O. Box 26684, Baltimore, MD 21207; or to the Office of Management and Budget, Paperwork Reduction Project(0838-0583), Washington, D.C. 20503.

aperwork Reduction	Project(0838-	0583), Washi	ngton, D.C. 2	0503.				
Provider/Supplier Number Pro			ovider/Supplie	er Name				
24E166		BIF	RCHWOOD CARE H	HOME				
Type of Survey (select all that apply): H I			A Complaint B Dumping In C Federal Mo D Follow-up	F Inspec G Valida	E Initial Certification I Recertification F Inspection of Care J Sanction/Hearing G Validation K State License H Life safety Code L Chow			
tent of Survey (Se	lect all that	apply):	A Routine/St B Extended S C Partial Ex D Other Surv	urvey (HHA o tended Surve	r long term		ity)	
			SURVEY TEAM A					
lease enter the wor Surveyor Id Number (A)	kload informa First Date Arrived (B)	Last Date Departed (C)	Pre-Survey Preparation Hours (D)	On-Site Hours 12am-8am (E)	veyor's info On-Site Hours 8am-6pm (F)	On-Site Hours 6pm-12am (G)		Off-Site Report Preparation Hours (I)
Team Leader 1. 37009	01-10-2017	01-10-2017	1.00	0.00	9.00	0.00	3.00	4.50
١.								
•								
•								
•								
9.								
LO.								
tal Supervisory Rev	<i>j</i> iew Hours							0.25

Was Statement of Deficiencies given to the provider on-site at completion of the survey?

FIRE SAFETY SURVEY REPORT CRUCIAL DATA EXTRACT (TO BE USED WITH CMS-2786 FORMS)

PROVIDER NUMBER	FACILITY NAME	SU	URVEY DATE			
K1 24E166	BIRCHWOOD CARE HOME	*	K4 01/10/2017			
K6 DATE OF PLAN APPROVAL	K3: MULTIPLE CONSTRUCTION TOTAL NUMBER OF BUILDINGS NUMBER OF THIS BUILDING	1 A B V	BUILDING WING FLOOR APARTMENT UNIT			
12 2786 R 13 2786 R 14 2786 U	ealth Care Form 2012 EXISTING 2012 NEW ASC Form 2012 EXISTING	COMPLETE IF ICF/MR IS SURVEYED UNDER SMALL (16 BEDS OR LI 1 PROMPT 2 SLOW 3 IMPRACTICA LARGE 4 PROMPT	ESS)			
16 2786 V, W 17 2786 V, W	, X 2012 NEW	K8: 5 SLOW 6 IMPRACTICA	AL			
	are marked as not applicable in the X, Y and Z.) K351: 3	K8: 7 PROMPT 8 SLOW 9 IMPRACTICAL ENTER E-SCORE HERE K5: e.g 2.5				
*K9 : FACILITY MEETS LS A1 (COMP. WITH ALL PROVISIONS)	C BASED ON: (Check all that apply) A2 X A3 (ACCEPTABLE POC) (W.		A5 PERFORMANCE BASED DESIGN)			
FACILITY DOES NOT MEE B.	T LSC: K180: A. X FULLY SPRINKLI (All required areas are s		C. NONE (No sprinkler system)			
*MANDATORY						

2012 LIFE SAFETY CODE

Form Approved OMB Exempt

FIRE SAFETY SURVEY REPORT : Medicare - N		E	1. (A) PROVIDER NUM 24E166	BER 1.	(B) MEDICAID I.D. NO.			
OPTIONAL — Chapter	PART I — Life Safet PART II — Health Care Fa PART III — Reco PART IV – C 4 – NFPA 101A - Fire Safety Evalu	acilities Co mmendati rucial Dat	ode, New and Existi ion for Waiver a Extract		es – CMS-2786T			
Identifying information as shown in applicable r	ecords. Enter changes, if any, along	gside each	item, giving date o	f change.				
2. NAME OF FACILITY Birchwood Care Home 2. (A) MULTIPLE CONSTRUCTION (BLDGS) A. BUILDING B. WING 71:			2. (B) ADDRESS OF FACILITY (STREET, CITY, STATE, ZIP CODE) 715 West 31st Street Minneapolis, MN 55408 A. Tully Sprinklered (All required areas are sprinkler by artially Sprinklered) (Not all required areas are sprinklered) (Not all required areas are sprinklered) (C. Jone (No sprinkler system)					
	1/10/2017	DATE OF PL	AN APPROVAL	SURVEY UND 5 2012 EX				
5. SURVEY FOR CERTIFICATION OF 1 HOSPITAL 2. SKILLED/NURSING	FACILITY 4. CF/IID UND	ER HEALTH	CARE 5.	HOSPICE				
IF "2" OR "5" ABOVE IS MARKED, CHECK APPROPRIAT 1 ENTIRE FACILITY 2. DISTINCT PART OF	, ,			_	HOSPITAL, IS HOSPITAL ACCREDITED?			
6. BED COMPOSITION a. TOTAL NO. OF BEDS IN THE FACILITY 60 CERTIFIED FOR MED			d. NUMBER OF SKI CERTIFIED FOR	ILLED BEDS MEDICAID <u>60</u>	e. NUMBER OF NF or ICF/IID BEDS CERTIFIED FOR MEDICAID			
7. A THE FACILITY MEETS THE STANDARD, BASE 1 COMPLIANCE WITH ALL PROVISIONS THE FACILITY DOES NOT MEET THE STAND	2. ACCEPTANCE OF A PLAN OF COR		RECOMMENDED V	WAIVERS 4	FSES 5. PERFORMANCE BASED DESIGN			
SURVEYOR (Signature) **EXECUTION OF THE SURVEYOR ID 37009 **EXECUTION OF THE SURVEYOR ID 37009	TITLE Deputy State Fire Marshal	Sta	ce ite Fire Marshal	Division	DATE 01/20/2017			
FIRE AUTHORITY OFFICIAL (Signature)	TITLE Fire Safety Supervisor	OFFI State	CE Fire Marshal Division		DATE 01-24-2017			
CMS FORMS SHALL BE COMPLETED AND RETAINED	AS PART OF THE SURVEY RECORD.							

FE166026

ID PREFIX		MET	NOT MET	N/A	REMARKS
	PART I – NFPA 101 LSC REQUIREMENTS (Items in italics relate to the FSES)				
	SECTION 1 – GENERAL REQUIREMENTS				
K100	General Requirements – Other				
	List in the REMARKS section any LSC Section 18.1 and 19.1 General Requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567.	•	0	0	
K111	Building Rehabilitation				
	Repair, Renovation, Modification, or Reconstruction				
	Any building undergoing repair, renovation, modification, or reconstruction complies with both of the following:				
	Requirements of Chapter 18 and 19.				
	Requirements of the applicable Sections 43.3, 43.4, 43.5, and 43.6.				
	18.1.1.4.3, 19.1.1.4.3, 43.1.2.1				
	Change of Use or Change of Occupancy				
	Any building undergoing change of use or change of occupancy classification complies with the requirements of Section 43.7, unless permitted by 18.1.1.4.2 or 19.1.1.4.2.				
	18.1.1.4.2 (4.6.7 and 4.6.11), 19.1.1.4.2 (4.6.7 and 4.6.11), 43.1.2.2 (43.7)				
	Additions				
	Any building undergoing an addition shall comply with the requirements of Section 43.8. If the building has a common wall with a nonconforming building, the common wall is a fire barrier having at least a two hour fire resistance rating constructed of materials as required for the addition. Communicating openings occur only in corridors and are protected by approved self-closing fire doors with at least a 1-1/2 hour fire resistance				
	rating. Additions comply with the requirements of Section 43.8.				
	18.1.1.4.1 (4.6.7 and 4.6.11), 18.1.1.4.1.1 (8.3), 18.1.1.4.1.2, 18.1.1.4.1.3, 19.1.1.4.1 (4.6.7 and 4.6.11), 19.1.1.4.1.1 (8.3), 19.1.1.4.1.2, 19.1.1.4.1.3, 43.1.2.3(43.8)				

ID PREFIX		MET	NOT MET	N/A	REMARKS
K112	Sprinkler Requirements for Major Rehabilitation If a nonsprinklered smoke compartment has undergone major rehabilitation the automatic sprinkler requirements of 18.3.5 have been applied to the smoke compartment. In cases where the building is not protected throughout by a sprinkler system, the requirements of 18.4.3.2, 18.4.3.3, and 18.4.3.8 are also met. Note: Major rehabilitation involves the modification of more than 50 percent, or more than 4500 ft² of the area of the smoke compartment. 18.1.1.4.3.3, 19.1.1.4.3.3	0	0	•	
K131	 Multiple Occupancies – Sections of Health Care Facilities Sections of health care facilities classified as other occupancies meet all of the following: They are not intended to serve four or more inpatients. They are separated from areas of health care occupancies by construction having a minimum two hour fire resistance rating in accordance with Chapter 8. The entire building is protected throughout by an approved, supervised automatic sprinkler system in accordance with Section 9.7. Hospital outpatient surgical departments are required to be classified as an Ambulatory Health Care Occupancy regardless of the number of patients served. 18.1.3.3, 19.1.3.3, 42 CFR 482.41, 42 CFR 485.623 	0	0	•	
K132	Multiple Occupancies – Contiguous Non-Health Care Occupancies Non-health care occupancies that are located immediately next to a Health Care Occupancy, but are primarily intended to provide outpatient services are permitted to be classified as Business or Ambulatory Health Care Occupancies, provided the facilities are separated by construction having not less than two hour fire resistance-rated construction, and are not intended to provide services simultaneously for four or more inpatients. Outpatient surgical departments must be classified as Ambulatory Health Care Occupancy regardless of the number of patients served. 18.1.3.4.1, 19.1.3.4.1	0	0	•	

ID PREFIX				MET	NOT MET	N/A	REMARKS
K133	 Multiple Occupancies – Construction Type Where separated occupancies are in accordance with 18/19.1.3.2 or 18/19.1.3.4, the most stringent construction type is provided throughout the building, unless a two hour separation is provided in accordance with 8.2.1.3, in which case the construction type is determined as follows: The construction type and supporting construction of the health care occupancy is based on the story in which it is located in the building in accordance with 18/19.1.6 and Tables 18/19.1.6.1. The construction type of the areas of the building enclosing the other occupancies shall be based on the applicable occupancy chapters. 18.1.3.5, 19.1.3.5, 8.2.1.3 			0	0	•	
K161	2012 EXI Building of	construction type and stories permitted by 19.1.6.2 throu	meets Table 19.1.6.1, unless				Birchwood Care Home is a 2-story building with a full basement. The building was constructed at 3 different times. The original 2 story building was constructed in 1966 and was determined to be of Type II(222) construction. In 1971, a 20 bed addition was constructed and was determined to be of Type II(222) construction. In 2000, an addition was constructed to add an elevator as well as dry
	Supervise Give a bri including fire barrie	ed automatic system in acco ef description, in REMARKS, o basements, floors on which p	Not allowed non-sprinklered Maximum 2 stories sprinklered Maximum 2 stories sprinklered Not allowed non-sprinklered Maximum 1 story sprinklered ed throughout by an approved, rdance with section 9.7. (See 19.3.5) of the construction, the number of stories, atients are located, location of smoke or complete sketch or attach small floor	•	0	0	and cold storage to the East that was determined to be of Type II(222) construction. Because the original building and the 2 additions are of the same type of construction, the facility was surveyed as one building. This building is fully fire sprinklered. The facility has a fire alarm system with smoke detection in the corridors and spaces open to the corridors that is monitored for automatic fire department notification.

ID PREFIX		MET	NOT MET	N/A	REMARKS
K161	Building construction type and stories meets Table 18.1.6.1, unless otherwise permitted by 18.1.6.2 through 18.1.6.7 18.1.6.4, 18.1.6.5 Construction Type 1	0	MEI	0	
K162	 Roofing Systems Involving Combustibles 2012 EXISTING Buildings of Type I (442), Type I (332), Type II (222), or Type II (111) having roof systems employing combustible roofing supports, decking or roofing meet the following: 1. roof covering meets Class C requirements. 2. roof is separated from occupied building portions with 2 hour fire resistive noncombustible floor assembly using not less than 2½ inches concrete or gypsum fill. 3. attic or other space is either unoccupied or protected throughout by an approved automatic sprinkler system. 19.1.6.2*, ASTM E108, ANSI/UL 790 	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K162	 2012 NEW Buildings of Type I (442), Type I (332), Type II (222), Type II (111) having roof systems employing combustible roofing supports, decking or roofing meet the following: 1. roof covering meets Class A requirements. 2. roof is separated from occupied building portions with 2 hour fire resistive noncombustible floor assembly using not less than 2½ inches concrete or gypsum fill. 3. the structural elements supporting the rated floor assembly meet the required fire resistance rating of the building. 18.1.6.2, ASTM E108, ANSI/UL 790 	0	0	0	
K163	Interior Nonbearing Wall Construction Interior nonbearing walls in Type I or II construction are constructed of noncombustible or limited-combustible materials. Interior nonbearing walls required to have a minimum 2 hour fire resistance rating are fire-retardant-treated wood enclosed within noncombustible or limited-combustible materials, provided they are not used as shaft enclosures. 18.1.6.4, 18.1.6.5, 19.1.6.4, 19.1.6.5	0	•	0	Observation revealed that the two hour fire rated roof had an access panel constructed of wood and unprotected metal.
K200	SECTION 2 – MEANS OF EGRESS REQUIREMENTS Means of Egress Requirements – Other List in the REMARKS section any LSC Section 18.2 and 19.2 Means of Egress requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. 18.2, 19.2	•	0	0	
K211	Means of Egress – General Aisles, passageways, corridors, exit discharges, exit locations, and accesses are in accordance with Chapter 7, and the means of egress is continuously maintained free of all obstructions to full use in case of emergency, unless modified by 18/19.2.2 through 18/19.2.11. 18.2.1, 19.2.1, 7.1.10.1	0	•		Observation revealed that the boiler room egress stairs were obstructed by storage.

ID PREFIX		MET	NOT MET	N/A	REMARKS
K221	Patient Sleeping Room Doors Locks on patient sleeping room doors are not permitted unless the keylocking device that restricts access from the corridor does not restrict egress from the patient room, or the locking arrangement is permitted for patient clinical, security or safety needs in accordance with 18.2.2.2.5 or 19.2.2.2.5. 18.2.2.2, 19.2.2.2, TIA 12-4	•	0	0	
K222	Egress Doors Doors in a required means of egress shall not be equipped with a latch or a lock that requires the use of a tool or key from the egress side unless using one of the following special locking arrangements: CLINICAL NEEDS OR SECURITY THREAT LOCKING Where special locking arrangements for the clinical security needs of the patient are used, only one locking device shall be permitted on each door and provisions shall be made for the rapid removal of occupants by: remote control of locks; keying of all locks or keys carried by staff at all times; or other such reliable means available to the staff at all times. 18.2.2.2.5.1, 18.2.2.2.6, 19.2.2.2.5.1, 19.2.2.2.6 SPECIAL NEEDS LOCKING ARRANGEMENTS Where special locking arrangements for the safety needs of the patient are used, all of the Clinical or Security Locking requirements are being met. In addition, the locks must be electrical locks that fail safely so as to release upon loss of power to the device; the building is protected by a supervised automatic sprinkler system and the locked space is protected by a complete smoke detection system (or is constantly monitored at an attended location within the locked space); and both the sprinkler and detection systems are arranged to unlock the doors upon activation. 18.2.2.2.5.2, 19.2.2.2.5.2, TIA 12-4	0	0	•	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K222	□ DELAYED-EGRESS LOCKING ARRANGEMENTS Approved, listed delayed-egress locking systems installed in accordance with 7.2.1.6.1 shall be permitted on door assemblies serving low and ordinary hazard contents in buildings protected throughout by an approved, supervised automatic fire detection system or an approved, supervised automatic sprinkler system. 18.2.2.2.4, 19.2.2.2.4 □ ACCESS-CONTROLLED EGRESS LOCKING ARRANGEMENTS Access-Controlled Egress Door assemblies installed in accordance with 7.2.1.6.2 shall be permitted. 18.2.2.2.4, 19.2.2.2.4 □ ELEVATOR LOBBY EXIT ACCESS LOCKING ARRANGEMENTS Elevator lobby exit access door locking in accordance with 7.2.1.6.3 shall be permitted on door assemblies in buildings protected throughout by an approved, supervised automatic fire detection system and an approved, supervised automatic sprinkler system. 18.2.2.2.4, 19.2.2.2.4	0	0	lacktriangle	
K223	 Doors with Self-Closing Devices Doors in an exit passageway, stairway enclosure, or horizontal exit, smoke barrier, or hazardous area enclosure are self-closing and kept in the closed position, unless held open by a release device complying with 7.2.1.8.2 that automatically closes all such doors throughout the smoke compartment or entire facility upon activation of: Required manual fire alarm system; and Local smoke detectors designed to detect smoke passing through the opening or a required smoke detection system; and Automatic sprinkler system, if installed; and Loss of power. 18.2.2.2.7, 18.2.2.2.8, 19.2.2.2.7, 19.2.2.2.8 	0	•	0	Observation revealed that the North exit stairway door in the second floor corridor, did not self-close and positively latch.

ID PREFIX		MET	NOT MET	N/A	REMARKS
K224	Horizontal-Sliding Doors Horizontal-sliding doors permitted by 7.2.1.14 that are not automatic-closing are limited to a single leaf and shall have a latch or other mechanism to ensure the door will not rebound.				
	Horizontal-sliding doors serving an occupant load fewer than 10 shall be permitted, providing all of the following criteria are met: • Area served by the door has no hazards.				
	 Door is operable from either side without special knowledge or effort. Force required to operate the door in the direction of travel is ≤ 30 lbf to set the door in motion and ≤ 15 lbf to close or open to the required width. 	0	0	•	
	Assembly is appropriately fire rated, and where rated, is self-or automatic-closing by smoke detection per 7.2.1.8, and installed per NFPA 80.				
	 Where required to latch, the door has a latch or other mechanism to ensure the door will not rebound. 18.2.2.2.10, 19.2.2.2.10 				
K225	Stairways and Smokeproof Enclosures Stairways and Smokeproof enclosures used as exits are in accordance with 7.2.	0	•	0	Observation revealed that there were combustible decorations in the exit stairways. Observation revealed that the first floor, North exit stairway fire-rated door was cracked.
K226	18.2.2.3, 18.2.2.4, 19.2.2.3, 19.2.2.4, 7.2 Horizontal Exits				
N220	Horizontal exits, if used, are in accordance with 7.2.4 and the provisions of 18.2.2.5.1 through 18.2.2.5.7, or 19.2.2.5.1 through 19.2.2.5.4.	0	0	•	
	18.2.2.5, 19.2.2.5				
K227	Ramps and Other Exits Ramps, exit passageways, fire escape ladders, alternating tread devices, and areas of refuge are in accordance with the provisions 7.2.5 through 7.2.12. 18.2.2.6 to 18.2.2.10 or 19.2.2.6 to 19.2.2.10	•	0	0	
K231	Means of Egress Capacity The capacity of required means of egress is in accordance with 7.3. 18.2.3.1, 19.2.3.1	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K232	Aisle, Corridor or Ramp Width 2012 EXISTING The width of aisles or corridors (clear or unobstructed) serving as exit access shall be at least 4 feet and maintained to provide the convenient removal of nonambulatory patients on stretchers, except as modified by	•	0	0	
	19.2.3.4, exceptions 1-5. 19.2.3.4, 19.2.3.5				
	2012 NEW The width of aisles or corridors (clear and unobstructed) serving as exit access in hospitals and nursing homes shall be at least 8 feet. In limited care facility and psychiatric hospitals, width of aisles or corridors shall be at least 6 feet, except as modified by the 18.2.3.4 or 18.2.3.5 exceptions. 18.2.3.4, 18.2.3.5	0	0	0	
K233	Clear Width of Exit and Exit Access Doors 2012 EXISTING Exit access doors and exit doors are of the swinging type and are at least 32 inches in clear width. Exceptions are provided for existing 34-inch doors and for existing 28-inch doors where the fire plan does not require evacuation by bed, gurney, or wheelchair. 19.2.3.6, 19.2.3.7	•	0	0	
	2012 NEW Exit access doors and exit doors are of the swinging type and are at least 41.5 inches in clear width. In psychiatric hospitals or limited care facilities, doors are at least 32 inches wide. Doors not subject to patient use, in exit stairway enclosures, or serving newborn nurseries shall be no less than 32 inches in clear width. If using a pair of doors, the doors shall be provided with a rabbet, bevel, or astragal at the meeting edge, at least one of the doors shall provide 32 inches in clear width, and the inactive leaf of the pair shall be secured with automatic flush bolts. 18.2.3.6, 18.2.3.7	0	0	0	
K241	Number of Exits – Story and Compartment Not less than two exits, remote from each other, and accessible from every part of every story are provided for each story. Each smoke compartment shall likewise be provided with two distinct egress paths to exits that do not require the entry into the same adjacent smoke compartment. 18.2.4.1-18.2.4.4, 19.2.4.1-19.2.4.4	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K251	Dead-End Corridors and Common Path of Travel				
	2012 EXISTING				
	Dead-end corridors shall not exceed 30 feet. Existing dead-end corridors greater than 30 feet shall be permitted to be continued to be used if it is impractical and unfeasible to alter them.	•	0	0	
	19.2.5.2				
K251	2012 NEW	_	_		
	Dead-end corridors shall not exceed 30 feet. Common path of travel shall not exceed 100 feet.	0	0	\bigcirc	
	18.2.5.2, 18.2.5.3				
K252	Number of Exits – Corridors				
	Every corridor shall provide access to not less than two approved exits in accordance with Sections 7.4 and 7.5 without passing through any intervening rooms or spaces other than corridors or lobbies.	•	0	0	
	18.2.5.4, 19.2.5.4				
K253	Number of Exits – Patient Sleeping and Non-Sleeping Rooms				
	Patient sleeping rooms of more than 1,000 square feet or nonsleeping rooms of more than 2,500 square feet have at least two exit access doors remotely located from each other.	•	0	0	
	18.2.5.5.1, 18.2.5.5.2, 19.2.5.5.1, 19.2.5.5.2				
K254	Corridor Access				
	All habitable rooms not within suites have a door leading directly outside to grade or have a door leading to an exit access corridor. Patient sleeping rooms with less than eight patient beds may have one room intervening to reach an exit access corridor provided the intervening room is equipped with an approved automatic smoke detection system.	•	0	0	
	18.2.5.6.1 through 18.2.5.6.4, 19.2.5.6.1 through 19.2.5.6.4				
K255	Suite Separation, Hazardous Content, and Subdivision				
	All suites are separated from the remainder of the building (including from other suites) by construction meeting the separation provisions for corridor construction (18.3.6.2-18.3.6.5 or 19.3.6.2-19.3.6.5). Existing approved barriers shall be allowed to continue to be used provided they limit the transfer of smoke. Intervening rooms have no hazardous areas and hazardous areas within suites comply with 18/19.2.5.7.1.3. Subdivision of suites shall be by noncombustible or limited-combustible construction. 18.2.5.7.1.2 through 18.2.5.7.1.4, 19.2.5.7.1.2, 19.2.5.7.1.3, 19.2.5.7.1.4	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K256	Sleeping Suites Occupants shall have exit access to a corridor or direct access to a horizontal exit. Where ≥ 2 exits are required, one exit access door may be to a stairway, passageway or to the exterior. Suites shall be provided with constant staff supervision. Staff shall have direct visual supervision of patient sleeping rooms, from a constantly attended location or the room shall be provided with an automatic smoke detection system. Suites more than 1,000 ft² shall have 2 or more remote exits. One means of egress from the suite shall be to a corridor and one may be into an adjacent suite separated in accordance with corridor requirements. Suites shall not exceed the following size limitations: • 5,000 square feet if the suite is not fully smoke detected or fully sprinklered. • 7,500 square feet if the suite is either fully smoke detected or fully sprinklered. • 10,000 square feet if the suite is both fully smoke detected and fully sprinklered and the sleeping rooms have direct supervision from a constantly attended location. Travel distance between any point in a suite to exit access shall not exceed 100 feet and distance to an exit shall not exceed 150 feet (200 feet if building is fully sprinklered). 18.2.5.7.2, 19.2.5.7.2	0	0	•	
K257	Non-Sleeping Suites Occupants shall have exit access to a corridor or direct access to a horizontal exit. Where ≥ 2 exits are required, one exit access door may be to a stairway, passageway or to the exterior. Suites more than 2,500 ft² shall have 2 or more remote exits. One means of egress from the suite shall be to a corridor and one may be into an adjacent suite separated in accordance with corridor requirements. Suites shall not exceed 10,000 ft². Travel distance between any point in a suite to exit access shall not exceed 100 feet and distance to an exit shall not exceed 150 feet (200 feet if building is fully sprinklered). 18.2.5.7.3, 19.2.5.7.3	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K261	Travel Distance to Exits				
	Travel distance (excluding suites) to exits are measured in accordance with 7.6.				
	 From any point in the room or suite to exit less than or equal to 150 feet (less than or equal to 200 feet if the building is fully sprinklered). 	•	0	0	
	 Point in a room to room door less than or equal to 50 feet. 				
	18.2.6, 19.2.6				
K271	Discharge from Exits				
	Exit discharge is arranged in accordance with 7.7, provides a level walking surface meeting the provisions of 7.1.7 with respect to changes in elevation and shall be maintained free of obstructions. Additionally, the exit discharge shall be a hard packed all-weather travel surface in accordance with CMS Survey and Certification Letter 05-38.	•	0	0	
	18.2.7, 19.2.7, S&C 05-38				
K281	Illumination of Means of Egress				
	Illumination of means of egress, including exit discharge, is arranged in accordance with 7.8 and shall be either continuously in operation or capable of automatic operation without manual intervention.	•	0	0	
	18.2.8, 19.2.8				
K291	Emergency Lighting				
	Emergency lighting of at least 1-1/2 hour duration is provided automatically in accordance with 7.9.	•	0	\bigcirc	
	18.2.9.1, 19.2.9.1				
K292	Life Support Means of Egress				
	2012 NEW (INDICATE N/A FOR EXISTING)				
	Buildings equipped with or requiring the use of life support systems (electro- mechanical or inhalation anesthetics) have illumination of means of egress, emergency lighting equipment, exit, and directional signs supplied by the life safety branch of the electrical system described in NFPA 99.	0	0	•	
	(Indicate N/A if life support equipment is for emergency purposes only.) 18.2.9.2, 18.2.10.5				

ID PREFIX		MET	NOT MET	N/A	REMARKS
K293	Exit Signage				
	2012 EXISTING				
	Exit and directional signs are displayed in accordance with 7.10 with continuous illumination also served by the emergency lighting system. 19.2.10.1 (Indicate N/A in one-story existing occupancies with less than 30 occupants	•	0	0	
	where the line of exit travel is obvious.)				
	2012 NEW				
	Exit and directional signs are displayed in accordance with 7.10 with continuous illumination also served by the emergency lighting system. 18.2.10.1	0	0	0	
	SECTION 3 – PROTECTION				
K300	Protection – Other				
	List in the REMARKS section any LSC Section 18.3 and 19.3 Protection requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567.	•	0	0	
K311	Vertical Openings – Enclosure 2012 EXISTING				
	Stairways, elevator shafts, light and ventilation shafts, chutes, and other vertical openings between floors are enclosed with construction having a fire resistance rating of at least 1-hour. An atrium may be used in accordance with 8.6.	•	0	0	
	19.3.1.1 through 19.3.1.6				
	If all vertical openings are properly enclosed with construction providing at least a 2 hour fire resistance rating, also check this box. □				
	2012 NEW				
	Stairways, elevator shafts, light and ventilation shafts, chutes, and other vertical openings between floors are enclosed with construction having a fire resistance rating of at least 2 hours connecting four or more stories. (1-hour for single story building and buildings up to three stories in height.) An atrium may be used in accordance with 8.6.7. 18.3.1 through 18.3.1.5	0	0	0	

ID PREFIX					MET	NOT MET	N/A	REMARKS
K321	Hazardous Areas – Enclosure 2012 EXISTING Hazardous areas are protected by resistance rating (with ¾ hour fire restinguishing system in accordance automatic fire extinguishing system separated from other spaces by snaccordance with 8.4. Doors shall be permitted to have nonrated or field exceed 48 inches from the bottom Describe the floor and zone location in REMARKS. 19.3.2.1	rated doors) or an a e with 8.7.1. When n option is used, the noke resisting partit e self-closing or au -applied protective of the door.	automatic fire the approve e areas shal tions and do tomatic-clos plates that o	e d I be ors in sing and do not		WILT		Observation revealed that the laundry room door was held open with a door wedge. Observation revealed that the medical records room is over 100 square feet and contains combustible storage but does not have and automatic door closer.
	Area	Automatic Sprinkler	Separation	N/A				
	a. Boiler and Fuel-Fired Heater Rooms	✓	'					
	b. Laundries (larger than 100 sq. ft.)	✓	~					
	c. Repair, Maintenance, and Paint Shops				\cup	\odot	\cup	
	d. Soiled Linen Rooms (exceeding 64 gal.)	✓	✓					
	e. Trash Collection Rooms (exceeding 64 gal.)							
	f. Combustible Storage Rooms/Spaces (over 50 sq. ft.)	✓	<u></u>					
	g. Laboratories (if classified as Severe Hazard - see K322)							

ID PREFIX	NOT MET	N/A	REMARKS
REFIX 2012 NEW Hazardous areas are protected in accordance with 18.3.2.1. The areas shall be enclosed with a 1-hour fire-rated barrier, with a ½ hour fire-rated door without windows (in accordance with 8.7.1.1). Doors shall be self-closing or automatic-closing in accordance with 7.2.1.8. Hazardous areas are protected by a sprinkler system in accordance with 9.7, 18.3.2.1, and 8.4. Describe the floor and zone locations of hazardous areas that are deficient in REMARKS.	MET	N/A	REMARKS

ID PREFIX		MET	NOT MET	N/A	REMARKS
K322	Laboratories Laboratories employing quantities of flammable, combustible, or hazardous materials that are considered a severe hazard are protected by 1-hour fire resistance-rated separation, automatic sprinkler system, and are in		IVILI		
	accordance with 8.7 and with NFPA 99. Laboratories not considered a severe hazard are protected as hazardous areas (see K321).				
	Laboratories using chemicals are in accordance with NFPA 45.				
	Gas appliances are of appropriate design and installed in accordance with NFPA 54. Shutoff valves are marked to identify material they control. Devices requiring medical grade oxygen from the piped distribution system meet the requirements under 11.4.2.2 (NFPA 99).				
	18.3.2.2, 19.3.2.2, 8.7, 8.7.4.1 (LSC)				
	9.3.1.2, 11.4.3.2, 15.4 (NFPA 99)				
			\bigcirc		
				0	

ID MET NOT N/A	REMARKS
	REMARKS

ID PREFIX		MET	NOT MET	N/A	REMARKS
K324	 Cooking Facilities Cooking equipment is protected in accordance with NFPA 96, Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations, unless: residential cooking equipment (i.e., small appliances such as microwaves, hot plates, toasters) are used for food warming or limited cooking in accordance with 18.3.2.5.2, 19.3.2.5.2. cooking facilities open to the corridor in smoke compartments with 30 or fewer patients comply with the conditions under 18.3.2.5.3, 19.3.2.5.3, or cooking facilities in smoke compartments with 30 or fewer patients comply with conditions under 18.3.2.5.4, 19.3.2.5.4. Cooking facilities protected according to NFPA 96 per 9.2.3 are not required to be enclosed as hazardous areas, but shall not be open to the corridor. 18.3.2.5.1 through 18.3.2.5.4, 19.3.2.5.1 through 19.3.2.5.5, 9.2.3, TIA 12-2 	•	0	0	
K325	 Alcohol Based Hand Rub Dispenser (ABHR) ABHRs are protected in accordance with 8.7.3.1, unless all conditions are met: Corridor is at least 6 feet wide. Maximum individual dispenser capacity is 0.32 gallons (0.53 gallons in suites) of fluid and 18 ounces of Level 1 aerosols. Dispensers shall have a minimum of four foot horizontal spacing. Not more than an aggregate of 10 gallons of fluid or 1135 ounces of aerosol are used in a single smoke compartment outside a storage cabinet, excluding one individual dispenser per room. Storage in a single smoke compartment greater than 5 gallons complies with NFPA 30. Dispensers are not installed within 1 inch of an ignition source. Dispensers over carpeted floors are in sprinklered smoke compartments. ABHR does not exceed 95 percent alcohol. Operation of the dispenser shall comply with Section 18.3.2.6(11) or 19.3.2.6(11). ABHR is protected against inappropriate access. 18.3.2.6, 19.3.2.6, 42 CFR Parts 403, 418, 460, 482, 483, and 485 	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K331	Interior Wall and Ceiling Finish 2012 EXISTING Interior wall and ceiling finishes, including exposed interior surfaces of buildings such as fixed or movable walls, partitions, columns, and have a flame spread rating of Class A or Class B. The reduction in class of interior finish for a sprinkler system as prescribed in 10.2.8.1 is permitted. 10.2, 19.3.3.1, 19.3.3.2 Indicate flame spread rating(s).	•	0	0	
	Interior wall and ceiling finishes, including exposed interior surfaces of buildings such as fixed or movable walls, partitions and columns have a flame spread rating of Class A. The reduction in class of interior finish for a sprinkler system as prescribed in 10.2.8.1 is permitted. Individual rooms not exceeding four persons may have a Class A or B finish. Lower half of corridor walls, not exceeding 4 feet in height, may have a Class A or B flame spread rating. 10.2, 18.3.3.1, 18.3.3.2 Indicate flame spread rating(s)	0	0	0	
K332	Interior Floor Finish 2012 NEW (Indicate N/A for 2012 EXISTING) Interior finishes shall comply with 10.2. Floor finishes in exit enclosures and exit access corridors and spaces not separated by walls that resist the passage of smoke shall be Class I or II. 18.3.3.3.1, 18.3.3.3.2, 18.3.3.3.3, 10.2, 10.2.7.1, 10.2.7.2	0	0	•	
K341	Fire Alarm System – Installation A fire alarm system is installed with systems and components approved for the purpose in accordance with NFPA 70, National Electric Code, and NFPA 72, National Fire Alarm Code to provide effective warning of fire in any part of the building. In areas not continuously occupied, detection is installed at each fire alarm control unit. In new occupancy, detection is also installed at notification appliance circuit power extenders, and supervising station transmitting equipment. Fire alarm system wiring or other transmission paths are monitored for integrity. 18.3.4.1, 19.3.4.1, 9.6, 9.6.1.8	0	•	0	Observation revealed that there was a manual switch installed in the main fire alarm panel that can disable the automatic fire shutter door in the kitchen.

ID PREFIX		MET	NOT MET	N/A	REMARKS
K342	Fire Alarm System – Initiation Initiation of the fire alarm system is by manual means and by any required				
	sprinkler system alarm, detection device, or detection system. Manual alarm boxes are provided in the path of egress near each required exit. Manual alarm boxes in patient sleeping areas shall not be required at exits if manual alarm boxes are located at all nurse's stations or other continuously attended staff location, provided alarm boxes are visible, continuously accessible, and 200' travel distance is not exceeded.	•	0	0	
	18.3.4.2.1, 18.3.4.2.2, 19.3.4.2.1, 19.3.4.2.2, 9.6.2.5				
K343	Fire Alarm – Notification				
	2012 EXISTING				
	Positive alarm sequence in accordance with 9.6.3.4 are permitted in buildings protected throughout by a sprinkler system. Occupant notification is provided automatically in accordance with 9.6.3 by audible and visual signals.	•	0	0	
	In critical care areas, visual alarms are sufficient. The fire alarm system transmits the alarm automatically to notify emergency forces in the event of a fire.				
	19.3.4.3, 19.3.4.3.1, 19.3.4.3.2, 9.6.4, 9.7.1.1(1)				
	2012 NEW				
	Positive alarm sequence in accordance with 9.6.3.4 are permitted. Occupant notification is provided automatically in accordance with 9.6.3 by audible and visual signals.				
	In critical care areas, visual alarms are sufficient. The fire alarm system transmits the alarm automatically to notify emergency forces in the event of a fire.	0	0	0	
	Annunciation and annunciation zoning for fire alarm and sprinklers shall be provided by audible and visual indicators and zones shall not be larger than 22,500 square feet per zone.				
	18.3.4.3 through 18.3.4.3.3, 9.6.4				
K344	Fire Alarm – Control Functions				
	The fire alarm automatically activates required control functions and is				
	provided with an alternative power supply in accordance with NFPA 72.				
	18.3.4.4, 19.3.4.4, 9.6.1, 9.6.5, NFPA 72				

ID PREFIX		MET	NOT MET	N/A	REMARKS
K345	Fire Alarm System – Testing and Maintenance A fire alarm system is tested and maintained in accordance with an approved program complying with the requirements of NFPA 70, National Electric Code, and NFPA 72, National Fire Alarm and Signaling Code. Records of system acceptance, maintenance and testing are readily available. 9.7.5, 9.7.7, 9.7.8, and NFPA 25	•		0	
K346	Fire Alarm – Out of Service Where required fire alarm system is out of services for more than 4 hours in a 24 hour period, the authority having jurisdiction shall be notified, and the building shall be evacuated or an approved fire watch shall be provided for all parties left unprotected by the shutdown until the fire alarm system has been returned to service. 9.6.1.6	0	•	0	Observation revealed that the facility could not provide a fire watch tour log sheet in the event of a fire alarm system outage.
K347	Smoke Detection 2012 EXISTING Smoke detection systems are provided in spaces open to corridors as required by 19.3.6.1. 19.3.4.5.2	•	0	0	
	2012 NEW Smoke detection systems are provided in spaces open to corridors as required by 18.3.6.1 In nursing homes, an automatic smoke detection system is installed in the corridors of all smoke compartments containing resident sleeping rooms, unless the resident sleeping rooms have: • smoke detection, or • automatic door closing devices with integral smoke detectors on the room side that provide occupant notification. Such detectors are electrically interconnected to the fire alarm system. 18.3.4.5.2, 18.3.4.5.3	0	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K351	Sprinkler System – Installation 2012 EXISTING Nursing homes, and hospitals where required by construction type, are protected throughout by an approved automatic sprinkler system in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems. In Type I and II construction, alternative protection measures are permitted to be substituted for sprinkler protection in specific areas where state or local regulations prohibit sprinklers. In hospitals, sprinklers are not required in clothes closets of patient sleeping rooms where the area of the closet does not exceed 6 ft² and sprinkler coverage covers the closet footprint as required by NFPA 13, Standard for Installation of Sprinkler Systems. 19.3.5.1, 19.3.5.2, 19.3.5.3, 19.3.5.4, 19.3.5.5, 19.4.2, 19.3.5.10, 9.7, 9.7.1.1(1)	•	0	0	
	Buildings are to be protected throughout by an approved automatic sprinkler system in accordance with NFPA 13, <i>Standard for the Installation of Sprinkler Systems</i> . In Type I and II construction, alternative protection measures are permitted to be substituted for sprinkler protection in specific areas where State and local regulations prohibit sprinklers. Listed quick-response or listed residential sprinklers are used throughout smoke compartments with patient sleeping rooms. In hospitals, sprinklers are not required in clothes closets of patient sleeping rooms where the area of the closet does not exceed 6 ft² and sprinkler coverage covers the closet footprint as required by NFPA 13, <i>Standard for Installation of Sprinkler Systems</i> . 18.3.5.1, 18.3.5.4, 18.3.5.5, 18.3.5.6, 9.7, 9.7.1.1(1), 18.3.5.10	0	0	0	
K352	Sprinkler System – Supervisory Signals Automatic sprinkler system supervisory attachments are installed and monitored for integrity in accordance with NFPA 72, National Fire Alarm and Signaling Code, and provide a signal that sounds and is displayed at a continuously attended location or approved remote facility when sprinkler operation is impaired. 9.7.2.1, NFPA 72	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K353	Sprinkler System – Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available. a) Date sprinkler system last checked. 02/12/2016 b) Who provided system test. Viking c) Water system supply source. City Water Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25	0	•	0	 Observation revealed that the facility could not provide evidence for a five year internal obstruction investigation of the automatic sprinkler system. Observation revealed that the sprinkler head in the dish washing room had an excessive amount of debris covering the frangible bulb. Observation revealed that the storage in the walk in freezer and kitchen pantry are piled in a manner that will block the pattern of the sprinkler head. Observation revealed that the spare automatic sprinkler heads were stored outside of the sprinkler cabinet.
K354	Sprinkler System – Out of Service Where the sprinkler system is impaired, the extent and duration of the impairment has been determined, areas or buildings involved are inspected and risks are determined, recommendations are submitted to management or designated representative, and the fire department and other authorities having jurisdiction have been notified. Where the sprinkler system is out of service for more than 10 hours in a 24 hour period, the building or portion of the building affected are evacuated or an approved fire watch is provided until the sprinkler system has been returned to service. 18.3.5.1, 19.3.5.1, 9.7.5, 15.5.2 (NFPA 25)	0	•	0	Observation revealed that the facility could not provide a fire watch tour log sheet in the event of an automatic sprinkler system outage.
K355	Portable Fire Extinguishers Portable fire extinguishers are selected, installed, inspected, and maintained in accordance with NFPA 10, Standard for Portable Fire Extinguishers. 18.3.5.12, 19.3.5.12, NFPA 10	•	0	0	
K361	Corridors – Areas Open to Corridor Spaces (other than patient sleeping rooms, treatment rooms and hazardous areas), waiting areas, nurse's stations, gift shops, and cooking facilities, open to the corridor are in accordance with the criteria under 18.3.6.1 and 19.3.6.1. 18.3.6.1, 19.3.6.1	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K362	Corridors – Construction of Walls 2012 EXISTING Corridors are separated from use areas by walls constructed with at least ½ hour fire resistance rating. In fully sprinklered smoke compartments, partitions are only required to resist the transfer of smoke. In nonsprinklered buildings, walls extend to the underside of the floor or roof deck above the ceiling. Corridor walls may terminate at the underside of ceilings where specifically permitted by Code. Fixed fire window assemblies in corridor walls are in accordance with Section 8.3, but in sprinklered compartments there are no restrictions in area or fire resistance of glass or frames. If the walls have a fire resistance rating, give the rating if the walls terminate at the underside of the ceiling, give brief description in REMARKS, describing the ceiling throughout the floor area. 19.3.6.2, 19.3.6.2.7	•	0	0	
	2012 NEW Corridor walls shall form a barrier to limit the transfer of smoke. Such walls shall be permitted to terminate at the ceiling where the ceiling is constructed to limit the transfer of smoke. No fire resistance rating is required for the corridor walls. 18.3.6.2	0	0		

ID PREFIX		MET	NOT MET	N/A	REMARKS
K363	Corridor – Doors 2012 EXISTING Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas shall be substantial doors, such as those constructed of 1¾ inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. Doors shall be provided with a means suitable for keeping the door closed. There is no impediment to the closing of the doors. Clearance between bottom of door and floor covering is not exceeding 1 inch. Roller latches are prohibited by CMS regulations on corridor doors and rooms containing flammable or combustible materials. Powered doors complying with 7.2.1.9 are permissible. Hold open devices that release when the door is pushed or pulled are permitted. Nonrated protective plates of unlimited height are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.3, unless the smoke compartment is sprinklered. Fixed fire window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies. 19.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc.	•		0	
	Doors protecting corridor openings shall be constructed to resist the passage of smoke. Clearance between bottom of door and floor covering is not exceeding 1 inch. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or pulled are permitted. Doors shall be provided with self-latching and positive latching hardware. Nonrated protective plates of unlimited height are permitted. Dutch doors meeting 18.3.6.3.6 are permitted. Roller latches are prohibited by CMS regulations on corridor doors and rooms containing flammable or combustible materials. 18.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatic closing devices, etc.	0	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K364	Corridor – Openings Transfer grilles are not used in corridor walls or doors. Auxiliary spaces that do not contain flammable or combustible materials are permitted to have louvers or be undercut. In other than smoke compartments containing patient sleeping rooms, miscellaneous openings are permitted in vision panels or doors, provided the openings per room do not exceed 20 in² and are at or below half the distance from floor to ceiling. In sprinklered rooms, the openings per room do not exceed 80 in². Vision panels in corridor walls or doors shall be fixed window assemblies in approved frames. (In fully sprinklered smoke compartments, there are no restrictions in the area and fire resistance of glass and frames.) 18.3.6.5.1, 19.3.6.5.2, 8.3	•	0	0	
K371	Subdivision of Building Spaces – Smoke Compartments 2012 EXISTING Smoke barriers shall be provided to form at least two smoke compartments on every sleeping floor with a 30 or more patient bed capacity. Size of compartments cannot exceed 22,500 square feet or a 200-foot travel distance from any point in the compartment to a door in the smoke barrier. 19.3.7.1, 19.3.7.2 Detail in REMARKS zone dimensions including length of zones and deadend corridors.	0	0	•	
	Smoke barriers shall be provided to form at least two smoke compartments on every floor used by inpatients for sleeping or treatment, and on every floor with an occupant load of 50 or more persons, regardless of use. Size of compartments cannot exceed 22,500 square feet or a 200-foot travel distance from any point in the compartment to a door in the smoke barrier. Smoke subdivision requirements do not apply to any of the stories or areas described in 18.3.7.2. 18.3.7.1, 18.3.7.2 Detail in REMARKS zone dimensions including length of zones and deadend corridors.	0	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K372	Subdivision of Building Spaces – Smoke Barrier Construction		IVILI		
	2012 EXISTING				
	Smoke barriers shall be constructed to a ½ hour fire resistance rating per 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke barrier.	0	0	•	
	19.3.7.3, 8.6.7.1(1)				
	Describe any mechanical smoke control system in REMARKS.				
	2012 NEW				
	Smoke barriers shall be constructed to provide at least a 1-hour fire resistance rating and constructed in accordance with 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations of fully ducted HVAC systems. 18.3.7.3, 18.3.7.4, 18.3.7.5, 8.3	0	0	0	
	Describe any mechanical smoke control system in REMARKS.				
K373	Subdivision of Building Spaces – Accumulation Space Space shall be provided on each side of smoke barriers to adequately accommodate the total number of occupants in adjoining compartments.	0	0	•	
1/074	18.3.7.5.1, 18.3.7.5.2, 19.3.7.5.1, 19.3.7.5.2				
K374	Subdivision of Building Spaces – Smoke Barrier Doors 2012 EXISTING Doors in smoke barriers are 1¾-inch thick solid bonded wood-core doors or of construction that resists fire for 20 minutes. Nonrated protective plates of unlimited height are permitted. Doors are permitted to have fixed fire window assemblies per 8.5. Doors are self-closing or automatic-closing, do not require latching, and are not required to swing in the direction of egress travel. Door opening provides a minimum clear width of 32 in for swinging or horizontal doors. 19.3.7.6, 19.3.7.8, 19.3.7.9	0	0	•	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K374	2012 NEW		IVIEI		
	Doors in smoke barriers have at least a 20-minute fire protection rating or are at least 1¾-inch thick solid bonded core wood. Required clear widths are provided per 18.3.7.6(4) and (5).				
	Nonrated protective plates of unlimited height are permitted. Horizontal-sliding doors comply with 7.2.1.14. Swinging doors shall be arranged so that each door swings in an opposite direction.	0	0	0	
	Doors shall be self-closing and rabbets, bevels, or astragals are required at the meeting edges. Positive latching is not required.				
	18.3.7.6, 18.3.7.7, 18.3.7.8				
K379	Smoke Barrier Door Glazing				
	2012 EXISTING	_	_	_	
	Openings in smoke barrier doors shall be fire-rated glazing or wired glass panels in steel frames.	0	0	•	
	19.3.7.6, 19.3.7.6.2, 8.5				
	2012 NEW				
	Windows in smoke barrier doors shall be installed in each cross corridor swinging or horizontal-sliding door protected by fire-rated glazing or by wired glass panels in approved frames.	0	0	0	
	18.3.7.9				
K381	Sleeping Room Outside Windows and Doors				
	Every patient sleeping room has an outside window or outside door. In new occupancies, sill height does not exceed 36 inches above the floor. Windows in atrium walls are considered outside windows. Newborn nurseries and rooms intended for occupancy less than 24 hours have no outside window or door requirements. Window sills in special nursing care areas (e.g., ICU, CCU, hemodialysis, neonatal) do not exceed 60 inches above the floor. 42 CFR 403, 418, 460, 482, 483, and 485	•	0	0	
	SECTION 4 – SPECIAL PROVISIONS				
K400	Special Provisions – Other				
	List in the REMARKS section any LSC Section 18.4 and 19.4 Special Provisions requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567.	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K421	High-Rise Buildings 2012 EXISTING				
	High-rise buildings are protected throughout by an approved, supervised automatic sprinkler system in accordance with Section 9.7 within 12 years of LSC final rule effective date. 19.4.2	0	0	•	
	2012 NEW				
	High-rise buildings comply with section 11.8.				
	18.4.2)))	
	SECTION 5 – BUILDING SERVICES				
K500	Building Services – Other				
	List in the REMARKS section any LSC Section 18.5 and 19.5 Building Services requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567.	•	0	0	
K511	Utilities – Gas and Electric				
	Equipment using gas or related gas piping complies with NFPA 54, <i>National Fuel Gas Code</i> , electrical wiring and equipment complies with NFPA 70, <i>National Electric Code</i> . Existing installations can continue in service provided no hazard to life.	•	0	0	
	18.5.1.1, 19.5.1.1, 9.1.1, 9.1.2				
K521	HVAC				Observation revealed that the facility is using
	Heating, ventilation, and air conditioning shall comply with 9.2 and shall be installed in accordance with the manufacturer's specifications.	0	•	0	the second and third floor corridors as an exhaust plenum.
	18.5.2.1, 19.5.2.1, 9.2				Saladet premami
K522	HVAC – Any Heating Device				
	Any heating device, other than a central heating plant, is designed and installed so combustible materials cannot be ignited by device, and has a safety feature to stop fuel and shut down equipment if there is excessive temperature or ignition failure. If fuel fired, the device also:	0	0	•	
	is chimney or vent connected.				
	takes air for combustion from outside.				
	 provides for a combustion system separate from occupied area atmosphere. 				
	18.5.2.2,				

ID PREFIX		MET	NOT MET	N/A	REMARKS
K523	 HVAC – Suspended Unit Heaters Suspended unit heaters are permitted provided the following are met: Not located in means of egress or in patient rooms. Located high enough to be out of reach of people in the area. Has a safety feature to stop fuel and shut down equipment if there is excessive temperature or ignition failure. 18.5.2.3(1), 19.5.2.3(1) 	0	0	•	
K524	HVAC – Direct-Vent Gas Fireplaces Direct-vent gas fireplaces, as defined in NFPA 54, inside of all smoke compartments containing patient sleeping areas comply with the requirements of 18.5.2.3(2), 19.5.2.3(2). 18.5.2.3(2), 19.5.2.3(2), NFPA 54	0	0	•	
K525	 HVAC – Solid Fuel-Burning Fireplaces Solid fuel-burning fireplaces are permitted in other than patient sleeping areas provided: Areas are separated by 1-hour fire resistance construction. Fireplace complies with 9.2.2. Fireplace enclosure resists breakage up to 650°F and has heat-tempered glass. Room has supervised CO detection per 9.8. 18.5.2.3(3) and 19.5.2.3(3) 	0	0	•	
K531	Elevators 2012 EXISTING Elevators comply with the provision of 9.4. Elevators are inspected and tested as specified in ASME A17.1, Safety Code for Elevators and Escalators. Firefighter's Service is operated monthly with a written record. Existing elevators conform to ASME/ANSI A17.3, Safety Code for Existing Elevators and Escalators. All existing elevators, having a travel distance of 25 feet or more above or below the level that best serves the needs of emergency personnel for firefighting purposes, conform with Firefighter's Service Requirements of ASME/ANSI A17.3. (Includes firefighter's service Phase I key recall and smoke detector automatic recall, firefighter's service Phase II emergency in-car key operation, machine room smoke detectors, and elevator lobby smoke detectors.) 19.5.3, 9.4.2, 9.4.3	•	0	0	

ID		MET	NOT	N/A	REMARKS
K531	2012 NEW Elevators comply with the provision of 9.4. Elevators are inspected and tested as specified in ASME A17.1, Safety Code for Elevators and Escalators. Firefighter's Service is operated monthly with a written record. New elevators conform to ASME/ANSI A17.1, Safety Code for Elevators and Escalators, including Firefighter's Service Requirements. (Includes firefighter's Phase I key recall and smoke detector automatic recall, firefighter's service Phase II emergency in-car key operation, machine room smoke detectors, and elevator lobby smoke detectors.) 18.5.3, 9.4.2, 9.4.3	0	MET	0	
K532	Escalators, Dumbwaiters, and Moving Walks 2012 EXISTING Escalators, dumbwaiters, and moving walks comply with the provisions of 9.4. All existing escalators, dumbwaiters, and moving walks conform to the requirements of ASME/ANSI A17.3, Safety Code for Existing Elevators and Escalators. (Includes escalator emergency stop buttons and automatic skirt obstruction stop. For power dumbwaiters, includes hoistway door locking to keep doors closed except for floor where car is being loaded or unloaded.) 19.5.3, 9.4.2.2	0	0	•	
	2012 NEW Escalators, dumbwaiters, and moving walks comply with the provisions of 9.4. 18.5.3, 9.4.2.2	0	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K541	 Rubbish Chutes, Incinerators, and Laundry Chutes 2012 EXISTING (1) Any existing linen and trash chute, including pneumatic rubbish and linen systems, that opens directly onto any corridor shall be sealed by fire resistive construction to prevent further use or shall be provided with a fire door assembly having a fire protection rating of 1-hour. All new chutes shall comply with 9.5. (2) Any rubbish chute or linen chute, including pneumatic rubbish and linen systems, shall be provided with automatic extinguishing protection in accordance with 9.7. (3) Any trash chute shall discharge into a trash collection room used for no other purpose and protected in accordance with 8.4. (Existing laundry chutes permitted to discharge into same room are protected by automatic sprinklers in accordance with 19.3.5.9 or 19.3.5.7.) (4) Existing fuel-fed incinerators shall be sealed by fire resistive construction to prevent further use. 	0		•	
	 19.5.4, 9.5, 8.4, NFPA 82 2012 NEW Rubbish chutes, incinerators, and laundry chutes shall comply with the provisions of Section 9.5, unless otherwise specified in 18.5.4.2. The fire resistance rating of chute charging room shall not be required to exceed 1-hour. Any rubbish chute or linen chute shall be provided with automatic extinguishing protection in accordance with Section 9.7. Chutes shall discharge into a trash collection room used for no other purpose and shall be protected in accordance with 8.7. 18.5.4.2, 8.7, 9.5, 9.7, NFPA 82 	0	0	0	
	SECTION 6 - RESERVED				
	SECTION 7 – OPERATING FEATURES				
K700	Operating Features – Other List in the REMARKS section any LSC Section 18.7 and 19.7 Operating Features requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included in Form CMS-2567.	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K711	Evacuation and Relocation Plan There is a written plan for the protection of all patients and for their evacuation in the event of an emergency. Employees are periodically instructed and kept informed with their duties under the plan, and a copy of the plan is readily available with telephone operator or with security. The plan addresses the basic response required of staff per 18/19.7.2.1.2 and provides for all of the fire safety plan components per 18/19.7.2.2. 18.7.1.1 through 18.7.1.3, 18.7.2.1.2, 18.7.2.2, 18.7.2.3, 19.7.1.1 through 19.7.1.3, 19.7.2.1.2, 19.7.2.2, 19.7.2.3	•	0	0	
K712	Fire Drills Fire drills include the transmission of a fire alarm signal and simulation of emergency fire conditions. Fire drills are held at unexpected times under varying conditions, at least quarterly on each shift. The staff is familiar with procedures and is aware that drills are part of established routine. Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are conducted between 9:00 PM and 6:00 AM, a coded announcement may be used instead of audible alarms. 18.7.1.4 through 18.7.1.7, 19.7.1.4 through 19.7.1.7	0	•	0	Observation revealed that the facility could not provide documentation for receiving a verified alarm signal from the central monitoring company.

ID PREFIX		MET	NOT MET	N/A	REMARKS
K741	 Smoking Regulations Smoking regulations shall be adopted and shall include not less than the following provisions: (1) Smoking shall be prohibited in any room, ward, or compartment where flammable liquids, combustible gases, or oxygen is used or stored and in any other hazardous location, and such area shall be posted with signs that read NO SMOKING or shall be posted with the international symbol for no smoking. (2) In health care occupancies where smoking is prohibited and signs are prominently placed at all major entrances, secondary signs with language that prohibits smoking shall not be required. (3) Smoking by patients classified as not responsible shall be prohibited. (4) The requirement of 18.7.4(3) shall not apply where the patient is under direct supervision. (5) Ashtrays of noncombustible material and safe design shall be provided in all areas where smoking is permitted. (6) Metal containers with self-closing cover devices into which ashtrays can be emptied shall be readily available to all areas where smoking is permitted. 18.7.4, 19.7.4 	•	0	0	
K751	Draperies, Curtains, and Loosely Hanging Fabrics Draperies, curtains including cubicle curtains and loosely hanging fabric or films shall be in accordance with 10.3.1. Excluding curtains and draperies: at showers and baths; on windows in patient sleeping room located in sprinklered compartments; and in non-patient sleeping rooms in sprinklered compartments where individual drapery or curtain panels do not exceed 48 square feet or total area does not exceed 20 percent of the wall. 18.7.5.1, 18.3.5.11, 19.7.5.1, 19.3.5.11, 10.3.1	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K752	Newly introduced upholstered furniture meets Class I or char length, and heat release criteria in accordance with 10.3.2.1 and 10.3.3, unless the building is fully sprinklered. Newly introduced mattresses shall meet char length and heat release criteria in accordance with 10.3.2.2 and 10.3.4, unless the building is fully sprinklered. Upholstered furniture and mattresses belonging to nursing home residents do not have to meet these requirements as all nursing homes are required to be fully sprinklered. Newly introduced upholstered furniture and mattresses means purchased on or after the LSC final rule effective date. 18.7.5.2, 18.7.5.4, 19.7.5.2, 19.7.5.4	•	0	0	
K753	Combustible Decorations Combustible decorations shall be prohibited unless one of the following is met: • Flame retardant or treated with approved fire-retardant coating that is listed and labeled for product. • Decorations meet NFPA 701. • Decorations exhibit heat release less than 100 kilowatts in accordance with NFPA 289. • Decorations, such as photographs, paintings and other art are attached to the walls, ceilings and non-fire-rated doors in accordance with 18.7.5.6 or 19.7.5.6. • The decorations in existing occupancies are in such limited quantities that a hazard of fire is not present. 18.7.5.6, 19.7.5.6	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K754	Soiled Linen and Trash Containers				
	Soiled linen or trash collection receptacles shall not exceed 32 gallons in capacity. The average density of container capacity in a room or space shall not exceed 0.5 gallons/square feet. A total container capacity of 32 gallons shall not be exceeded within any 64 square feet area. Mobile soiled linen or trash collection receptacles with capacities greater than 32 gallons shall be located in a room protected as a hazardous area when not attended.	0	0	0	
	Containers used solely for recycling are permitted to be excluded from the above requirements where each container is ≤ 96 gal. unless attended, and containers for combustibles are labeled and listed as meeting FM Approval Standard 6921 or equivalent. 18.7.5.7, 19.7.5.7				
K771	Engineer Smoke Control Systems				
	2012 EXISTING				
	When installed, engineered smoke control systems are tested in accordance with established engineering principles. Test documentation is maintained on the premises.	0	0	•	
	19.7.7				
	2012 NEW When installed, engineered smoke control systems are tested in accordance with NFPA 92, <i>Standard for Smoke Control Systems</i> . Test documentation is maintained on the premises. 18.7.7	0	0	0	
K781	Portable Space Heaters Portable space heating devices shall be prohibited in all health care occupancies. Unless used in nonsleeping staff and employee areas where the heating elements do not exceed 212 degrees Fahrenheit (100 degrees Celsius). 18.7.8, 19.7.8	0	•	0	Observation revealed that the facility could not initially provide documentation for a space heater policy. Later in the survey a policy was produced but was dated as of the date of survey.
K791	Construction, Repair, and Improvement Operations				
	Construction, repair, and improvement operations shall comply with 4.6.10. Any means of egress in any area undergoing construction, repair, or improvements shall be inspected daily to ensure its ability to be used instantly in case of emergency and compliance with NFPA 241. 18.7.9, 19.7.9, 4.6.10, 7.1.10.1	0	0	•	

ID PREFIX		MET	NOT MET	N/A	REMARKS
	PART II – HEALTH CARE FACILITIES CODE REQUIREMENTS				
K900	Health Care Facilities Code - Other List in the REMARKS section any NFPA 99 requirements (excluding Chapter 7, 8, 12, and 13) that are not addressed by the provided K-Tags, but are deficient. This information, along with the applicable Health Care Facilities Code or NFPA standard citation, should be included on Form CMS-2567.	•	0	0	
K901	Fundamentals – Building System Categories Building systems are designed to meet Category 1 through 4 requirements as detailed in NFPA 99. Categories are determined by a formal and documented risk assessment procedure performed by qualified personnel. Chapter 4 (NFPA 99)	0	•	0	Observation revealed that the facility could not provide a risk assessment planned for building systems.
K902	Gas and Vacuum Piped Systems – Other List in the REMARKS section any NFPA 99 Chapter 5 Gas and Vacuum Systems requirements that are not addressed by the provided K-Tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. Chapter 5 (NFPA 99)	0	0	•	
K903	Gas and Vacuum Piped Systems – Categories Medical gas, medical air, surgical vacuum, WAGD, and air supply systems in which failure is likely to cause major injury or death are designated: □ Category 1. Systems in which failure is likely to cause minor injury to patients are designated. □ Category 2. Systems in which failure is not likely to cause injury, but can cause discomfort is designated. □ Category 3. Deep sedation and general anesthesia are not administered when using a Category 3 medical gas system. 5.1.1.1, 5.2.1, 5.3.1.1, 5.3.1.5 (NFPA 99)	0	0	•	
K904	Gas and Vacuum Piped Systems – Warning Systems All master, area, and local alarm systems used for medical gas and vacuum systems comply with appropriate Category warning system requirements, as applicable. 5.1.9, 5.2.9, 5.3.6.2.2 (NFPA 99)	0	0	•	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K905	Gas and Vacuum Piped Systems – Central Supply System Identification and Labeling Containers, cylinders and tanks are designed, fabricated, tested, and marked in accordance with 5.1.3.1.1 through 5.1.3.1.7. Locations containing only oxygen or medical air have doors labeled with "Medical	0	0	•	
	Gases, NO Smoking or Open Flame". Locations containing other gases have doors labeled "Positive Pressure Gases, NO Smoking or Open Flame, Room May Have Insufficient Oxygen, Open Door and Allow Room to Ventilate Before Opening." 5.1.3.1, 5.2.3.1, 5.3.10 (NFPA 99))))	
K906	Gas and Vacuum Piped Systems – Central Supply System Operations				
	Adaptors or conversion fittings are prohibited. Cylinders are handled in accordance with 11.6.2. Only cylinders, reusable shipping containers, and their accessories are stored in rooms containing central supply systems or cylinders. No flammable materials are stored with cylinders. Cryogenic liquid storage units intended to supply the facility are not used to transfill. Cylinders are kept away from sources of heat. Valve protection caps are secured in place, if supplied, unless cylinder is in use. Cylinders are not stored in tightly closed spaces. Cylinders in use and storage are prevented from exceeding 130°F, and nitrous oxide and carbon dioxide cylinders are prevented from reaching temperatures lower than manufacture recommendations or 20°F. Full or empty cylinders, when not connected, are stored in locations complying with 5.1.3.3.2 through 5.1.3.3.3, and are not stored in enclosures containing motor-driven machinery, unless for instrument air reserve headers. 5.1.3.2, 5.1.3.3.17, 5.1.3.3.1.8, 5.1.3.3.4, 5.2.3.2, 5.2.3.3, 5.3.6.20.4, 5.6.20.5, 5.3.6.20.7, 5.3.6.20.8, 5.3.6.20.9 (NFPA 99)	0	0	•	
K907	Gas and Vacuum Piped Systems – Maintenance Program				
	Medical gas, vacuum, WAGD, or support gas systems have documented maintenance programs. The program includes an inventory of all source systems, control valves, alarms, manufactured assemblies, and outlets. Inspection and maintenance schedules are established through risk assessment considering manufacturer recommendations. Inspection procedures and testing methods are established through risk assessment. Persons maintaining systems are qualified as demonstrated by training and certification or credentialing to the requirements of AASE 6030 or 6040. 5.1.14.2.1, 5.1.14.2.2, 5.1.15, 5.2.14, 5.3.13.4.2 (NFPA 99)	0	0	•	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K908	Gas and Vacuum Piped Systems – Inspection and Testing Operations				
	The gas and vacuum systems are inspected and tested as part of a maintenance program and include the required elements. Records of the inspections and testing are maintained as required. 5.1.14.2.3, B.5.2, 5.2.13, 5.3.13, 5.3.13.4 (NFPA 99)	0	\bigcirc	•	
K909	Gas and Vacuum Piped Systems – Information and Warning Signs				
	Piping is labeled by stencil or adhesive markers identifying the gas or vacuum system, including the name of system or chemical symbol, color code (Table 5.1.11), and operating pressure if other than standard. Labels are at intervals not more than 20 feet, are in every room, at both sides of wall penetrations, and on every story traversed by riser. Piping is not painted. Shutoff valves are identified with the name or chemical symbol of the gas or vacuum system, room or area served, and caution to not use the valve except in emergency. 5.1.14.3, 5.1.11.1, 5.1.11.2, 5.2.11, 5.3.13.3, 5.3.11 (NFPA 99)	0	0	•	
K910	Gas and Vacuum Piped Systems – Modifications				
1.010	Whenever modifications are made that breach the pipeline, any necessary installer and verification test specified in 5.1.2 is conducted on the downstream portion of the medical gas piping system. Permanent records of all tests required by system verification tests are maintained.	0	0	•	
	5.1.14.4.1, 5.1.14.4.6, 5.2.13, 5.3.13.4.3 (NFPA 99)				
K911	Electrical Systems – Other List in the REMARKS section any NFPA 99 Chapter 6 Electrical Systems requirements that are not addressed by the provided K-Tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. Chapter 6 (NFPA 99)	•	0	0	
K912	Electrical Systems – Receptacles				
	Power receptacles have at least one, separate, highly dependable grounding pole capable of maintaining low-contact resistance with its mating plug. In pediatric locations, receptacles in patient rooms, bathrooms, play rooms, and activity rooms, other than nurseries, are listed tamper-resistant or employ a listed cover. If used in patient care room, ground-fault circuit interrupters (GFCI) are listed. 6.3.2.2.6.2 (F), 6.3.2.4.2 (NFPA 99)	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K913	Electrical Systems – Wet Procedure Locations Operating rooms are considered wet procedure locations, unless otherwise determined by a risk assessment conducted by the facility governing body. Operating rooms defined as wet locations are protected by either isolated power or ground-fault circuit interrupters. A written record of the risk assessment is maintained and available for inspection. 6.3.2.2.8.4, 6.3.2.2.8.7, 6.4.4.2	0	0	•	
K914	Electrical Systems – Maintenance and Testing Hospital-grade receptacles at patient bed locations and where deep sedation or general anesthesia is administered, are tested after initial installation, replacement or servicing. Additional testing is performed at intervals defined by documented performance data. Receptacles not listed as hospital-grade at these locations are tested at intervals not exceeding 12 months. Line isolation monitors (LIM), if installed, are tested at intervals of ≤ 1 month by actuating the LIM test switch per 6.3.2.6.3.6, which activates both visual and audible alarm. For LIM circuits with automated self-testing, this manual test is performed at intervals ≤ 12 months. LIM circuits are tested per 6.3.3.3.2 after any repair or renovation to the electric distribution system. Records are maintained of required tests and associated repairs or modifications, containing date, room or area tested, and results. 6.3.4 (NFPA 99)	0	0	•	
K915	Electrical Systems – Essential Electric System Categories Critical care rooms (Category 1) in which electrical system failure is likely to cause major injury or death of patients, including all rooms where electric life support equipment is required, are served by a Type 1 EES. General care rooms (Category 2) in which electrical system failure is likely to cause minor injury to patients (Category 2) are served by a Type 1 or Type 2 EES. Basic care rooms (Category 3) in which electrical system failure is not likely to cause injury to patients and rooms other than patient care rooms are not required to be served by an EES. Type 3 EES life safety branch has an alternate source of power that will be effective for 1 1/2 hours. 3.3.138, 6.3.2.2.10, 6.6.2.2.2, 6.6.3.1.1 (NFPA 99), TIA 12-3	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K916	Electrical Systems – Essential Electric System Alarm Annunciator A remote annunciator that is storage battery powered is provided to operate outside of the generating room in a location readily observed by operating personnel. The annunciator is hard-wired to indicate alarm conditions of the emergency power source. A centralized computer system (e.g., building information system) is not to be substituted for the alarm annunciator. 6.4.1.1.17, 6.4.1.1.17.5 (NFPA 99)	•	0	0	
K917	Electrical Systems – Essential Electric System Receptacles Electrical receptacles or cover plates supplied from the life safety and critical branches have a distinctive color or marking. 6.4.2.2.6, 6.5.2.2.4.2, 6.6.2.2.3.2 (NFPA 99)	•	0	0	
K918	Electrical Systems – Essential Electric System Maintenance and Testing The generator or other alternate power source and associated equipment is capable of supplying service within 10 seconds. If the 10-second criterion is not met during the monthly test, a process shall be provided to annually confirm this capability for the life safety and critical branches. Maintenance and testing of the generator and transfer switches are performed in accordance with NFPA 110. Generator sets are inspected weekly, exercised under load 30 minutes 12 times a year in 20-40 day intervals, and exercised once every 36 months for 4 continuous hours. Scheduled test under load conditions include a complete simulated cold start and automatic or manual transfer of all EES loads, and are conducted by competent personnel. Maintenance and testing of stored energy power sources (Type 3 EES) are in accordance with NFPA 111. Main and feeder circuit breakers are inspected annually, and a program for periodically exercising the components is established according to manufacturer requirements. Written records of maintenance and testing are maintained and readily available. EES electrical panels and circuits are marked and readily identifiable. Minimizing the possibility of damage of the emergency power source is a design consideration for new installations. 6.4.4, 6.5.4, 6.6.4 (NFPA 99), NFPA 110, NFPA 111, 700.10 (NFPA 70)	0	•	0	 Observation revealed that the facility did not document the 30 minute generator load test separately from the minimum five minute cool-down period. Observation revealed that the facility could not provide evidence that the generator was tested monthly under at least 30 percent load capacity.

ID PREFIX		MET	NOT MET	N/A	REMARKS
K919	Electrical Equipment – Other List in the REMARKS section any NFPA 99 Chapter 10, Electrical Equipment, requirements that are not addressed by the provided K-Tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. Chapter 10 (NFPA 99)	•	0	0	
K920	Electrical Equipment – Power Cords and Extension Cords Power strips in a patient care vicinity are only used for components of movable patient-care-related electrical equipment (PCREE) assembles that have been assembled by qualified personnel and meet the conditions of 10.2.3.6. Power strips in the patient care vicinity may not be used for non-PCREE (e.g., personal electronics), except in long-term care resident rooms that do not use PCREE. Power strips for PCREE meet UL 1363A or UL 60601-1. Power strips for non-PCREE in the patient care rooms (outside of vicinity) meet UL 1363. In non-patient care rooms, power strips meet other UL standards. All power strips are used with general precautions. Extension cords are not used as a substitute for fixed wiring of a structure. Extension cords used temporarily are removed immediately upon completion of the purpose for which it was installed and meets the conditions of 10.2.4. 10.2.3.6 (NFPA 99), 10.2.4 (NFPA 99), 400-8 (NFPA 70), 590.3(D) (NFPA 70), TIA 12-5	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K921	Electrical Equipment – Testing and Maintenance Requirements				
	The physical integrity, resistance, leakage current, and touch current tests for fixed and portable patient-care related electrical equipment (PCREE) is performed as required in 10.3. Testing intervals are established with policies and protocols. All PCREE used in patient care rooms is tested in accordance with 10.3.5.4 or 10.3.6 before being put into service and after any repair or modification. Any system consisting of several electrical appliances demonstrates compliance with NFPA 99 as a complete system. Service manuals, instructions, and procedures provided by the manufacturer include information as required by 10.5.3.1.1 and are considered in the development of a program for electrical equipment maintenance. Electrical equipment instructions and maintenance manuals are readily available, and safety labels and condensed operating instructions on the appliance are legible. A record of electrical equipment tests, repairs, and modifications is maintained for a period of time to demonstrate compliance in accordance with the facility's policy. Personnel responsible for the testing, maintenance and use of electrical appliances receive continuing training. 10.3, 10.5.2.1, 10.5.2.1.2, 10.5.2.5, 10.5.3, 10.5.6, 10.5.8	•	0	0	
K922	Gas Equipment – Other				
	List in the REMARKS section any NFPA 99 Chapter 11 Gas Equipment requirements that are not addressed by the provided K-Tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. Chapter 11 (NFPA 99)	0	0	•	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K923	Storage locations are designed, constructed, and ventilated in accordance with 5.1.3.3.2 and 5.1.3.3.3. > 300 but <3,000 cubic feet Storage locations are outdoors in an enclosure or within an enclosed interior space of non- or limited- combustible construction, with door (or gates outdoors) that can be secured. Oxidizing gases are not stored with flammables, and are separated from combustibles by 20 feet (5 feet if sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating. ≤ 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of ≤ 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING". Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99)	0	•	0	Observation revealed that oxygen was being stored within five feet of combustible storage in the central nursing storage room.
K924	Gas Equipment – Testing and Maintenance Requirements Anesthesia apparatus are tested at the final path to patient after any adjustment, modification or repair. Before the apparatus is returned to service, each connection is checked to verify proper gas and an oxygen analyzer is used to verify oxygen concentration. Defective equipment is immediately removed from service. Areas designated for servicing of oxygen equipment are clean and free of oil, grease, or other flammables. Manufacturer service manuals are used to maintain equipment and a scheduled maintenance program is followed. 11.4.1.3, 11.5.1.3, 11.6.2.5, 11.6.2.6 (NFPA 99)	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K925	Gas Equipment – Respiratory Therapy Sources of Ignition				
	Smoking materials are removed from patients receiving respiratory therapy. When a nasal cannula is delivering oxygen outside of a patient's room, no sources of ignition are within in the site of intentional expulsion (1-foot). When other oxygen deliver equipment is used or oxygen is delivered inside a patient's room, no sources of ignition are within the area are of administration (15-feet). Solid fuel-burning appliances is not in the area of administration. Nonmedical appliances with hot surfaces or sparking mechanisms are not within oxygen-delivery equipment or site of intentional expulsion.	•	0	0	
	11.5.1.1, TIA 12-6 (NFPA 99)				
K926	Gas Equipment – Qualifications and Training of Personnel Personnel concerned with the application, maintenance and handling of medical gases and cylinders are trained on the risk. Facilities provide continuing education, including safety guidelines and usage requirements. Equipment is serviced only by personnel trained in the maintenance and operation of equipment. 11.5.2.1 (NFPA 99)	•	0	0	
K927	Gas Equipment – Transfilling Cylinders				
	Transfilling of oxygen from one cylinder to another is in accordance with CGA P-2.5, <i>Transfilling of High Pressure Gaseous Oxygen Used for Respiration</i> . Transfilling of any gas from one cylinder to another is prohibited in patient care rooms. Transfilling to liquid oxygen containers or to portable containers over 50 psi comply with conditions under 11.5.2.3.1 (NFPA 99). Transfilling to liquid oxygen containers or to portable containers under 50 psi comply with conditions under 11.5.2.3.2 (NFPA 99). 11.5.2.2 (NFPA 99)	0	0	•	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K928	Gas Equipment – Labeling Equipment and Cylinders				
	Equipment listed for use in oxygen-enriched atmospheres are so labeled. Oxygen metering equipment and pressure reducing regulators are labeled "OXYGEN-USE NO OIL". Flowmeters, pressure reducing regulators, and oxygen-dispensing apparatus are clearly and permanently labeled designating the gases for which they are intended. Oxygen-metering equipment, pressure reducing regulators, humidifiers, and nebulizers are labeled with name of manufacturer or supplier. Cylinders and containers are labeled in accordance with CGA C-7. Color coding is not utilized as the primary method of determining cylinder or container contents. All labeling is durable and withstands cleaning or disinfecting. 11.5.3.1 (NFPA 99)	•	0	0	
K929	Gas Equipment – Precautions for Handling Oxygen Cylinders and Manifolds Handling of oxygen cylinders and manifolds is based on CGA G-4, Oxygen. Oxygen cylinders, containers, and associated equipment are protected from contact with oil and grease, from contamination, protected from damage, and handled with care in accordance with precautions provided under 11.6.2.1 through 11.6.2.4 (NFPA 99).	•	0	0	
	11.6.2 (NFPA 99)				
K930	Gas Equipment – Liquid Oxygen Equipment The storage and use of liquid oxygen in base reservoir containers and portable containers comply with sections 11.7.2 through 11.7.4 (NFPA 99). 11.7 (NFPA 99)	•	0	0	
K931	Hyperbaric Facilities				
	All occupancies containing hyperbaric facilities comply with construction, equipment, administration, and maintenance requirements of NFPA 99. Chapter 14 (NFPA 99)	0	0	•	
K932	Features of Fire Protection – Other List in the REMARKS section any NFPA 99 Chapter 15 Features of Fire Protection requirements that are not addressed by the provided K-Tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. Chapter 15 (NFPA 99)	•	0	0	

ID PREFIX		MET	NOT MET	N/A	REMARKS
K933	applications and in anit deces.	0	MET		

Name of Facility 20	2012 LIFE SAFETY CODE
---------------------	-----------------------

PART III – RECOMMENDATION FOR WAIVER OF SPECIFIC LIFE SAFETY CODE PROVISIONS

For each item of the Life Safety Code recommended for waiver, list the survey report form item number and state the reason for the conclusion that: (a) the specific provisions of the code, if rigidly applied, would result in unreasonable hardship on the facility, and (b) the waiver of such unmet provisions will not adversely affect the health and safety of the patients. If additional space is required, attach additional sheet(s).

PROVISION NUMBER(S)	JUSTIFICATION	JUSTIFICATION		
K400				

Surveyor (Signature)	Title	Office	Date
Fire Authority Official (Signature)	Title	Office	Date

PART IV - FIRE SAFETY SURVEY REPORT CRUCIAL DATA EXTRACT (TO BE USED WITH CMS 2786 FORMS)


Provider Number		Facility Name		Survey Date						
K1					*K4					
						1 131				
		OF PLAN	K3 MULT	IPLE CONSTRUCTION	ON A. BUILDING					
	APPF	ROVAL	TOTAL NUME	BER OF BUILDINGS	D MINO					
			C. FLOOR							
			NUMBER OF	THIS BUILDING		D. APARTMEN	T UNIT			
LSC	FORM	M INDICATOR			COMPLETE IF EXISTING	ICF/IID IS SURVEYE	D UNDER CHAPTER 33,			
		HEALTH	CARE FORM		EXISTING					
	12	2786R	2012 EXISTIN	G	SMALL (1	6 BEDS OR LESS)				
	13	2786R	2012 NEW			1. PROMP	Т			
					K8	2. SLOW 3. IMPRAC	CTICAL			
		AHC	O FORM		LARGE					
	14	2786U	2012 EXISTIN	G						
	15	2786U	2012 NEW			4. PROMP 5. SLOW	T			
					K8	6. IMPRAC	CTICAL			
		ICF/II	D FORM		APARTMENT HOUSE					
	16	2786V, W, X	2012 EXISTIN	G	ALAKTWENT		-			
	17	2786V, W, X	2012 NEW		K8	7. PROMP 8. SLOW	1			
						9. IMPRAC	CTICAL			
*K7		SELECT NUMBE								
l	=	BELECT NOWB	ER OF FORM U	SED FROM ABOVE						
(Cho	ok if k	(221 or K251 or	e marked as not	applicable	COMPLETE IF ICF/IID IS SURVEYED UNDER CHAPTER 33, EXISTING					
•		6 M, R, T, U, V,		аррисавіе	ENTER E – SCORE					
			, ,		ENTER E – SCORE					
		K321:	K351:		K5:	e.g. 2.5				
*K9	ΕΛ	CILITY MEETS	L SC BASED O	N (Chook all that Ann	h ()					
			LOC BASED O	N (Check all that App	<i>'y)</i>					
	A′	l	A2.	A3	3.	A4.	A5.			
		MP. WITH ALL ROVISIONS)	(ACCEP	TABLE POC)	(WAIVERS)	(FSES)	(PERFORMANCE BASED DESIGN)			
FAC	ILITY	DOES NOT ME	ET LSC	K0180						
				А.	B.		C.			
В.		FULLY SPRINKLER	RED PARTIAI	LY SPRINKLERED	NONE					
		<u></u>		(All required areas ar		Il required areas are	(No sprinkler system)			
*****	NDAT	ODV		sprinklered)		sprinklered)				
IVIAI	NDAI	OIN I								


BIRCHWOOD CARG HONE

Dining Room Food Storage 82 REAR

For Fire Marshal Division File

BIRCHWOOD CARGE HOME 715 W 31ST ST MPLS, MN





ORIGINAL For Fire Marshal Division File

Minnesota State Fire Marshal Division-CMS Survey Draft Statement of Deficiencies Page of							
PROJEC	T NUMBER:	PROVIDER NAME		SURVEY DATE			
Adminis	strator:		Phone Numb	Der:			
Email address:							
State Fir	re Inspector:						
These ar		findings only. A complete and final S	Statement of Deficiencies	2567 report will be provided			
At 1 Satin t	the time of this fety Code app the Medicare/I	s inspection. this facility was found to licable to: SNF/NF Hospital Medicaid programs. re/life safety deficiencies were fou	I □ICFMR □ASC F	acilities participating			
K TAG S& S		Summary of Deficiency(ies)	Revisit	☐ Clearance			

Minnesota State Fire Marshal Division-CMS Survey Draft Statement of Deficiencies Page of							
PROJEC	T NUMBER:	PROVIDER NAME		SURVEY DATE			
Adminis	strator:		Phone Numb	Der:			
Email address:							
State Fir	re Inspector:						
These ar		findings only. A complete and final S	Statement of Deficiencies	2567 report will be provided			
At 1 Satin t	the time of this fety Code app the Medicare/I	s inspection. this facility was found to licable to: SNF/NF Hospital Medicaid programs. re/life safety deficiencies were fou	I □ICFMR □ASC F	acilities participating			
K TAG S& S		Summary of Deficiency(ies)	Revisit	☐ Clearance			

Minnesota	State Fire Mars	hal Division-CMS Survey Draft Statemen	nt of Deficiencies	Page of		
PROJEC	T NUMBER:	PROVIDER NAME		SURVEY DATE		
Adminis	strator:	I.	Phone Numb	DÈT:		
Email a	ddress:					
State Fin	re Inspector:					
These ar		findings only. A complete and final S	Statement of Deficiencies	2567 report will be provided		
At 1 Satin t						
K TAG S& S		Summary of Deficiency(ies)	Revisit	☐ Clearance		

MINNESOTA DEPARTMENT OF HEALTH Division of Health Policy, Information and Compliance Monitoring 85 East Seventh Place, Suite 300, P.O. Box 64900 St. Paul, Minnesota 55164-0900

Email for Admini	strator: randy Pbirchw	oodcare.com
National Provide One facility may ha	r Identifier (NPI) Number: 145 ve multiple NPI Numbers. Please verify the	
OWNERSHIP INFO	DRMATION AT THE TIME OF SURVEY	
Name of Facility:	BIRCHWOOD CARE HOME	City: MINNEAPOLIS
Name of Legal En	tity Operating Provider: <u>DYNAMIC HEA</u>	ALTH CONCEPTS, INC.
Name and Addres	s of Governing Board President:	
Name:	RANDAL HAGEMEYER	
	5000 NOB HILL DR	
	EDINA, MN 55439 resident of the governing board is diffenation below.	
Name of Facility		City:
	ntity Operating Provider:	
	ess of Governing Board President:	
Name:		
Address:		
City/State/	Zip:	
SIGNATURE Completed by:	RANDAIL HALEMEYN	2.1
	1017	