Electronically Delivered

May 15, 2025

Licensee
Advanced Group Home LLC
2325 Explorer Court
Burnsville, MN 55337

RE: Project Number(s) SL39827015

Dear Licensee:

This is your **official notice** that you have been **granted your assisted living facility license.** Your license effective and expiration dates remain the same as on your provisional license. Your updated status will be listed on the license certificate at renewal and **this letter serves as proof** in the meantime. If you have not received a letter from us with information regarding renewing your license within 60 days prior to your expiration date, please contact us at (651) 201-5273 or by email at Health.assistedliving@state.mn.us.

On April 21, 2025, the Minnesota Department of Health completed a follow-up survey of your facility to determine correction of orders from the survey completed on October 15, 2025. This follow-up survey verified that the facility is in substantial compliance.

You are encouraged to retain this document for your records. It is your responsibility to share the information contained in the letter with your organization's Governing Body.

Please feel free to call me with any questions.

Sincerely,

Jess Schoenecker, Supervisor
State Evaluation Team
Email: Jess.Schoenecker@state.mn.us
Telephone: 651-201-3789 Fax: 1-866-890-9290

HHH

DEPARTMENT OF HEALTH

Protecting, Maintaining and Improving the Health of All Minnesotans

NOTICE OF PROVISIONAL EXTENSION AND CONDITIONAL LICENSE

Electronically Delivered

March 6, 2025

Licensee
Advanced Group Home LLC
2325 Explorer Court
Burnsville, MN 55337

RE: Provisional Conditional License Number 412316
Health Facility Identification Number (HFID) 39827
Project Number(s) SL39827015

Dear Licensee:

The Minnesota Department of Health (MDH) completed a follow-up survey on December 30, 2024, for the purpose of assessing compliance with state licensing statutes. Based on the follow-up survey results you were found not to be in substantial compliance with the laws pursuant to Minnesota Statutes, Chapter 144G.

As a result, pursuant to Minn. Stat. § 144G.16, Subd. 3(b)(2), MDH is extending the provisional license for 60-days and applying conditions necessary to bring the facility into substantial compliance. The provisional license extension and conditions are due to expire **May 5, 2025**.

IMPOSITION OF FINES
In accordance with Minn. Stat. § 144G.31, Subd. 4, fines and enforcement actions may be imposed based on the level and scope of the violations and may be imposed immediately with no opportunity to correct the violation first as follows:

Level 1: no fines or enforcement.
Level 2: a fine of $500 per violation, in addition to any enforcement mechanism authorized in § 144G.20 for widespread violations;
Level 3: a fine of $3,000 per violation per incident, in addition to any enforcement mechanism authorized in § 144G.20.
Level 4: a fine of $5,000 per incident, in addition to any enforcement mechanism authorized in § 144G.20.

MDH may assess fines based on the level and scope of the orders outlined below. The total amount of **potential** fines that may be assessed related to these correction orders is $3,000.00. **MDH is not imposing these fines against your provisional license at this time.**

St - 0 - 0470 - 144g.41 Subdivision 1 - Minimum Requirements - $3,000.00

The details of the violation(s) noted at the time of this follow-up survey are delineated on the attached State Form. Only the ID Prefix Tag in the left hand column without brackets will identify these state correction orders. It is not necessary to develop a plan of correction.

DOCUMENTATION OF ACTION TO COMPLY

In accordance with Minn. Stat. § 144G.30, Subd. 5(c), the provisional licensee must document actions taken to comply with the correction orders and immediately correct any reissued orders outlined on the state form; however, plans of correction are not required to be submitted for approval. **If corrections are not made, MDH may impose fines as described above and in accordance with Minnesota Statutes 144G.**

The correction order documentation should include the following:

- Identify how the area(s) of noncompliance was corrected related to the resident(s)/employee(s) identified in the correction order.
- Identify how the area(s) of noncompliance was corrected for all of the provider's resident(s)/employees that may be affected by the noncompliance.
- Identify what changes to your systems and practices were made to ensure compliance with the specific statute(s).

CORRECTION ORDER RECONSIDERATION PROCESS

In accordance with Minn. Stat. § 144G.32, Subd. 2, you may challenge the correction order(s) issued, including the level and scope, and any fine assessed through the correction order reconsideration process. The request for reconsideration must be in writing and received by MDH within 15 calendar days of the correction order receipt date.

To submit a reconsideration request, please visit:
https://forms.web.health.state.mn.us/form/HRDAppealsForm

CONDITIONAL LICENSE ISSUED:

MDH will extend the provisional conditional assisted living facility license for Advanced Group Home LLC for an additional 60 calendar days from the date of this notice. At an unannounced point in time, within the 60 calendar days, MDH will conduct a follow-up survey, as defined in Minn. Stat. § 144G.30, Subd. 6. Based on the results of the follow-up survey, MDH will determine if Advanced Group Home LLC is in substantial compliance.

The following conditions on the license have been removed, effective March 6, 2025:

a. **Health Facility Construction Permit:** Advanced Group Home LLC, will contact The Minnesota Department of Labor and Industry (MNDLI) or City with delegated authority to review and inspect State Licensed Facilities in accordance with Minn. Stat. § 326B.103, Subd. 13 and obtain a construction

permit for a health facility. Within 21-days from the date of this notice, Advanced Group Home LLC, will provide MDH with a copy of the permit obtained from MNDLI or City with delegated authority.

b. **General Contractor:** Advanced Group Home LLC must provide the following to Benjamin J. Zwart (Benjamin.Zwart@state.mn.us) via email within 21-days of the date of this notice:
    i. Name
    ii. License Number
    iii. Contact Information

c. **Egress Window Requirements:** Advanced Group Home LLC will replace at least one window in unoccupied resident sleeping room #4 meeting the minimum size requirements.
    i. Must have a minimum openable width of no less than 20 inches
    ii. Must have a minimum openable height of no less than 20 inches
    iii. Must have a total openable area of no less than 648 square inches (4.5 square feet)
    iv. Must have a windowsill height of no more than 48 inches from the floor to the clear opening
    v. All measurements must be achieved under normal operation of opening window without the use of a key, tool or special knowledge

The following condition has been applied to the conditional assisted living facility license:

a. **No new admissions:** Advanced Group Home LLC will not admit any new residents under its conditional assisted living facility license until MDH removes the "no new admissions" condition. Advanced Group Home LLC must provide the Department:

    i. A list of the names and birthdates of any individuals Advanced Group Home LLC is currently in the process of admitting. These individuals will be able to continue the admittance process.

    ii. A list of all current residents including:
        1. Name and birthdate of each resident
        2. Current payment source for services
        3. If Elderly Waiver, the name and contact information of the care coordinator/case manager
        4. If the resident is not able to make informed decisions, the name of their representative and how to contact the representative

RESULTS OF FOLLOW-UP EVALUATION DURING THE CONDITIONAL PROVISIONAL LICENSE PERIOD:
MDH will determine if Advanced Group Home LLC is in substantial compliance based on the results of

the follow up survey. MDH will make this determination within the 90-day conditional provisional license period. If MDH determines Advanced Group Home LLC is in substantial compliance on the follow up survey, MDH will remove the conditions and grant the assisted living facility license to Advanced Group Home LLC. If MDH determines Advanced Group Home LLC is not in substantial compliance, MDH may deny the license pursuant to Minn. Stat. § 144G.16, Subd. 3 (b) (2).

REQUEST FOR RECONSIDERATION:

Pursuant to Minn. Stat. §144G.16, Subd. 4, if a provisional licensee whose assisted living facility license has been denied, or extended with conditions, disagrees with the action taken against the provisional license under this section, the provisional licensee may request a reconsideration no later than 15 calendar days after provisional licensee receives notice of the action. **This is your only ability to request a reconsideration under this enforcement action.**

To submit a reconsideration request, please visit:
https://forms.web.health.state.mn.us/form/HRDAppealsForm

You are encouraged to retain this document for your records. It is your responsibility to share the information contained in the letter and state form with your organization's Governing Body.

If you have any questions, please contact Jodi Johnson directly at: 507-344-2730.

Sincerely,

Rick Michals

Rick Michals, J.D.
Executive Regional Operations Manager

Minnesota Department of Health
Health Regulation Division

HHH

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{0 000}	Initial Comments *****ATTENTION****** ASSISTED LIVING PROVIDER LICENSING CORRECTION ORDER In accordance with Minnesota Statutes, section 144G.08 to 144G.95 this correction order(s) has been issued pursuant to a survey. Determination of whether a violation has been corrected requires compliance with all requirements provided at the Statute number indicated below. When Minnesota Statute contains several items, failure to comply with any of the items will be considered lack of compliance. INITIAL COMMENTS: SL39827015-1 On December 30, 2024, the Minnesota Department of Health conducted a follow-up survey at the above provider to follow-up on orders issued pursuant to a survey completed on October 15, 2024. At the time of the survey, there were two residents receiving services under the provisional Assisted Living license. As a result of the follow-up survey, the following orders were issued or reissued.	{0 000}	Minnesota Department of Health is documenting the State Correction Orders using federal software. Tag numbers have been assigned to Minnesota State Statutes for Assisted Living Facilities. The assigned tag number appears in the far-left column entitled "ID Prefix Tag." The state Statute number and the corresponding text of the state Statute out of compliance is listed in the "Summary Statement of Deficiencies" column. This column also includes the findings which are in violation of the state requirement after the statement, "This Minnesota requirement is not met as evidenced by." Following the evaluators ' findings is the Time Period for Correction. PLEASE DISREGARD THE HEADING OF THE FOURTH COLUMN WHICH STATES,"PROVIDER'S PLAN OF CORRECTION." THIS APPLIES TO FEDERAL DEFICIENCIES ONLY. THIS WILL APPEAR ON EACH PAGE. THERE IS NO REQUIREMENT TO SUBMIT A PLAN OF CORRECTION FOR VIOLATIONS OF MINNESOTA STATE STATUTES. THE LETTER IN THE LEFT COLUMN IS USED FOR TRACKING PURPOSES AND REFLECTS THE SCOPE AND LEVEL ISSUED PURSUANT TO 144G.31 SUBDIVISION 1-3.	
0 470 SS=I	144G.41 Subdivision 1 Minimum requirements (11) develop and implement a staffing plan for	0 470		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 470	Continued From page 1 determining its staffing level that: (i) includes an evaluation, to be conducted at least twice a year, of the appropriateness of staffing levels in the facility; (ii) ensures sufficient staffing at all times to meet the scheduled and reasonably foreseeable unscheduled needs of each resident as required by the residents' assessments and service plans on a 24-hour per day basis; and (iii) ensures that the facility can respond promptly and effectively to individual resident emergencies and to emergency, life safety, and disaster situations affecting staff or residents in the facility; (12) ensure that one or more persons are available 24 hours per day, seven days per week, who are responsible for responding to the requests of residents for assistance with health or safety needs. Such persons must be: (i) awake; (ii) located in the same building, in an attached building, or on a contiguous campus with the facility in order to respond within a reasonable amount of time; (iii) capable of communicating with residents; (iv) capable of providing or summoning the appropriate assistance; and (v) capable of following directions; This MN Requirement is not met as evidenced by: Based on observation and interview, the licensee failed to ensure one or more persons were available 24 hours per day, seven days per week, who are responsible for responding the the requests of residents for assistance with health or safety needs. This had the potential to affect all residents, staff, and visitors. This practice resulted in a level three violation (a violation that harmed a resident's health or safety,	0 470		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 470	Continued From page 2 not including serious injury, impairment, or death, or a violation that has the potential to lead to serious injury, impairment, or death) and was issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has potential to affect a large portion or all of the residents). The findings include: On December 30, 2024, at 11:05 a.m., the surveyor initiated a follow-up on orders issued pursuant to a survey completed on October 15, 2024. The surveyor knocked on the front door of the facility three different times and rang the doorbell two separate times. After approximately five minutes of no answer, the surveyor returned to their car that was parked directly in front of the facility. At 11:18 a.m. while the surveyor was attempting to get phone contact information for the facility, a black sedan pulled into the driveway and the occupant walked up the sidewalk and entered the facility through the front door. The surveyor went back to the front door and knocked. The same person answered the door. The surveyor identified themself and reason for their visit. The occupant reported that they had just taken a resident to Walmart on American Blvd and dropped them off. The surveyor asked their name and position. They responded with their name, and title as unlicensed personnel (ULP)-C. The surveyor asked ULP-C if they were the only staff working at that time, and ULP-C stated that they were. The surveyor asked ULP-C how many residents they were providing services for, and ULP-C said two. The surveyor asked ULP-C where the other resident (R1) was when ULP-C left the facility. ULP-C stated R1 was in	0 470		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 470	Continued From page 3 their room sleeping, but ULP-C had informed R1 of the trip to Walmart prior to leaving the facility. After the surveyor completed their inspection in a different resident room, the surveyor asked ULP-C which other resident room was occupied. ULP-C said resident room 5 was the other occupied room. Prior to the surveyor leaving the facility, R1 came to their room door and asked ULP-C who the surveyor was. The surveyor did not hear any response as they were walking down the stairs to leave the facility. No further information was provided. TIME PERIOD FOR CORRECTION: IMMEDIATE	0 470		
{0 480} SS=F	144G.41 Subdivision 1 Subd. 1a (a-b) Minimum requirements; required food services (a) Except as provided in paragraph (b), food must be prepared and served according to the Minnesota Food Code, Minnesota Rules, chapter 4626. (b) For an assisted living facility with a licensed capacity of ten or fewer residents: (1) notwithstanding Minnesota Rules, part 4626.0033, item A, the facility may share a certified food protection manager (CFPM) with one other facility located within a 60-mile radius and under common management provided the CFPM is present at each facility frequently enough to effectively administer, manage, and supervise each facility's food service operation; (2) notwithstanding Minnesota Rules, part 4626.0545, item A, kick plates that are not removable or cannot be rotated open are allowed unless the facility has been issued repeated correction orders for violations of Minnesota Rules, part 4626.1565 or 4626.1570;	{0 480}		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{0 480}	Continued From page 4 (3) notwithstanding Minnesota Rules, part 4626.0685, item A, the facility is not required to provide integral drainboards, utensil racks, or tables large enough to accommodate soiled and clean items that may accumulate during hours of operation provided soiled items do not contaminate clean items, surfaces, or food, and clean equipment and dishes are air dried in a manner that prevents contamination before storage; (4) notwithstanding Minnesota Rules, part 4626.1070, item A, the facility is not required to install a dedicated handwashing sink in its existing kitchen provided it designates one well of a two-compartment sink for use only as a handwashing sink; (5) notwithstanding Minnesota Rules, parts 4626.1325, 4626.1335, and 4626.1360, item A, existing floor, wall, and ceiling finishes are allowed provided the facility keeps them clean and in good condition; (6) notwithstanding Minnesota Rules, part 4626.1375, shielded or shatter-resistant lightbulbs are not required, but if a light bulb breaks, the facility must discard all exposed food and fully clean all equipment, dishes, and surfaces to remove any glass particles; and (7) notwithstanding Minnesota Rules, part 4626.1390, toilet rooms are not required to be provided with a self-closing door. This MN Requirement is not met as evidenced by:	{0 480}	Not reviewed during this survey.	
{0 780} SS=F	144G.45 Subd. 2 (a) (1) Fire protection and physical environment	{0 780}		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{0 780}	Continued From page 5 for dwellings or sleeping units, as defined in the State Fire Code: (i) provide smoke alarms in each room used for sleeping purposes; (ii) provide smoke alarms outside each separate sleeping area in the immediate vicinity of bedrooms; (iii) provide smoke alarms on each story within a dwelling unit, including basements, but not including crawl spaces and unoccupied attics; (iv) where more than one smoke alarm is required within an individual dwelling unit or sleeping unit, interconnect all smoke alarms so that actuation of one alarm causes all alarms in the individual dwelling unit or sleeping unit to operate; and (v) ensure the power supply for existing smoke alarms complies with the State Fire Code, except that newly introduced smoke alarms in existing buildings may be battery operated; This MN Requirement is not met as evidenced by:	{0 780}	Not reviewed during this survey.	
{0 800} SS=F	144G.45 Subd. 2 (a) (4) Fire protection and physical environment (4) keep the physical environment, including walls, floors, ceiling, all furnishings, grounds, systems, and equipment in a continuous state of good repair and operation with regard to the health, safety, comfort, and well-being of the residents in accordance with a maintenance and repair program.	{0 800}		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{0 800}	Continued From page 6 This MN Requirement is not met as evidenced by:	{0 800}	Not reviewed during this survey.	
{0 810} SS=F	144G.45 Subd. 2 (b-f) Fire protection and physical environment (b) Each assisted living facility shall develop and maintain fire safety and evacuation plans. The plans shall include but are not limited to: (1) location and number of resident sleeping rooms; (2) staff actions to be taken in the event of a fire or similar emergency; (3) fire protection procedures necessary for residents; and (4) procedures for resident movement, evacuation, or relocation during a fire or similar emergency including the identification of unique or unusual resident needs for movement or evacuation. (c) Staff of assisted living facilities shall receive training on the fire safety and evacuation plans upon hiring and at least twice per year thereafter. (d) Fire safety and evacuation plans shall be readily available at all times within the facility. (e) Residents who are capable of assisting in their own evacuation shall be trained on the proper actions to take in the event of a fire to include movement, evacuation, or relocation. The training shall be made available to residents at least once per year. (f) Evacuation drills are required for staff twice per year per shift with at least one evacuation drill every other month. Evacuation of the residents is not required. Fire alarm system activation is not	{0 810}		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{0 810}	Continued From page 7 required to initiate the evacuation drill. This MN Requirement is not met as evidenced by:	{0 810}	Not reviewed during this survey.	
{01620} SS=F	144G.70 Subd. 2 (c-e) Initial reviews, assessments, and monitoring (c) Resident reassessment and monitoring must be conducted no more than 14 calendar days after initiation of services. Ongoing resident reassessment and monitoring must be conducted as needed based on changes in the needs of the resident and cannot exceed 90 calendar days from the last date of the assessment. (d) For residents only receiving assisted living services specified in section 144G.08, subdivision 9, clauses (1) to (5), the facility shall complete an individualized initial review of the resident's needs and preferences. The initial review must be completed within 30 calendar days of the start of services. Resident monitoring and review must be conducted as needed based on changes in the needs of the resident and cannot exceed 90 calendar days from the date of the last review. (e) A facility must inform the prospective resident of the availability of and contact information for long-term care consultation services under section 256B.0911, prior to the date on which a prospective resident executes a contract with a facility or the date on which a prospective resident moves in, whichever is earlier. This MN Requirement is not met as evidenced by:	{01620}	Not reviewed during this survey.	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	R 12/30/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{01650} SS=F	144G.70 Subd. 4 (f) Service plan, implementation and revisions to (f) The service plan must include: (1) a description of the services to be provided, the fees for services, and the frequency of each service, according to the resident's current assessment and resident preferences; (2) the identification of staff or categories of staff who will provide the services; (3) the schedule and methods of monitoring assessments of the resident; (4) the schedule and methods of monitoring staff providing services; and (5) a contingency plan that includes: (i) the action to be taken if the scheduled service cannot be provided; (ii) information and a method to contact the facility; (iii) the names and contact information of persons the resident wishes to have notified in an emergency or if there is a significant adverse change in the resident's condition, including identification of and information as to who has authority to sign for the resident in an emergency; and (iv) the circumstances in which emergency medical services are not to be summoned consistent with chapters 145B and 145C, and declarations made by the resident under those chapters. This MN Requirement is not met as evidenced by:	{01650}	Not reviewed during this survey.	

DEPARTMENT OF HEALTH

Protecting, Maintaining and Improving the Health of All Minnesotans

NOTICE OF PROVISIONAL EXTENSION AND CONDITIONAL LICENSE

Electronically Delivered

November 20, 2024

Licensee
Advanced Group Home LLC
2325 Explorer Court
Burnsville, MN 55337

RE: Provisional Conditional License Number 412316
Health Facility Identification Number (HFID) 39827
Project Number(s) SL39827015

Dear Licensee:

The Minnesota Department of Health (MDH) completed a survey on October 15, 2024, for the purpose of assessing compliance with state licensing statutes. Based on the survey results you were found not to be in substantial compliance with the laws pursuant to Minnesota Statutes, Chapter 144G.

As a result, pursuant to Minn. Stat. § 144G.16, Subd. 3(b)(2), MDH is extending the provisional license for 90-days and applying conditions necessary to bring the facility into substantial compliance. The provisional license extension and conditions are due to expire **February 18, 2025**.

STATE CORRECTION ORDERS
The enclosed State Form documents the state correction orders. MDH documents state correction orders using federal software. Tag numbers are assigned to Minnesota state statutes for Assisted Living Facilities. The assigned tag number appears in the far left column entitled "ID Prefix Tag." The state statute number and the corresponding text of the state statute out of compliance are listed in the "Summary Statement of Deficiencies" column. This column also includes the findings that are in violation of the state statute after the statement, "This MN Requirement is not met as evidenced by . . ."

In accordance with Minn. Stat. § 144G.31 Subd. 4, MDH may assess fines based on the level and scope of the violations; **however, no immediate fines are assessed for this survey of your facility**.

DOCUMENTATION OF ACTION TO COMPLY
In accordance with Minn. Stat. § 144G.30, Subd. 5(c), the provisional licensee must document actions taken to comply with the correction orders and immediately correct any reissued orders outlined on the state form; however, plans of correction are not required to be submitted for approval.

The correction order documentation should include the following:

- Identify how the area(s) of noncompliance was corrected related to the resident(s)/employee(s) identified in the correction order.
- Identify how the area(s) of noncompliance was corrected for all of the provider's resident(s)/employees that may be affected by the noncompliance.
- Identify what changes to your systems and practices were made to ensure compliance with the specific statute(s).

CORRECTION ORDER RECONSIDERATION PROCESS

In accordance with Minn. Stat. § 144G.32, Subd. 2, you may challenge the correction order(s) issued, including the level and scope, and any fine assessed through the correction order reconsideration process. The request for reconsideration must be in writing and received by MDH within 15 calendar days of the correction order receipt date.

To submit a reconsideration request, please visit:
https://forms.web.health.state.mn.us/form/HRDAppealsForm

CONDITIONAL LICENSE ISSUED:

MDH will issue Advanced Group Home LLC a conditional provisional assisted living facility license for 90 calendar days from the date of this notice. At an unannounced point in time, within the 90 calendar days, MDH will conduct a follow-up survey, as defined in Minn. Stat. § 144G.30, Subd. 6. Based on the results of the follow-up survey, MDH will determine if Advanced Group Home LLC is in substantial compliance.

The following conditions apply on the conditional provisional assisted living facility license:

a. **Health Facility Construction Permit:** Advanced Group Home LLC, will contact The Minnesota Department of Labor and Industry (MNDLI) or City with delegated authority to review and inspect State Licensed Facilities in accordance with Minn. Stat. § 326B.103, Subd. 13 and obtain a construction permit for a health facility. Within 21-days from the date of this notice, Advanced Group Home LLC, will provide MDH with a copy of the permit obtained from MNDLI or City with delegated authority.

b. **General Contractor:** Advanced Group Home LLC must provide the following to Benjamin J. Zwart (Benjamin.Zwart@state.mn.us) via email within 21-days of the date of this notice:
    i. Name
    ii. License Number
    iii. Contact Information

c. **Egress Window Requirements:** Advanced Group Home LLC will replace at least one window in unoccupied resident sleeping room #4 meeting the minimum size requirements.

i. Must have a minimum openable width of no less than 20 inches
ii. Must have a minimum openable height of no less than 20 inches
iii. Must have a total openable area of no less than 648 square inches (4.5 square feet)
iv. Must have a windowsill height of no more than 48 inches from the floor to the clear opening
v. All measurements must be achieved under normal operation of opening window without the use of a key, tool or special knowledge

RESULTS OF FOLLOW-UP EVALUATION DURING THE CONDITIONAL PROVISIONAL LICENSE PERIOD:
MDH will determine if Advanced Group Home LLC is in substantial compliance based on the results of the follow up survey. MDH will make this determination within the 90-day conditional provisional license period. If MDH determines Advanced Group Home LLC is in substantial compliance on the follow up survey, MDH will remove the conditions and grant the assisted living facility license to Advanced Group Home LLC. If MDH determines Advanced Group Home LLC is not in substantial compliance, MDH may deny the license pursuant to Minn. Stat. § 144G.16, Subd. 3 (b) (2).

REQUEST FOR RECONSIDERATION:
Pursuant to Minn. Stat. §144G.16, Subd. 4, if a provisional licensee whose assisted living facility license has been denied, or extended with conditions, disagrees with the action taken against the provisional license under this section, the provisional licensee may request a reconsideration no later than 15 calendar days after provisional licensee receives notice of the action. **This is your only ability to request a reconsideration under this enforcement action.**

To submit a reconsideration request, please visit:
https://forms.web.health.state.mn.us/form/HRDAppealsForm

You are encouraged to retain this document for your records. It is your responsibility to share the information contained in the letter and state form with your organization's Governing Body.

If you have any questions, please contact Benjamin J. Zwart directly at: 651-201-3715.

Sincerely,

Rick Michals

Rick Michals, J.D.
Executive Regional Operations Manager

Minnesota Department of Health
Health Regulation Division

JMD

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 000	Initial Comments ASSISTED LIVING PROVIDER LICENSING CORRECTION ORDER(S) In accordance with Minnesota Statutes, section 144G.08 to 144G.95, these correction orders are issued pursuant to a survey. Determination of whether violations are corrected requires compliance with all requirements provided at the Statute number indicated below. When Minnesota Statute contains several items, failure to comply with any of the items will be considered lack of compliance. INITIAL COMMENTS: SL39827015-0 On October 14, 2024, through October 15, 2024, the Minnesota Department of Health conducted a full survey at the above provider. At the time of the survey, there was one resident; one receiving services under the Provisional Assisted Living Facility license.	0 000	Minnesota Department of Health is documenting the State Correction Orders using federal software. Tag numbers have been assigned to Minnesota State Statutes for Assisted Living Facilities. The assigned tag number appears in the far left column entitled "ID Prefix Tag." The state Statute number and the corresponding text of the state Statute out of compliance is listed in the "Summary Statement of Deficiencies" column. This column also includes the findings which are in violation of the state requirement after the statement, "This Minnesota requirement is not met as evidenced by." Following the evaluators ' findings is the Time Period for Correction. PLEASE DISREGARD THE HEADING OF THE FOURTH COLUMN WHICH STATES,"PROVIDER'S PLAN OF CORRECTION." THIS APPLIES TO FEDERAL DEFICIENCIES ONLY. THIS WILL APPEAR ON EACH PAGE. THERE IS NO REQUIREMENT TO SUBMIT A PLAN OF CORRECTION FOR VIOLATIONS OF MINNESOTA STATE STATUTES. THE LETTER IN THE LEFT COLUMN IS USED FOR TRACKING PURPOSES AND REFLECTS THE SCOPE AND LEVEL ISSUED PURSUANT TO 144G.31 SUBDIVISION 1-3.	
0 480 SS=F	144G.41 Subd 1 (13) (i) (B) Minimum requirements	0 480		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 480	Continued From page 1 (13) offer to provide or make available at least the following services to residents: (B) food must be prepared and served according to the Minnesota Food Code, Minnesota Rules, chapter 4626; and This MN Requirement is not met as evidenced by: Based on observation, interview, and record review, the licensee failed to ensure food was prepared and served according to the Minnesota Food Code. This practice resulted in a level two violation (a violation that did not harm a resident's health or safety but had the potential to have harmed a resident's health or safety) and was issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has the potential to affect a large portion or all the residents). The findings include: Please refer to the document titled, Food and Beverage Establishment Inspection Report (FBEIR) dated October 14, 2024, for the specific Minnesota Food Code violations. The Inspection Report was provided to the licensee within 24 hours of the inspection. TIME PERIOD FOR CORRECTION: Please refer to the FBEIR for any compliance dates.	0 480		
0 780 SS=F	144G.45 Subd. 2 (a) (1) Fire protection and physical environment (a) Each assisted living facility must comply with the State Fire Code in Minnesota Rules, chapter	0 780		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 780	Continued From page 2 7511, and: (1) for dwellings or sleeping units, as defined in the State Fire Code: (i) provide smoke alarms in each room used for sleeping purposes; (ii) provide smoke alarms outside each separate sleeping area in the immediate vicinity of bedrooms; (iii) provide smoke alarms on each story within a dwelling unit, including basements, but not including crawl spaces and unoccupied attics; (iv) where more than one smoke alarm is required within an individual dwelling unit or sleeping unit, interconnect all smoke alarms so that actuation of one alarm causes all alarms in the individual dwelling unit or sleeping unit to operate; and (v) ensure the power supply for existing smoke alarms complies with the State Fire Code, except that newly introduced smoke alarms in existing buildings may be battery operated; This MN Requirement is not met as evidenced by: Based on observation, and interview the licensee failed to provide code compliant locking arrangement on the signed entry/exit doors. This deficient condition had the ability to affect all staff and residents. This practice resulted in a level two violation (a violation that did not harm a resident's health or safety but had the potential to have harmed a resident's health or safety, but was not likely to cause serious injury, impairment, or death), and was issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has potential to affect	0 780		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 780	Continued From page 3 a large portion or all of the residents). The findings include: On October 15, 2024, from 11:20 a.m. to 12:50 a.m., the surveyor toured the facility with assisted living director in residency (ALDIR)-A. The following was observed. The main entry/exit door for the facility had a lockable handle, a deadbolt, and a second deadbolt style lock. Exit doors are only allowed to have two locks. ALDIR-A acknowledged and stated that they understood the locking requirements. At time of discovery, ALDIR-A directed another staff member to remove the strike side of the lock rendering it inoperable. The kitchen door to the rear yard was signed as an exit door as well as identified as an exit on the posted egress maps. The kitchen door to the rear yard had a lockable handle, a deadbolt, a second deadbolt style lock, and a chain style lock installed on it. Exit doors are only allowed to have two locks. ALDIR-A acknowledged and stated that they understood the locking requirements. At time of discovery, ALDIR-A stated that since the kitchen door to the rear yard was not a required exit that they would remove the exit sign and remove the kitchen door to the rear yard as a signed exit door on the posted egress maps. TIME PERIOD FOR CORRECTION: Seven (7) days	0 780		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 800	Continued From page 4	0 800		
0 800 SS=F	144G.45 Subd. 2 (a) (4) Fire protection and physical environment (4) keep the physical environment, including walls, floors, ceiling, all furnishings, grounds, systems, and equipment in a continuous state of good repair and operation with regard to the health, safety, comfort, and well-being of the residents in accordance with a maintenance and repair program. This MN Requirement is not met as evidenced by: Based on observation and interview, the licensee failed to maintain the physical environment, including walls, floors, ceiling, all furnishings, grounds, systems, and equipment in a continuous state of good repair and operation with regard to the health, safety, comfort, and well-being of the residents. This deficient condition had the potential to affect all staff, residents, and visitors. This practice resulted in a level two violation (a violation that did not harm a resident's health or safety but had the potential to have harmed a resident's health or safety, but was not likely to cause serious injury, impairment, or death), and was issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has potential to affect a large portion or all of the residents). The findings include: On October 15, 2024, from 11:20 a.m. to 12:50 p.m., the surveyor toured the facility with assisted living director in residency (ALDIR)-A. The following was observed.	0 800		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 800	Continued From page 5 There was missing and damaged drywall in the required fire rated ceiling in the garage by the chimney. Fire separation is required to be maintained between the garage and the rest of the facility. TIME PERIOD FOR CORRECTION: Seven (7) days	0 800		
0 810 SS=F	144G.45 Subd. 2 (b)-(f) Fire protection and physical environment (b) Each assisted living facility shall develop and maintain fire safety and evacuation plans. The plans shall include but are not limited to: (1) location and number of resident sleeping rooms; (2) employee actions to be taken in the event of a fire or similar emergency; (3) fire protection procedures necessary for residents; and (4) procedures for resident movement, evacuation, or relocation during a fire or similar emergency including the identification of unique or unusual resident needs for movement or evacuation. (c) Employees of assisted living facilities shall receive training on the fire safety and evacuation plans upon hiring and at least twice per year thereafter. (d) Fire safety and evacuation plans shall be readily available at all times within the facility. (e) Residents who are capable of assisting in their own evacuation shall be trained on the proper actions to take in the event of a fire to include movement, evacuation, or relocation. The training shall be made available to residents at least once per year. (f) Evacuation drills are required for employees	0 810		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 810	Continued From page 6 twice per year per shift with at least one evacuation drill every other month. Evacuation of the residents is not required. Fire alarm system activation is not required to initiate the evacuation drill. This MN Requirement is not met as evidenced by: Based on observation, interview, and record review, the licensee failed to develop the fire safety and evacuation plan with the required content and provide the required training and drills. This had the potential to directly affect all residents, staff, and visitors. This practice resulted in a level two violation (a violation that did not harm a resident's health or safety but had the potential to have harmed a resident's health or safety) and was issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has potential to affect a large portion or all of the residents). The findings include: On October 15, 2024, from 11:20 a.m. to 12:50 p.m., the surveyor observed the fire evacuation diagrams included the garage as an emergency exit. The surveyor explained to assisted living director in residency (ALDIR)-A that emergency exits are not allowed through a higher hazard area like a garage. The evacuation diagrams also failed to show the location and number of resident sleeping rooms. Evacuation diagrams must be correctly labeled to reduce confusion and potential obstructions to egress in a fire or similar emergency.	0 810		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 810	Continued From page 7 During interview with ALDIR-A on October 15, 2024, at 12:45 p.m. ALDIR-A stated that they would make the needed adjustments to the fire evacuation diagrams. TIME PERIOD FOR CORRECTION: Twenty-one (21) days	0 810		
0 820 SS=F	144G.45 Subd. 2 (g) Fire protection and physical environment (g) Existing construction or elements, including assisted living facilities that were registered as housing with services establishments under chapter 144D prior to August 1, 2021, shall be permitted to continue in use provided such use does not constitute a distinct hazard to life. Any existing elements that an authority having jurisdiction deems a distinct hazard to life must be corrected. The facility must document in the facility's records any actions taken to comply with a correction order, and must submit to the commissioner for review and approval prior to correction. This MN Requirement is not met as evidenced by: Based on observation and interview, the licensee failed to ensure physical facility elements did not constitute a distinct hazard to life. The licensee failed to provide resident bedrooms with the minimum window opening meeting the minimum state standard for egress. This had the potential to affect some residents, staff, and visitors. This practice resulted in a level two violation (a violation that did not harm a resident's health or	0 820		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
0 820	Continued From page 8 safety but had the potential to have harmed a resident's health or safety) and was issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has the potential to affect a large portion or all of the residents). The findings include: On October 15, 2024, from 11:20 a.m. to 12:50 p.m., the surveyor toured the facility with assisted living director in residency (ALDIR)-A. During the tour, the surveyor asked ALDIR-A to open the windows in the resident rooms for measurement. The noncompliant measurements were as follows: In unoccupied resident room 4 measured 19 ½ inches in clear width, and 37 ½ inches in clear height, and 731 ¼ square inches total open area. The window did not meet the requirement for clear window width. Existing emergency escape and rescue openings are required to meet a minimum clear opening area of 648 square inches and have a minimum dimension of 20 inches in height and a minimum dimension of 20 inches in width. TIME PERIOD FOR CORRECTION: Two (2) days	0 820		
01620 SS=F	144G.70 Subd. 2 (c-e) Initial reviews, assessments, and monitoring (c) Resident reassessment and monitoring must be conducted no more than 14 calendar days after initiation of services. Ongoing resident reassessment and monitoring must be conducted	01620		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
01620	Continued From page 9 as needed based on changes in the needs of the resident and cannot exceed 90 calendar days from the last date of the assessment. (d) For residents only receiving assisted living services specified in section 144G.08, subdivision 9, clauses (1) to (5), the facility shall complete an individualized initial review of the resident's needs and preferences. The initial review must be completed within 30 calendar days of the start of services. Resident monitoring and review must be conducted as needed based on changes in the needs of the resident and cannot exceed 90 calendar days from the date of the last review. (e) A facility must inform the prospective resident of the availability of and contact information for long-term care consultation services under section 256B.0911, prior to the date on which a prospective resident executes a contract with a facility or the date on which a prospective resident moves in, whichever is earlier. This MN Requirement is not met as evidenced by: Based on observation, interview, and record review, the licensee failed to complete a comprehensive assessment every 90 days for the licensee's one resident (R1). This practice resulted in a level two violation (a violation that did not harm a resident's health or safety but had the potential to have harmed a resident's health or safety) and was issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has the potential to affect a large portion or all of the residents). The findings include: On October 15, 2024, at 8:13 a.m. ULP-C was	01620		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
01620	Continued From page 10 observed administering medications to R1. R1's medical record included the following: - 14-day comprehensive assessment completed on June 1, 2024 - 90 day comprehensive assessment completed on September 5, 2024, there was 96 days between assessments. On October 15, 2024, at 10:20 a.m. clinical nurse supervisor (CNS)-B stated the assessment was late and should have been completed within 90 days. No further information was provided. TIME PERIOD FOR CORRECTION: Twenty-one (21) days	01620		
01650 SS=F	144G.70 Subd. 4 (f) Service plan, implementation and revisions to (f) The service plan must include: (1) a description of the services to be provided, the fees for services, and the frequency of each service, according to the resident's current assessment and resident preferences; (2) the identification of staff or categories of staff who will provide the services; (3) the schedule and methods of monitoring assessments of the resident; (4) the schedule and methods of monitoring staff providing services; and (5) a contingency plan that includes: (i) the action to be taken if the scheduled service cannot be provided; (ii) information and a method to contact the facility; (iii) the names and contact information of persons	01650		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
01650	Continued From page 11 the resident wishes to have notified in an emergency or if there is a significant adverse change in the resident's condition, including identification of and information as to who has authority to sign for the resident in an emergency; and (iv) the circumstances in which emergency medical services are not to be summoned consistent with chapters 145B and 145C, and declarations made by the resident under those chapters. This MN Requirement is not met as evidenced by: Based on observation, interview, and record review, the licensee failed to ensure the service plan included all required content for the licensee's one resident (R1). This practice resulted in a level two violation (a violation that did not harm a resident's health or safety but had the potential to have harmed a resident's health or safety) and was issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has the potential to affect a large portion or all of the residents). The findings include: On October 15, 2024, at 8:13 a.m. ULP-C was observed administering medications to R1. R1's Service Plan - Modification dated May 18, 2024, indicated R1's services included bathing, dressing, medication administration, housekeeping, and laundry. R1's service plan failed to include the following required content: - the fee for services - the schedule and methods of monitoring	01650		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	39827	A. BUILDING: _____ B. WING _____	10/15/2024

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ADVANCED GROUP HOME LLC	2325 EXPLORER COURT BURNSVILLE, MN 55337

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
01650	Continued From page 12 assessments of the resident; - the schedule and methods of monitoring staff providing services; and - a contingency plan that includes: - the action to be taken if the scheduled service cannot be provided; - information and a method to contact the facility; - the names and contact information of persons the resident wishes to have notified in an emergency or if there is a significant adverse change in the resident's condition, including identification of and information as to who has authority to sign for the resident in an emergency; and - the circumstances in which emergency medical services are not to be summoned consistent with chapters 145B and 145C, and declarations made by the resident under those chapters. On October 15, 2024, at 10:32 a.m. assisted living director in residency (ALDIR)-A stated the incorrect document was printed from the electronic system and therefore it did not contain the required information. No further information was provided. TIME PERIOD FOR CORRECTION: Twenty-One (21) days.	01650		

Minnesota Department of Health
Food, Pools, & Lodging Services
P.O. Box 64975
Saint Paul, MN 55164-0975
651-201-4500

Type: Full
Date: *10/14/24*
Time: 13:30:00
Report: 1005241264

Food and Beverage Establishment Inspection Report

Location:
ADVANCED GROUP HOME LLC
2325 EXPLORER COURT
Burnsville, MN55337
Dakota County, 19

Establishment Info:
ID #: 0043714
Risk:
Announced Inspection: No

License Categories:

Expires on: 12/31/24

Operator:

Phone #:
ID #:

The violations listed in this report include any previously issued orders and deficiencies identified during this inspection. Compliance dates are shown for each item.

The following orders were issued during this inspection.

3-500B Microbial Control: hot and cold holding

3-501.16A2 ***** Priority 1 *****

MN Rule 4626.0395A2 Maintain all cold, TCS foods at 41 degrees F (5 degrees C) or below under mechanical refrigeration.

SOME TCS FOODS IN THE REFRIGERATOR WERE ABOVE 41 DEGREES F. REFRIGERATOR WAS ADJUSTED TO A COLDER TEMPERATURE. USE FOOD THERMOMETER TO VERIFY TEMPERATURES AND ADJUST FURTHER IF NEEDED.

Comply By: 10/14/24

Surface and Equipment Sanitizers

Utensil Surface Temp.: = at 160+ Degrees Fahrenheit
Location: DISHWASHER
Violation Issued: No

Food and Equipment Temperatures

Process/Item: Cold Hold/MILK
Temperature: 44 Degrees Fahrenheit - Location: KITCHEN REFRIGERATOR
Violation Issued: Yes

Process/Item: Cold Hold/NOODLES
Temperature: 39 Degrees Fahrenheit - Location: KITCHEN REFRIGERATOR
Violation Issued: No

Process/Item: Cold Hold/CHEESE
Temperature: 43 Degrees Fahrenheit - Location: KITCHEN REFRIGERATOR
Violation Issued: Yes

Type: Full
Date: *10/14/24*
Time: 13:30:00
Report: 1005241264
ADVANCED GROUP HOME LLC

Food and Beverage Establishment Inspection Report

Total Orders In This Report	Priority 1	Priority 2	Priority 3
	1	0	0

INSPECTION COMPLETED WITH STAFF AND REVIEWED WITH HRD NURSING EVALUATOR WENDY BUCKHOLZ.

FACILITY RUNS THERMOLABELS THROUGH THE DISHWASHER ONCE PER MONTH AND KEEPS THEM IN A LOG. THE LAST LABEL WAS RUN ON 10/1/24 AND REACHED A TEMPERATURE OF 160+ DEGREES F.

DISCUSSED DATE MARKING, GLOVE USE, COOKING TEMPERATURES, CROSS-CONTAMINATION, AND EMPLOYEE ILLNESS.

KITCHEN IS RESIDENTIAL AND FOOD IS PREPARED FOR SAME DAY SERVICE.

FLOORING IS LAMINATE, CABINETS ARE WOOD WITH HOLLOW BASE, AND COUNTERS ARE LAMINATE. ALL ARE FOUND TO BE IN GOOD CONDITION AND WILL BE MONITORED AT FUTURE INSPECTIONS. IF AT SUCH A TIME THEY ARE FOUND TO BE A CONCERN OR RISK OF CONTAMINATION, THEY WILL BE ORDERED TO BE REPLACED AND BROUGHT UP TO CODE.

NOTE: Plans and specifications must be submitted for review and approval prior to new construction, remodeling or alterations.

I acknowledge receipt of the Minnesota Department of Health inspection report number 1005241264 of 10/14/24.

Certified Food Protection Manager: SUMAYO J. MOHAMUD

Certification Number: FM117754 Expires: 05/23/26

Inspection report reviewed with person in charge and emailed.

Signed: _____
FATIMA MOHAMUD

Signed: _____
Jessica Davis
Public Health Sanitarian III
651-201-3961
jessica.davis@state.mn.us