

Protecting, Maintaining and Improving the Health of All Minnesotans

Electronically Delivered January 17, 2024

Administrator Littlefork Medical Center 912 Main Street Littlefork, MN 56653

RE: CCN: 245542 Cycle Start Date: December 6, 2023

Dear Administrator:

On January 4, 2024, the Minnesota Departments of Health and Public Safety, completed a revisit to verify that your facility had achieved and maintained compliance. Based on our review, we have determined that your facility has achieved substantial compliance; therefore no remedies will be imposed.

Feel free to contact me if you have questions.

Sincerely,

Kumala Fiske Downing

Kamala Fiske-Downing Minnesota Department of Health Health Regulation Division Telephone: (651) 201-4112 Email: <u>Kamala.Fiske-Downing@state.mn.us</u>

An equal opportunity employer.



Protecting, Maintaining and Improving the Health of All Minnesotans

Electronically delivered December 13, 2023

Administrator Littlefork Medical Center 912 Main Street Littlefork, MN 56653

RE: CCN: 245542 Cycle Start Date: December 6, 2023

Dear Administrator:

On December 6, 2023, a survey was completed at your facility by the Minnesota Departments of Health and Public Safety, to determine if your facility was in compliance with Federal participation requirements for skilled nursing facilities and/or nursing facilities participating in the Medicare and/or Medicaid programs.

This survey found the most serious deficiencies in your facility to be widespread deficiencies that constituted no actual harm with potential for more than minimal harm that was not immediate jeopardy (Level F), as evidenced by the electronically attached CMS-2567 whereby corrections are required.

ELECTRONIC PLAN OF CORRECTION (ePoC)

Within **ten (10) calendar days** after your receipt of this notice, you must submit an acceptable ePOC for the deficiencies cited. An acceptable ePOC will serve as your allegation of compliance. Upon receipt of an acceptable ePOC, we will authorize a revisit to your facility to determine if substantial compliance has been achieved.

To be acceptable, a provider's ePOC must include the following:

- How corrective action will be accomplished for those residents found to have been affected by the
 - deficient practice.
- How the facility will identify other residents having the potential to be affected by the same deficient practice.
- What measures will be put into place, or systemic changes made, to ensure that the deficient practice will not recur.
- How the facility will monitor its corrective actions to ensure that the deficient practice is being corrected and will not recur.
- The date that each deficiency will be corrected.
- An electronic acknowledgement signature and date by an official facility representative.

An equal opportunity employer.

Littlefork Medical Center December 13, 2023 Page 2

The state agency may, in lieu of an onsite revisit, determine correction and compliance by accepting the facility's ePoC if the ePoC is reasonable, addresses the problem and provides evidence that the corrective action has occurred.

If an acceptable ePoC is not received within 10 calendar days from the receipt of this letter, we will recommend to the CMS Region V Office that one or more of the following remedies be imposed:

- Denial of payment for new Medicare and Medicaid admissions (42 CFR 488.417);
- Civil money penalty (42 CFR 488.430 through 488.444).
- Termination of your facility's Medicare and/or Medicaid agreement (488.456(b)).

DEPARTMENT CONTACT

Questions regarding this letter and all documents submitted as a response to the resident care deficiencies (those preceded by an "F"and/or an "E" tag), i.e., the plan of correction should be directed to:

Jen Bahr, RN, Unit Supervisor Bemidji District Office Licensing and Certification Program Health Regulation Division Minnesota Department of Health 705 5th Street NW, Suite A Bemidji, Minnesota 56601-2933 Email: Jennifer.bahr@state.mn.us Office: (218) 308-2104 Mobile: (218) 368-3683

PRESUMPTION OF COMPLIANCE - CREDIBLE ALLEGATION OF COMPLIANCE

The facility's ePoC will serve as your allegation of compliance upon the Department's acceptance. In order for your allegation of compliance to be acceptable to the Department, the ePoC must meet the criteria listed in the plan of correction section above. You will be notified by the Minnesota Department of Health, Licensing and Certification Program staff and/or the Department of Public Safety, State Fire

Marshal Division staff, if your ePoC for the respective deficiencies (if any) is acceptable.

VERIFICATION OF SUBSTANTIAL COMPLIANCE

Upon receipt of an acceptable ePoC, a Post Certification Revisit (PCR), of your facility will be conducted to validate that substantial compliance with the regulations has been attained in accordance with your verification.

If substantial compliance has been achieved, certification of your facility in the Medicare and/or Medicaid program(s) will be continued and remedies will not be imposed. Compliance is certified as of the latest correction date on the approved ePoC, unless it is determined that either correction actually Littlefork Medical Center December 13, 2023 Page 3

occurred between the latest correction date on the ePoC and the date of the first revisit, or correction occurred sooner than the latest correction date on the ePoC.

FAILURE TO ACHIEVE SUBSTANTIAL COMPLIANCE BY THE THIRD OR SIXTH MONTH AFTER THE LAST DAY OF THE SURVEY

If substantial compliance with the regulations is not verified by March 6, 2024 (three months after the identification of noncompliance), the CMS Region V Office must deny payment for new admissions as mandated by the Social Security Act (the Act) at Sections 1819(h)(2)(D) and 1919(h)(2)(C) and Federal regulations at 42 CFR Section 488.417(b).

In addition, if substantial compliance with the regulations is not verified by June 6, 2024 (six months after the identification of noncompliance) your provider agreement will be terminated. This action is mandated by the Social Security Act at Sections 1819(h)(2)(C) and 1919(h)(3)(D) and Federal

regulations at 42 CFR Sections 488.412 and 488.456.

Please note that this notice does not constitute formal notice of imposition of alternative remedies or termination of your provider agreement. Should the Centers for Medicare & Medicaid Services determine that termination or any other remedy is warranted, it will provide you with a separate formal notification of that determination.

INFORMAL DISPUTE RESOLUTION (IDR) / INDEPENDENT INFORMAL DISPUTE RESOLUTION (IIDR)

In accordance with 42 CFR 488.331, you have one opportunity to question cited deficiencies through an informal dispute resolution process. You are required to send your written request, along with the specific deficiencies being disputed, and an explanation of why you are disputing those deficiencies, to:

> Nursing Home Informal Dispute Process Minnesota Department of Health Health Regulation Division P.O. Box 64900 St. Paul, Minnesota 55164-0900

This request must be sent within the same ten days you have for submitting an ePoC for the cited

deficiencies. All requests for an IDR or IIDR of federal deficiencies must be submitted via the web at: https://mdhprovidercontent.web.health.state.mn.us/ltc_idr.cfm

You must notify MDH at this website of your request for an IDR or IIDR within the 10 calendar day period allotted for submitting an acceptable electronic plan of correction. A copy of the Department's informal dispute resolution policies are posted on the MDH Information Bulletin website at: <u>https://www.health.state.mn.us/facilities/regulation/infobulletins/ib04_8.html</u>

Please note that the failure to complete the informal dispute resolution process will not delay the dates specified for compliance or the imposition of remedies.

Littlefork Medical Center December 13, 2023 Page 4

Questions regarding all documents submitted as a response to the Life Safety Code deficiencies (those preceded by a "K" tag), i.e., the plan of correction, request for waivers, should be directed to:

> Travis Z. Ahrens Interim State Fire Safety Supervisor Health Care & Correctional Facilities/Explosives MN Department of Public Safety-Fire Marshal Division 445 Minnesota St., Suite 145 St. Paul, MN 55101 travis.ahrens@state.mn.us Cell: 1-507-308-4189

Feel free to contact me if you have questions.

Sincerely,

Kumala Fiske Downing

Kamala Fiske-Downing Minnesota Department of Health Health Regulation Division Telephone: (651) 201-4112 Email: <u>Kamala.Fiske-Downing@state.mn.us</u>

DEPARTMENT OF HEALTH AND HUMAN SERVICES

PRINTED: 01/19/2024 FORM APPROVED OMB NO: 0938-0391

CENTE	JENTERS FOR MEDICARE & MEDICAID SERVICES					. 0938-039
	TATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA ND PLAN OF CORRECTION IDENTIFICATION NUMBER:		, ,	IPLE CONSTRUCTION	` '	E SURVEY
		245542	B. WING		12/	C / 06/2023
NAME OF PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 912 MAIN STREET LITTLEFORK, MN 56653			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIVE ACTION SHO (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPE DEFICIENCY)	ULD BE	(X5) COMPLETION DATE
E 000	Initial Comments		E 00	00		
	compliance with Ap Preparedness Req	h 12/6/23, a survey for opendix Z, Emergency uirements, §483.73(b)(6) was standard recertification was in compliance.				

The facility's plan of correction (POC) will serve as your allegation of compliance upon the Department's acceptance. Because you are enrolled in ePOC, your signature is not required at the bottom of the first page of the CMS-2567 form. Upon receipt of an acceptable electronic POC, an onsite revisit of your facility may be conducted to validate substantial compliance with the regulation has been attained.

F 000 INITIAL COMMENTS

On 12/4/23 through 12/6/23, a standard recertification survey was conducted at your facility. Complaint investigations were also conducted. Your facility was in compliance with the requirements of 42 CFR 483, Subpart B, Requirements for Long Term Care Facilities.

The following complaints were reviewed with no deficiencies cited: H55427533C (MN92638), H55427532C (MN93021), H55427531C (MN93656), H55427530C (MN94384), and H55427529C (MN94647).

The facility's plan of correction (POC) will corve

F 000

Electronically Signed Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution		12/19/2023
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
as your allegation of compliance upon the Departments acceptance. Because you are enrolled in ePOC, your signature is not required at the bottom of the first page of the CMS-2567 form. Your electronic submission of the POC will be used as verification of compliance.		

following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 733411


Facility ID: 00324

If continuation sheet Page 1 of 2

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/19/2024 FORM APPROVED OMB NO: 0938-0391

CENTE	KS FOR MEDICARE	& MEDICAID SERVICES			ONR NO	. 0938-0391
STATEMENT OF DEFICIENCIES (X1 AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING		(X3) DATE SURVEY COMPLETED	
		245542	B. WING			C 06/2023
	PROVIDER OR SUPPLIER	ER		STREET ADDRESS, CITY, STATE, ZIP CODE 912 MAIN STREET LITTLEFORK, MN 56653		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	EFIX (EACH CORRECTIVE ACTION SHOULD BE		(X5) COMPLETION DATE
F 000	Continued From pa	ige 1	F 00	0		
	onsite revisit of you	acceptable electronic POC, an ir facility may be conducted to compliance with the en attained.				



FORM CMS-2567(02-99) Previous Versions Obsolete	Event ID: 733411	Facility ID: 00324	If continuation sheet Page 2 of 2

		ID HUMAN SERVICES MEDICAID SERVICES	5542035		PRINTED: 12/21/2023 FORM APPROVED OMB NO. 0938-0391
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		LE CONSTRUCTION 5 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED
		245542	B. WING		12/06/2023
	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 912 MAIN STREET LITTLEFORK, MN 56653	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIVE (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPR DEFICIENCY)	JLD BE COMPLETION
K 000	INITIAL COMMENTS		K 00	0	
	FIRE SAFETY				
	conducted by the Mir Safety, State Fire Ma	recertification survey was nesota Department of Public rshal Division on 12/06/2023.			

At the time of this survey, Littlefork Medical Center was found not in compliance with the requirements for participation in Medicare/Medicaid at 42 CFR, Subpart 483.70(a), Life Safety from Fire, and the 2012 edition of National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19 Existing Health Care and the 2012 edition of NFPA 99, Health Care Facilities Code.

THE FACILITY'S POC WILL SERVE AS YOUR ALLEGATION OF COMPLIANCE UPON THE DEPARTMENT'S ACCEPTANCE. YOUR SIGNATURE AT THE BOTTOM OF THE FIRST PAGE OF THE CMS-2567 FORM WILL BE USED AS VERIFICATION OF COMPLIANCE.

UPON RECEIPT OF AN ACCEPTABLE POC, AN ONSITE REVISIT OF YOUR FACILITY MAY BE CONDUCTED TO VALIDATE THAT SUBSTANTIAL COMPLIANCE WITH THE REGULATIONS HAS BEEN ATTAINED IN ACCORDANCE WITH YOUR VERIFICATION.

PLEASE RETURN THE PLAN OF CORRECTION

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institutio other safeguards provide sufficient protection to the patients. (See instructions.) Except for a days following the date of survey whether or not a plan of correction is provided. For nursing disclosable 14 days following the date these documents are made available to the facility. If to continued program participation.	nursing homes, the findings stated above are disclosab g homes, the above findings and plans of correction are	ole 90 e
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE Electronically Signed	TITLE	(X6) DATE 12/20/2023
IF PARTICIPATING IN THE E-POC PROCESS, A PAPER COPY OF THE PLAN OF CORRECTION IS NOT REQUIRED.		
FOR THE FIRE SAFETY DEFICIENCIES (K-TAGS) TO:		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 733421

Facility ID: 00324

If continuation sheet Page 1 of 5

		ID HUMAN SERVICES MEDICAID SERVICES			FOR	D: 12/21/2023 M APPROVED D. 0938-0391
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	, ,	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		E SURVEY PLETED
		245542	B. WING		12	/06/2023
	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 912 MAIN STREET LITTLEFORK, MN 56653		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL _SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
K 000	Continued From page	e 1	K 00	00		
	Healthcare Fire Inspe State Fire Marshal Di 445 Minnesota St., S St. Paul, MN 55101-5 By email to:	vision uite 145				

FM.HC.Inspections@state.mn.us

THE PLAN OF CORRECTION FOR EACH DEFICIENCY MUST INCLUDE ALL OF THE FOLLOWING INFORMATION:

1. A detailed description of the corrective action taken or planned to correct the deficiency.

2. Address the measures that will be put in place to ensure the deficiency does not reoccur.

3. Indicate how the facility plans to monitor future performance to ensure solutions are sustained.

4. Identify who is responsible for the corrective actions and monitoring of compliance.

5. The actual or proposed date for completion of the remedy.

Littlefork Medical Center was constructed at 3 different times. The original building was built

In 1964 as a nospital and was type II (000). In 1978		
a 1-story without a basement, Type III (200)		
construction was constructed to the east of the		
hospital. In 1992 1-story additions were		
constructed to the north and east wings and are		
Type III (200) construction. The facility is divided		
into 3 smoke zones by 30 minute fire barriers and		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 733421

Facility ID: 00324

If continuation sheet Page 2 of 5

		ID HUMAN SERVICES MEDICAID SERVICES			FOR	D: 12/21/2023 MAPPROVED D. 0938-0391
		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		LE CONSTRUCTION 6 01 - MAIN BUILDING 01	(X3) DATE COMF	E SURVEY PLETED
		245542	B. WING		12	/06/2023
NAME OF PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 912 MAIN STREET LITTLEFORK, MN 56653			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROF DEFICIENCY)	DBE	(X5) COMPLETION DATE
K 000	separated from the ol 2-hour fire barrier. Th not have a fire sprink This part of the buildi sprinkler system. The	d hospital building with a e old hospital section does	K 00	00		

system with full comdor smoke detection, resident rooms and spaces open to the corridors that are monitored for automatic fire department notification. The facility has a capacity of 49 beds and had a census of 30 at the time of the survey. The requirements at 42 CFR, Subpart 483.70(a), are NOT MET as evidenced by: K 353 Sprinkler System - Maintenance and Testing SS=D CFR(s): NFPA 101 Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available.

a) Date sprinkler system last checked

K 353 12/29/23

b) Who provided system test		
c) Water system supply source		
Provide in REMARKS information on coverage for		
any non-required or partial automatic sprinkler		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 733421

Facility ID: 00324

If continuation sheet Page 3 of 5

		ID HUMAN SERVICES MEDICAID SERVICES			PRINTED: 12/21/2023 FORM APPROVED OMB NO. 0938-0391
		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	, ,	E CONSTRUCTION 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED
		245542	B. WING		12/06/2023
NAME OF PROVIDER OR SUPPLIER				STREET ADDRESS, CITY, STATE, ZIP CODE 912 MAIN STREET LITTLEFORK, MN 56653	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	BE COMPLETION
K 353	Based on observatio facility failed to mainta sprinkler system per l	d NFPA 25 is not met as evidenced by: n and staff interview, the	K 353	In order to comply with NFPA 101, 9.7.5,9.7.7,9.7.8 and NFPA 25, modifications were made to the Sprink Cabinet that will allow for each spare	kler

edition), the Standard for the Inspection, Testing, and Maintenance of Water Based Fire Protection Systems, section 5.4.1.4, and 5.4.1.4.2. This deficient finding could have an isolated impact on the residents within the facility.

Findings include:

On 12/06/2023 at 11:46 AM, it was revealed by observation that there were unsecured fire sprinkler heads that were not protected from being damaged, stored loosely within the spare sprinkler head boxes located by the fire sprinkler riser in the utility room.

An interview with Maintenance Director verified this deficient finding at the time of discovery.

K 372 Subdivision of Building Spaces - Smoke Barrie SS=F CFR(s): NFPA 101

> Subdivision of Building Spaces - Smoke Barrier Construction 2012 EXISTING

Smalle harriare shall be constructed to a 1/2 hour

sprinkler head to be secure in the cabinet. All spare sprinkler heads are stored in this location.

The Environmental Services Director is responsible for the correction and compliance with this deficiency.

K 372

12/29/23

Smoke barriers shall be constructed to a 1/2-hour	
fire resistance rating per 8.5. Smoke barriers shall	
be permitted to terminate at an atrium wall. Smoke	
dampers are not required in duct penetrations in	
fully ducted HVAC systems where an approved	
sprinkler system is installed for smoke	
compartments adjacent to the smoke barrier.	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 733421

Facility ID: 00324

If continuation sheet Page 4 of 5

		ID HUMAN SERVICES MEDICAID SERVICES			FORM): 12/21/2023 /IAPPROVED). 0938-0391
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING		(X3) DATE SURVEY COMPLETED 12/06/2023	
	245542					
	ROVIDER OR SUPPLIER		9	TREET ADDRESS, CITY, STATE, ZIP CODE 12 MAIN STREET .ITTLEFORK, MN 56653		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 372	Continued From page 4 19.3.7.3, 8.6.7.1(1) Describe any mechanical smoke control system in REMARKS. This REQUIREMENT is not met as evidenced by: Based on observation and staff interview, the facility failed to maintain their smoke barrier per NFPA 101 (2012 edition). Life Safety Code.		K 372	In order to comply with NFPA 101, 19.3.7.1, 19.3.7.3, 8.5.2.2 and 8.5.6.5,	the	

sections 19.3.7.1, 19.3.7.3, 8.5.2.2, and 8.5.6.5. These deficient findings could have a widespread impact on the residents within the facility.

Findings include:

On 12/06/2023 at 11:53am, it was revealed by observation that there was a penetration running from one smoke compartment to another above doors leading to the east wing.

An interview with Maintenance Director verified this deficient finding at the time of discovery.

from one smoke compartment to another in the east wing was fire caulked. A full inspection of other areas in the care center will be completed and no other areas were noted in the inspection. A form was provided to the Environmental Services Director to be completed when any work is performed by an outside contract to ensure there are no new penetrations that are not properly fire caulked.

The Environmental Services Director is responsible for the correction and compliance with this deficiency.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: 733421

Facility ID: 00324

If continuation sheet Page 5 of 5